# Ventura Call Box Report

## 2020 Annual Report

# Ventura County Transportation Commission

## Call Box Executive Summary

## Annual Report 2020

### Executive Summary

| | |
|---|---|
| Number of active call boxes (12/20) | 427 |
| Total calls for assistance in 2020 | 1,111 |
| Average calls to aid per box per year | 2.6 |
| Average # of calls to aid each day | 3 |
| Average time per call to aid | 2:40 |

### Call boxes Usage

| | |
|---|---|
| Active boxes **used** to call aid | 315 |
| boxes ***not*** **used** to call aid | 112 |

### Calls Grouped by CHP Watch

| | Aid | Maint. |
|---|---|---|
| A Watch (6am to 2pm) | 479 | 10,105 |
| B Watch (2pm to 10pm) | 454 | 29784 |
| C Watch (10pm to 6am) | 178 | 49631 |
| Total number of calls | 1,111 | 89,520 |

### Cellular Time Summary

| | | Averages per box |
|---|---|---|
| Minutes to aid | 2,958 | 6.9 minutes per box |
| Minutes to maintenance | 191,285 | 448.0 minutes per box |
| Minutes to other destinations | 22 | 0.1 minutes per box |
| Total Minutes | 194,265 | 455.0 minutes per box |

### Cellular Call Summary

| | | Averages per box |
|---|---|---|
| Calls to aid | 1,111 | 2.6 calls per box |
| Calls to maintenance | 89,520 | 209.6 calls per box |
| Calls to other destinations | 13 | 0.0 calls per box |
| Total calls | 90,644 | 212.3 calls per box |

### Calls Grouped by Call Length

| Call Length | Maint calls | Calls for aid |
|---|---|---|
| 0:00 to 1:00 | 1,002 | 516 |
| 1:01 to 2:00 | 75577 | 217 |
| 2:01 to 3:00 | 12666 | 137 |
| 3:01 to 5:00 | 271 | 121 |
| 5:01 to 7:00 | 4 | 59 |
| 7:01 *or longer* | 0 | 61 |
| Total calls | 89,520 | 1,111 |

# Ventura Call Box Call History

| | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Jan | 531 | 546 | 389 | 312 | 282 | 360 | 318 | 362 | 249 | 236 | 154 | 267 | 227 | 223 | 192 | 165 | 91 | Jan |
| Feb | 567 | 457 | 406 | 262 | 292 | 234 | 270 | 195 | 204 | 317 | 273 | 217 | 180 | * **304** | 252 | 191 | 63 | Feb |
| Mar | 543 | 407 | 376 | 328 | 288 | 340 | 330 | 303 | 309 | 347 | 296 | 275 | 244 | 244 | 220 | * **349** | 94 | Mar |
| Apr | 578 | 532 | 442 | 626 | 376 | 387 | 322 | 341 | 252 | 203 | 277 | 269 | 112 | 147 | 216 | 134 | 99 | Apr |
| May | 565 | 494 | 487 | * **733** | 430 | 392 | 298 | 220 | 299 | 123 | 220 | 204 | 174 | 186 | 89 | 100 | 110 | May |
| Jun | 587 | 551 | 522 | 590 | 335 | 223 | 227 | 260 | 216 | 296 | 292 | * **414** | * **182** | 298 | 107 | 159 | 80 | Jun |
| Jul | * **667** | 549 | * **539** | 517 | 388 | 374 | 337 | 323 | 318 | 296 | 232 | 366 | 395 | 235 | * **327** | * **149** | 109 | Jul |
| Aug | 665 | * **563** | 497 | 540 | * **445** | * **467** | 371 | 313 | 284 | * **370** | * **449** | 206 | 206 | 170 | 314 | 129 | 98 | Aug |
| Sep | 666 | 440 | 424 | 507 | 311 | 416 | * **387** | 271 | 296 | 246 | 208 | 261 | 287 | 149 | 144 | 121 | 94 | Sep |
| Oct | 579 | 444 | 489 | 473 | 323 | 331 | 263 | 257 | 252 | 111 | 264 | 380 | 322 | 130 | 75 | 105 | * **111** | Oct |
| Nov | 516 | 446 | 374 | 428 | 331 | 201 | 273 | * **362** | * **461** | 148 | 148 | 113 | 138 | 110 | 133 | 77 | 56 | Nov |
| Dec | 481 | 386 | 293 | 323 | 155 | 193 | 231 | 238 | 193 | 109 | 99 | 120 | 115 | 60 | 85 | 91 | 106 | Dec |
| **TOTALS** | 6,945 | 5,815 | 5,238 | 5,639 | 3,956 | 3,918 | 3,627 | 3,445 | 3,333 | 2,802 | 2,912 | 3,092 | 2,582 | 2,256 | 2,154 | 1,770 | 1,111 | **TOTALS** |

* Represents the highest monthly call volume for that year (light blue shading).

Call total since January 1st, 2004 60,595

# Ventura County Transportation Commission

## Call Box Calls by Highway

## Annual Report 2020

| CALL BOXES | 1 | 23 | 33 | 34 | 101 | 118 | 126 | 150 | *Unas. or Test | Totals |
|---|---|---|---|---|---|---|---|---|---|---|
| Active | 42 | 43 | 24 | 3 | 129 | 63 | 100 | 23 | 0 | 427 |
| Temp. Removal | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| Permanent Removal | 16 | 0 | 0 | 0 | 82 | 16 | 28 | 0 | 0 | 142 |
| CALL BOX CALLS TO… | | | | | | | | | | |
| Aid | 256 | 43 | 41 | 4 | 373 | 144 | 147 | 103 | 0 | **1,111** |
| Maintenance | 8762 | 8713 | 4917 | 601 | 27378 | 13529 | 20900 | 4720 | 0 | 89,520 |
| Other places | 2 | 0 | 0 | 0 | 5 | 0 | 2 | 4 | 0 | 13 |
| Total | 9020 | 8756 | 4958 | 605 | 27756 | 13673 | 21049 | 4827 | 0 | 90,644 |
| AVERAGE NUMBER OF CALLS TO.. | | | | | | | | | | |
| **Aid** | 6.1 | 1.0 | 1.7 | 1.3 | 2.9 | 2.3 | 1.5 | 4.5 | 0.0 | **2.6** |
| Maintenance | 209 | 203 | 205 | 200 | 212 | 215 | 209 | 205 | 0 | 210 |
| Other places | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 215 | 204 | 207 | 202 | 215 | 217 | 210 | 210 | 0 | 212 |
| CELLULAR MINUTES TO… | | | | | | | | | | |
| **Aid** | 614 | 90 | 82 | 10 | 1117 | 389 | 386 | 270 | 0 | **2,958** |
| Maintenance | 18638 | 18337 | 10369 | 1273 | 58950 | 29086 | 44615 | 10017 | 0 | 191,285 |
| Other places | 6 | 0 | 0 | 0 | 7 | 0 | 2 | 7 | 0 | 22 |
| Total | 19258 | 18427 | 10451 | 1283 | 60074 | 29475 | 45003 | 10294 | 0 | 194,265 |

*Unas = a phone number not assigned to a call box (is not counted as part of active call box total)

# Ventura Call Boxes Used To Call Aid By Highway

## Annual Report 2020

| Highway | Active call boxes | Called for aid | % calling aid in 2020 |
|---|---|---|---|
| 001 | 42 | 40 | 95% |
| 023 | 43 | 23 | 53% |
| 033 | 24 | 17 | 71% |
| 034 | 3 | 3 | 100% |
| 101 | 129 | 104 | 81% |
| 118 | 63 | 46 | 73% |
| 126 | 100 | 55 | 55% |
| 150 | 23 | 20 | 87% |
| Total | 427 | 308 | 72% |

Percent of call boxes calling aid (by highway)

| Highway | Jan 2020 | Feb 2020 | Mar 2020 | Apr 2020 | May 2020 | Jun 2020 | Jul 2020 | Aug 2020 | Sep 2020 | Oct 2020 | Nov 2020 | Dec 2020 | AVG |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 001 | 37% | 9% | 26% | 30% | 28% | 30% | 21% | 37% | 37% | 35% | 26% | 24% | 28% |
| 023 | 9% | 9% | 9% | 0% | 5% | 5% | 12% | 12% | 5% | 7% | 5% | 5% | 7% |
| 033 | 33% | 4% | 8% | 4% | 21% | 8% | 29% | 4% | 8% | 4% | 4% | 4% | 11% |
| 034 | 0% | 33% | 0% | 0% | 0% | 33% | 0% | 0% | 33% | 0% | 33% | 0% | 11% |
| 101 | 14% | 10% | 16% | 17% | 15% | 12% | 17% | 12% | 15% | 17% | 12% | 20% | 15% |
| 118 | 13% | 14% | 11% | 13% | 11% | 8% | 24% | 10% | 13% | 16% | 8% | 19% | 13% |
| 126 | 5% | 7% | 8% | 8% | 8% | 14% | 7% | 11% | 5% | 10% | 6% | 13% | 9% |
| 150 | 13% | 22% | 26% | 22% | 39% | 17% | 17% | 26% | 35% | 30% | 9% | 13% | 22% |
| Average | 14% | 10% | 14% | 13% | 14% | 13% | 16% | 14% | 14% | 16% | 10% | 16% | 15% |

# Ventura Call Box Calls By Hour

## Annual Report 2020

| | All calls from CALL BOXES | Call box calls to MAINTENANCE | Call box calls to OTHER PLACES | Call box calls for ASSISTANCE (CHP) |
|---|---|---|---|---|
| 6 AM | 6,516 | 6,494 | 0 | 22 |
| 7 AM | 705 | 676 | 0 | 29 |
| 8 AM | 509 | 474 | 1 | 34 |
| 9 AM | 744 | 696 | 0 | 48 |
| 10 AM | 888 | 814 | 0 | 74 |
| 11 AM | 461 | 367 | 4 | 90 |
| 12 PM | 344 | 259 | 0 | 85 |
| 1 PM | 422 | 325 | 0 | 97 |
| 2 PM | 378 | 290 | 0 | 88 |
| 3 PM | 73 | 23 | 0 | 50 |
| 4 PM | 64 | 16 | 2 | 46 |
| 5 PM | 130 | 71 | 1 | 58 |
| 6 PM | 8,384 | 8,324 | 0 | 60 |
| 7 PM | 6,331 | 6,266 | 3 | 62 |
| 8 PM | 8,115 | 8,078 | 0 | 37 |
| 9 PM | 6,770 | 6,716 | 1 | 53 |
| 10 PM | 3,048 | 3,013 | 1 | 34 |
| 11 PM | 7,879 | 7,853 | 0 | 26 |
| 12 AM | 8,551 | 8,519 | 0 | 32 |
| 1 AM | 6,324 | 6,302 | 0 | 22 |
| 2 AM | 7,385 | 7,354 | 0 | 31 |
| 3 AM | 5,849 | 5,838 | 0 | 11 |
| 4 AM | 4,465 | 4,456 | 0 | 9 |
| 5 AM | 6,309 | 6,296 | 0 | 13 |
| TOTAL | 90,644 | 89,520 | 13 | 1,111 |

# Ventura County Transportation Commission

## Top 10 call boxes used to call for assistance
## Annual Report 2020

| Call Box | Calls | Phone # |
|---|---|---|
| **VE-001-0027** | 27 | (805) 256-0034 |
| **VE-001-0077** | 27 | (805) 665-8525 |
| **VE-001-0063** | 26 | (805) 256-0435 |
| **VE-001-0003** | 24 | (805) 850-8927 |
| **VE-150-0212** | 24 | (805) 320-8156 |
| **VE-001-0067** | 12 | (805) 850-9207 |
| **VE-118-0003** | 12 | (805) 218-0762 |
| **VE-001-0083** | 11 | (805) 256-0587 |
| **VE-001-0023** | 11 | (805) 256-0183 |
| **VE-101-0362** | 11 | (805) 256-0907 |

# Ventura Call Boxes with Usage Charges

## Call Boxes with a Total Air Time exceeding 60 Minutes in a bill cycle

## Annual Report 2020

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 1 | VE-150-0293 | (805) 320-8173 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 2 | VE-150-0293 | (805) 320-8173 | 2 | 4 | 2 | 24 | 58 | 3 | 26 | 62 | $ 0.80 | 2020-06 |
| 3 | VE-150-0267 | (805) 256-0579 | 1 | 1 | 1 | 34 | 89 | 3 | 35 | 90 | $ 12.00 | 2020-09 |
| 4 | VE-150-0249 | (805) 850-9553 | 2 | 2 | 1 | 27 | 68 | 3 | 29 | 70 | $ 4.00 | 2020-09 |
| 5 | VE-150-0221 | (805) 320-8158 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 6 | VE-150-0212 | (805) 320-8156 | 2 | 2 | 1 | 28 | 71 | 3 | 30 | 73 | $ 5.20 | 2020-09 |
| 7 | VE-150-0131 | (805) 320-8154 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 8 | VE-150-0097 | (805) 320-8196 | | | | 25 | 64 | 3 | 25 | 64 | $ 1.60 | 2020-09 |
| 9 | VE-150-0083 | (805) 320-8190 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 10 | VE-150-0042 | (805) 256-4267 | 3 | 3 | 1 | 33 | 66 | 3 | 36 | 69 | $ 3.60 | 2020-11 |
| 11 | VE-150-0018 | (805) 320-8189 | 1 | 10 | 10 | 22 | 53 | 3 | 23 | 63 | $ 1.20 | 2020-06 |
| 12 | VE-150-0018 | (805) 320-8189 | 1 | 29 | 29 | 22 | 52 | 3 | 23 | 81 | $ 8.40 | 2020-04 |
| 13 | VE-150-0002 | (805) 256-4269 | 3 | 5 | 3 | 25 | 65 | 4 | 28 | 70 | $ 4.00 | 2020-09 |
| 14 | VE-126-0343 | (805) 256-0042 | 1 | 9 | 9 | 30 | 78 | 3 | 31 | 87 | $ 10.80 | 2020-09 |
| 15 | VE-126-0342 | (805) 850-9389 | | | | 33 | 86 | 3 | 33 | 86 | $ 10.40 | 2020-09 |
| 16 | VE-126-0342 | (805) 850-9389 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-06 |
| 17 | VE-126-0336 | (805) 850-8776 | | | | 31 | 75 | 3 | 31 | 75 | $ 6.00 | 2020-09 |
| 18 | VE-126-0336 | (805) 850-8776 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-06 |
| 19 | VE-126-0332 | (805) 850-9676 | | | | 29 | 75 | 3 | 29 | 75 | $ 6.00 | 2020-09 |
| 20 | VE-126-0317 | (805) 256-0584 | | | | 32 | 83 | 3 | 32 | 83 | $ 9.20 | 2020-09 |
| 21 | VE-126-0316 | (805) 850-9604 | | | | 28 | 67 | 3 | 28 | 67 | $ 2.80 | 2020-09 |
| 22 | VE-126-0316 | (805) 850-9604 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-06 |
| 23 | VE-126-0313 | (805) 850-9578 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 24 | VE-126-0306 | (805) 850-9404 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 25 | VE-126-0303 | (805) 850-9462 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 26 | VE-126-0302 | (805) 850-9374 | | | | 26 | 62 | 3 | 26 | 62 | $ 0.80 | 2020-09 |
| 27 | VE-126-0302 | (805) 850-9374 | 2 | 5 | 3 | 25 | 63 | 4 | 27 | 68 | $ 3.20 | 2020-06 |
| 28 | VE-126-0296 | (805) 850-9433 | | | | 29 | 72 | 3 | 29 | 72 | $ 4.80 | 2020-09 |
| 29 | VE-126-0293 | (805) 256-4229 | | | | 33 | 86 | 3 | 33 | 86 | $ 10.40 | 2020-09 |
| 30 | VE-126-0293 | (805) 256-4229 | | | | 27 | 67 | 3 | 27 | 67 | $ 2.80 | 2020-06 |
| 31 | VE-126-0292 | (805) 850-9127 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 32 | VE-126-0287 | (805) 850-9413 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 33 | VE-126-0286 | (805) 850-9386 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 34 | VE-126-0286 | (805) 850-9386 | | | | 26 | 64 | 3 | 26 | 64 | $ 1.60 | 2020-04 |
| 35 | VE-126-0283 | (805) 850-9486 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 36 | VE-126-0282 | (805) 850-9382 | | | | 38 | 101 | 3 | 38 | 101 | $ 16.40 | 2020-09 |
| 37 | VE-126-0277 | (805) 850-9467 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-09 |
| 38 | VE-126-0276 | (805) 850-9438 | | | | 39 | 102 | 3 | 39 | 102 | $ 16.80 | 2020-09 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 39 | VE-126-0276 | (805) 850-9438 | 1 | 1 | 1 | 29 | 63 | 3 | 30 | 64 | $ 1.60 | 2020-06 |
| 40 | VE-126-0276 | (805) 850-9438 | | | | 31 | 61 | 3 | 31 | 61 | $ 0.40 | 2020-04 |
| 41 | VE-126-0273 | (805) 850-9479 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-06 |
| 42 | VE-126-0257 | (805) 850-9532 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 43 | VE-126-0256 | (805) 256-0581 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 44 | VE-126-0246 | (805) 850-8034 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 45 | VE-126-0243 | (805) 850-9439 | | | | 34 | 87 | 3 | 34 | 87 | $ 10.80 | 2020-06 |
| 46 | VE-126-0237 | (805) 850-9531 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 47 | VE-126-0232 | (805) 850-5716 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 48 | VE-126-0227 | (805) 850-9478 | 1 | 5 | 5 | 31 | 80 | 3 | 32 | 85 | $ 10.00 | 2020-09 |
| 49 | VE-126-0227 | (805) 850-9478 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-06 |
| 50 | VE-126-0226 | (805) 850-5728 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 51 | VE-126-0226 | (805) 850-5728 | | | | 28 | 68 | 3 | 28 | 68 | $ 3.20 | 2020-04 |
| 52 | VE-126-0197 | (805) 850-5698 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 53 | VE-126-0196 | (805) 850-5893 | | | | 32 | 83 | 3 | 32 | 83 | $ 9.20 | 2020-09 |
| 54 | VE-126-0193 | (805) 850-5859 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 55 | VE-126-0193 | (805) 850-5859 | 1 | 3 | 3 | 25 | 62 | 3 | 26 | 65 | $ 2.00 | 2020-06 |
| 56 | VE-126-0192 | (805) 850-8041 | | | | 35 | 89 | 3 | 35 | 89 | $ 11.60 | 2020-09 |
| 57 | VE-126-0192 | (805) 850-8041 | | | | 31 | 78 | 3 | 31 | 78 | $ 7.20 | 2020-06 |
| 58 | VE-126-0186 | (805) 256-0591 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-09 |
| 59 | VE-126-0179 | (805) 850-5767 | 2 | 7 | 6 | 26 | 66 | 3 | 28 | 73 | $ 5.20 | 2020-09 |
| 60 | VE-126-0177 | (805) 850-5752 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 61 | VE-126-0173 | (805) 850-5743 | 1 | 4 | 4 | 24 | 58 | 3 | 25 | 62 | $ 0.80 | 2020-06 |
| 62 | VE-126-0167 | (805) 256-0575 | | | | 33 | 86 | 3 | 33 | 86 | $ 10.40 | 2020-09 |
| 63 | VE-126-0166 | (805) 256-0182 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 64 | VE-126-0162 | (805) 256-0178 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 65 | VE-126-0157 | (805) 850-5777 | | | | 26 | 64 | 3 | 26 | 64 | $ 1.60 | 2020-04 |
| 66 | VE-126-0156 | (805) 256-0576 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 67 | VE-126-0152 | (805) 256-0578 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-09 |
| 68 | VE-126-0147 | (805) 850-5785 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 69 | VE-126-0143 | (805) 218-8442 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 70 | VE-126-0142 | (805) 256-0588 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 71 | VE-126-0137 | (805) 850-5916 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-09 |
| 72 | VE-126-0137 | (805) 850-5916 | | | | 29 | 73 | 3 | 29 | 73 | $ 5.20 | 2020-04 |
| 73 | VE-126-0136 | (805) 850-5942 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 74 | VE-126-0136 | (805) 850-5942 | | | | 26 | 64 | 3 | 26 | 64 | $ 1.60 | 2020-06 |
| 75 | VE-126-0133 | (805) 850-5920 | | | | 24 | 61 | 3 | 24 | 61 | $ 0.40 | 2020-09 |
| 76 | VE-126-0132 | (805) 850-5872 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 77 | VE-126-0123 | (805) 850-5935 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 78 | VE-126-0122 | (805) 850-5937 | | | | 27 | 70 | 3 | 27 | 70 | $ 4.00 | 2020-09 |
| 79 | VE-126-0112 | (805) 850-8023 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 80 | VE-126-0103 | (805) 850-5815 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 81 | VE-126-0093 | (805) 850-5796 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 82 | VE-126-0092 | (805) 850-5894 | | | | 29 | 75 | 3 | 29 | 75 | $ 6.00 | 2020-09 |
| 83 | VE-126-0083 | (805) 256-4258 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 84 | VE-126-0082 | (805) 850-5865 | | | | 37 | 99 | 3 | 37 | 99 | $ 15.60 | 2020-09 |
| 85 | VE-126-0072 | (805) 850-5871 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 86 | VE-126-0063 | (805) 256-4253 | | | | 30 | 77 | 3 | 30 | 77 | $ 6.80 | 2020-09 |
| 87 | VE-126-0062 | (805) 850-5936 | | | | 33 | 87 | 3 | 33 | 87 | $ 10.80 | 2020-09 |
| 88 | VE-126-0053 | (805) 850-5957 | | | | 30 | 77 | 3 | 30 | 77 | $ 6.80 | 2020-09 |
| 89 | VE-126-0052 | (805) 850-8012 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 90 | VE-126-0052 | (805) 850-8012 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-04 |
| 91 | VE-126-0043 | (805) 256-0589 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 92 | VE-126-0042 | (805) 256-4254 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 93 | VE-126-0033 | (805) 218-8528 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 94 | VE-126-0032 | (805) 218-2967 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 95 | VE-126-0032 | (805) 218-2967 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-04 |
| 96 | VE-126-0023 | (805) 256-0052 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 97 | VE-126-0022 | (805) 256-0029 | 1 | 6 | 6 | 26 | 66 | 3 | 27 | 72 | $ 4.80 | 2020-09 |
| 98 | VE-126-0022 | (805) 256-0029 | | | | 27 | 67 | 3 | 27 | 67 | $ 2.80 | 2020-06 |
| 99 | VE-126-0022 | (805) 256-0029 | | | | 29 | 73 | 3 | 29 | 73 | $ 5.20 | 2020-04 |
| 100 | VE-126-0013 | (805) 256-0043 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-09 |
| 101 | VE-126-0012 | (805) 218-8430 | 2 | 9 | 7 | 27 | 58 | 3 | 29 | 67 | $ 2.80 | 2020-11 |
| 102 | VE-126-0012 | (805) 218-8430 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 103 | VE-126-0012 | (805) 218-8430 | | | | 29 | 73 | 3 | 29 | 73 | $ 5.20 | 2020-06 |
| 104 | VE-126-0012 | (805) 218-8430 | | | | 26 | 64 | 3 | 26 | 64 | $ 1.60 | 2020-04 |
| 105 | VE-118-0326 | (805) 256-0719 | | | | 40 | 103 | 4 | 40 | 103 | $ 17.20 | 2020-09 |
| 106 | VE-118-0326 | (805) 256-0719 | 1 | 3 | 3 | 27 | 60 | 3 | 28 | 63 | $ 1.20 | 2020-06 |
| 107 | VE-118-0326 | (805) 256-0719 | | | | 36 | 88 | 3 | 36 | 88 | $ 11.20 | 2020-04 |
| 108 | VE-118-0323 | (805) 256-0595 | | | | 30 | 73 | 3 | 30 | 73 | $ 5.20 | 2020-09 |
| 109 | VE-118-0323 | (805) 256-0595 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-04 |
| 110 | VE-118-0317 | (805) 850-9822 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 111 | VE-118-0316 | (805) 256-0358 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 112 | VE-118-0313 | (805) 256-0378 | | | | 30 | 75 | 4 | 30 | 75 | $ 6.00 | 2020-09 |
| 113 | VE-118-0312 | (805) 256-0747 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 114 | VE-118-0306 | (805) 256-0357 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 115 | VE-118-0287 | (805) 256-0304 | 2 | 4 | 3 | 28 | 71 | 3 | 30 | 75 | $ 6.00 | 2020-09 |
| 116 | VE-118-0286 | (805) 320-4294 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 117 | VE-118-0283 | (805) 320-5767 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-04 |
| 118 | VE-118-0282 | (805) 256-0807 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 119 | VE-118-0273 | (805) 256-0718 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 120 | VE-118-0272 | (805) 218-0725 | | | | 31 | 79 | 3 | 31 | 79 | $ 7.60 | 2020-09 |
| 121 | VE-118-0267 | (805) 256-0187 | | | | 33 | 81 | 3 | 33 | 81 | $ 8.40 | 2020-09 |
| 122 | VE-118-0267 | (805) 256-0187 | | | | 27 | 67 | 3 | 27 | 67 | $ 2.80 | 2020-06 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 123 | VE-118-0267 | (805) 256-0187 | | | | 27 | 67 | 3 | 27 | 67 | $ 2.80 | 2020-04 |
| 124 | VE-118-0266 | (805) 256-0757 | | | | 39 | 105 | 3 | 39 | 105 | $ 18.00 | 2020-09 |
| 125 | VE-118-0257 | (805) 218-5353 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 126 | VE-118-0256 | (805) 256-0759 | | | | 35 | 89 | 3 | 35 | 89 | $ 11.60 | 2020-09 |
| 127 | VE-118-0256 | (805) 256-0759 | | | | 29 | 73 | 3 | 29 | 73 | $ 5.20 | 2020-04 |
| 128 | VE-118-0247 | (805) 256-0297 | | | | 31 | 82 | 3 | 31 | 82 | $ 8.80 | 2020-09 |
| 129 | VE-118-0247 | (805) 256-0297 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 130 | VE-118-0246 | (805) 850-9561 | | | | 43 | 113 | 3 | 43 | 113 | $ 21.20 | 2020-09 |
| 131 | VE-118-0246 | (805) 850-9561 | | | | 29 | 73 | 3 | 29 | 73 | $ 5.20 | 2020-06 |
| 132 | VE-118-0246 | (805) 850-9561 | | | | 31 | 73 | 3 | 31 | 73 | $ 5.20 | 2020-04 |
| 133 | VE-118-0237 | (805) 256-0604 | | | | 41 | 111 | 3 | 41 | 111 | $ 20.40 | 2020-09 |
| 134 | VE-118-0236 | (805) 850-9576 | | | | 30 | 71 | 3 | 30 | 71 | $ 4.40 | 2020-09 |
| 135 | VE-118-0236 | (805) 850-9576 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 136 | VE-118-0236 | (805) 850-9576 | | | | 27 | 67 | 3 | 27 | 67 | $ 2.80 | 2020-04 |
| 137 | VE-118-0227 | (805) 256-0386 | | | | 36 | 95 | 3 | 36 | 95 | $ 14.00 | 2020-09 |
| 138 | VE-118-0227 | (805) 256-0386 | 1 | 2 | 2 | 29 | 73 | 3 | 30 | 75 | $ 6.00 | 2020-06 |
| 139 | VE-118-0227 | (805) 256-0386 | 1 | 3 | 3 | 28 | 71 | 3 | 29 | 74 | $ 5.60 | 2020-04 |
| 140 | VE-118-0226 | (805) 850-9766 | | | | 37 | 92 | 3 | 37 | 92 | $ 12.80 | 2020-09 |
| 141 | VE-118-0226 | (805) 850-9766 | 1 | 3 | 3 | 24 | 58 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 142 | VE-118-0226 | (805) 850-9766 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-04 |
| 143 | VE-118-0217 | (805) 256-0795 | 1 | 1 | 1 | 32 | 84 | 3 | 33 | 85 | $ 10.00 | 2020-09 |
| 144 | VE-118-0216 | (805) 850-9835 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 145 | VE-118-0213 | (805) 256-0339 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-09 |
| 146 | VE-118-0212 | (805) 850-9836 | | | | 30 | 70 | 3 | 30 | 70 | $ 4.00 | 2020-09 |
| 147 | VE-118-0212 | (805) 850-9836 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-04 |
| 148 | VE-118-0207 | (805) 256-0328 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 149 | VE-118-0206 | (805) 218-0231 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 150 | VE-118-0202 | (805) 218-0311 | | | | 29 | 70 | 3 | 29 | 70 | $ 4.00 | 2020-09 |
| 151 | VE-118-0202 | (805) 218-0311 | 1 | 4 | 4 | 24 | 58 | 3 | 25 | 62 | $ 0.80 | 2020-06 |
| 152 | VE-118-0202 | (805) 218-0311 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-04 |
| 153 | VE-118-0197 | (805) 256-0324 | | | | 36 | 96 | 3 | 36 | 96 | $ 14.40 | 2020-09 |
| 154 | VE-118-0196 | (805) 218-0472 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 155 | VE-118-0193 | (805) 256-0325 | | | | 28 | 73 | 4 | 28 | 73 | $ 5.20 | 2020-09 |
| 156 | VE-118-0192 | (805) 218-0328 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 157 | VE-118-0187 | (805) 256-0334 | | | | 33 | 87 | 3 | 33 | 87 | $ 10.80 | 2020-09 |
| 158 | VE-118-0153 | (805) 850-9543 | 1 | 1 | 1 | 29 | 69 | 3 | 30 | 70 | $ 4.00 | 2020-09 |
| 159 | VE-118-0153 | (805) 850-9543 | | | | 28 | 70 | 3 | 28 | 70 | $ 4.00 | 2020-06 |
| 160 | VE-118-0147 | (805) 850-9936 | | | | 27 | 66 | 3 | 27 | 66 | $ 2.40 | 2020-09 |
| 161 | VE-118-0144 | (805) 850-9967 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-04 |
| 162 | VE-118-0133 | (805) 850-9924 | 3 | 14 | 6 | 31 | 80 | 3 | 34 | 94 | $ 13.60 | 2020-04 |
| 163 | VE-118-0126 | (805) 218-0678 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 164 | VE-118-0096 | (805) 850-9840 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-09 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 165 | VE-118-0058 | (805) 218-0798 | 1 | 11 | 11 | 21 | 50 | 3 | 22 | 61 | $ 0.40 | 2020-04 |
| 166 | VE-118-0042 | (805) 850-9847 | 1 | 4 | 4 | 23 | 57 | 3 | 24 | 61 | $ 0.40 | 2020-09 |
| 167 | VE-118-0032 | (805) 850-9963 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 168 | VE-118-0026 | (805) 850-9841 | 2 | 9 | 7 | 26 | 65 | 3 | 28 | 74 | $ 5.60 | 2020-09 |
| 169 | VE-118-0003 | (805) 218-0762 | 1 | 2 | 2 | 25 | 62 | 3 | 26 | 64 | $ 1.60 | 2020-06 |
| 170 | VE-101-0432 | (805) 256-0848 | | | | 29 | 75 | 3 | 29 | 75 | $ 6.00 | 2020-09 |
| 171 | VE-101-0427W | (805) 701-8009 | 1 | 1 | 1 | 27 | 69 | 3 | 28 | 70 | $ 4.00 | 2020-09 |
| 172 | VE-101-0426 | (805) 256-0887 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-06 |
| 173 | VE-101-0426 | (805) 256-0887 | 2 | 11 | 10 | 26 | 58 | 3 | 28 | 69 | $ 3.60 | 2020-04 |
| 174 | VE-101-0422 | (805) 256-4537 | | | | 30 | 74 | 3 | 30 | 74 | $ 5.60 | 2020-09 |
| 175 | VE-101-0422 | (805) 256-4537 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-06 |
| 176 | VE-101-0417W | (805) 256-8258 | 2 | 5 | 3 | 27 | 69 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 177 | VE-101-0413W | (805) 901-5654 | 1 | 2 | 2 | 24 | 59 | 3 | 25 | 61 | $ 0.40 | 2020-09 |
| 178 | VE-101-0412 | (805) 256-0888 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 179 | VE-101-0412 | (805) 256-0888 | 4 | 51 | 43 | 19 | 43 | 3 | 23 | 94 | $ 13.60 | 2020-04 |
| 180 | VE-101-0403 | (805) 256-4271 | 1 | 6 | 6 | 23 | 56 | 3 | 24 | 62 | $ 0.80 | 2020-09 |
| 181 | VE-101-0402 | (805) 256-0886 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 182 | VE-101-0396 | (805) 256-0862 | | | | 27 | 65 | 3 | 27 | 65 | $ 2.00 | 2020-09 |
| 183 | VE-101-0392 | (805) 256-0860 | | | | 34 | 90 | 3 | 34 | 90 | $ 12.00 | 2020-09 |
| 184 | VE-101-0387 | (805) 218-7147 | 1 | 2 | 2 | 25 | 62 | 3 | 26 | 64 | $ 1.60 | 2020-09 |
| 185 | VE-101-0386 | (805) 256-0841 | 1 | 1 | 1 | 26 | 66 | 3 | 27 | 67 | $ 2.80 | 2020-09 |
| 186 | VE-101-0383 | (805) 320-8128 | 1 | 3 | 3 | 28 | 71 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 187 | VE-101-0376 | (805) 256-0574 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 188 | VE-101-0367 | (805) 850-9225 | 2 | 17 | 16 | 21 | 51 | 3 | 23 | 68 | $ 3.20 | 2020-09 |
| 189 | VE-101-0363 | (805) 256-0120 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 190 | VE-101-0362 | (805) 256-0907 | | | | 31 | 82 | 3 | 31 | 82 | $ 8.80 | 2020-09 |
| 191 | VE-101-0362 | (805) 256-0907 | 2 | 2 | 1 | 27 | 66 | 4 | 29 | 68 | $ 3.20 | 2020-04 |
| 192 | VE-101-0357 | (805) 218-7159 | | | | 36 | 91 | 3 | 36 | 91 | $ 12.40 | 2020-09 |
| 193 | VE-101-0357 | (805) 218-7159 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-04 |
| 194 | VE-101-0352 | (805) 256-0922 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 195 | VE-101-0352 | (805) 256-0922 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-06 |
| 196 | VE-101-0347 | (805) 218-9408 | 2 | 7 | 4 | 26 | 65 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 197 | VE-101-0342 | (805) 850-8379 | | | | 36 | 92 | 3 | 36 | 92 | $ 12.80 | 2020-09 |
| 198 | VE-101-0342 | (805) 850-8379 | 2 | 12 | 10 | 24 | 59 | 3 | 26 | 71 | $ 4.40 | 2020-06 |
| 199 | VE-101-0337 | (805) 218-4768 | 1 | 2 | 2 | 27 | 64 | 3 | 28 | 66 | $ 2.40 | 2020-09 |
| 200 | VE-101-0337 | (805) 218-4768 | | | | 29 | 62 | 4 | 29 | 62 | $ 0.80 | 2020-06 |
| 201 | VE-101-0332 | (805) 850-5619 | 4 | 9 | 3 | 33 | 83 | 3 | 37 | 92 | $ 12.80 | 2020-09 |
| 202 | VE-101-0322 | (805) 477-8445 | | | | 27 | 70 | 3 | 27 | 70 | $ 4.00 | 2020-09 |
| 203 | VE-101-0313 | (805) 218-1206 | 1 | 5 | 5 | 23 | 56 | 3 | 24 | 61 | $ 0.40 | 2020-09 |
| 204 | VE-101-0312 | (805) 850-9172 | | | | 29 | 75 | 3 | 29 | 75 | $ 6.00 | 2020-09 |
| 205 | VE-101-0306 | (805) 320-7913 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 206 | VE-101-0306 | (805) 320-7913 | | | | 30 | 77 | 3 | 30 | 77 | $ 6.80 | 2020-06 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 207 | VE-101-0297 | (805) 320-8079 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 208 | VE-101-0296 | (805) 320-7928 | 1 | 3 | 3 | 26 | 66 | 3 | 27 | 69 | $ 3.60 | 2020-09 |
| 209 | VE-101-0296 | (805) 320-7928 | | | | 30 | 77 | 3 | 30 | 77 | $ 6.80 | 2020-06 |
| 210 | VE-101-0286 | (805) 256-0188 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 211 | VE-101-0286 | (805) 256-0188 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-06 |
| 212 | VE-101-0277 | (805) 320-8120 | | | | 33 | 86 | 3 | 33 | 86 | $ 10.40 | 2020-09 |
| 213 | VE-101-0276 | (805) 320-7867 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 214 | VE-101-0276 | (805) 320-7867 | | | | 30 | 77 | 3 | 30 | 77 | $ 6.80 | 2020-06 |
| 215 | VE-101-0267 | (805) 320-8031 | | | | 26 | 64 | 3 | 26 | 64 | $ 1.60 | 2020-09 |
| 216 | VE-101-0266 | (805) 320-7883 | | | | 34 | 90 | 3 | 34 | 90 | $ 12.00 | 2020-09 |
| 217 | VE-101-0266 | (805) 320-7883 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-06 |
| 218 | VE-101-0256 | (805) 665-8436 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 219 | VE-101-0256 | (805) 665-8436 | | | | 33 | 86 | 3 | 33 | 86 | $ 10.40 | 2020-06 |
| 220 | VE-101-0247 | (805) 320-8123 | 1 | 1 | 1 | 27 | 62 | 3 | 28 | 63 | $ 1.20 | 2020-09 |
| 221 | VE-101-0247 | (805) 320-8123 | | | | 28 | 62 | 3 | 28 | 62 | $ 0.80 | 2020-06 |
| 222 | VE-101-0246 | (805) 218-9511 | | | | 34 | 90 | 3 | 34 | 90 | $ 12.00 | 2020-09 |
| 223 | VE-101-0237 | (805) 320-4272 | 2 | 5 | 3 | 26 | 65 | 3 | 28 | 70 | $ 4.00 | 2020-09 |
| 224 | VE-101-0236 | (805) 850-9513 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 225 | VE-101-0227 | (805) 850-9789 | | | | 34 | 85 | 3 | 34 | 85 | $ 10.00 | 2020-09 |
| 226 | VE-101-0227 | (805) 850-9789 | | | | 26 | 62 | 3 | 26 | 62 | $ 0.80 | 2020-04 |
| 227 | VE-101-0226 | (805) 320-4256 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 228 | VE-101-0226 | (805) 320-4256 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-06 |
| 229 | VE-101-0217 | (805) 850-8145 | 1 | 7 | 7 | 27 | 68 | 3 | 28 | 75 | $ 6.00 | 2020-09 |
| 230 | VE-101-0216 | (805) 256-0155 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-06 |
| 231 | VE-101-0207 | (805) 218-4922 | | | | 32 | 85 | 4 | 32 | 85 | $ 10.00 | 2020-09 |
| 232 | VE-101-0206 | (805) 561-9092 | | | | 37 | 99 | 3 | 37 | 99 | $ 15.60 | 2020-09 |
| 233 | VE-101-0206 | (805) 561-9092 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-06 |
| 234 | VE-101-0197 | (805) 561-9091 | | | | 35 | 89 | 3 | 35 | 89 | $ 11.60 | 2020-09 |
| 235 | VE-101-0197 | (805) 561-9091 | 2 | 14 | 12 | 24 | 58 | 3 | 26 | 72 | $ 4.80 | 2020-04 |
| 236 | VE-101-0196 | (805) 320-8596 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 237 | VE-101-0196 | (805) 320-8596 | | | | 41 | 96 | 3 | 41 | 96 | $ 14.40 | 2020-06 |
| 238 | VE-101-0187 | (805) 256-0213 | | | | 31 | 76 | 3 | 31 | 76 | $ 6.40 | 2020-09 |
| 239 | VE-101-0187 | (805) 256-0213 | 1 | 3 | 3 | 24 | 58 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 240 | VE-101-0186 | (805) 320-5895 | 2 | 5 | 4 | 31 | 81 | 3 | 33 | 86 | $ 10.40 | 2020-06 |
| 241 | VE-101-0177 | (805) 256-0200 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 242 | VE-101-0176 | (805) 256-0207 | | | | 37 | 99 | 3 | 37 | 99 | $ 15.60 | 2020-09 |
| 243 | VE-101-0176 | (805) 256-0207 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-06 |
| 244 | VE-101-0167 | (805) 561-8824 | | | | 32 | 83 | 3 | 32 | 83 | $ 9.20 | 2020-09 |
| 245 | VE-101-0166 | (805) 256-8323 | | | | 41 | 107 | 3 | 41 | 107 | $ 18.80 | 2020-09 |
| 246 | VE-101-0166 | (805) 256-8323 | 1 | 2 | 2 | 26 | 65 | 3 | 27 | 67 | $ 2.80 | 2020-06 |
| 247 | VE-101-0157 | (805) 320-7135 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 248 | VE-101-0156 | (805) 256-0063 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 249 | VE-101-0156 | (805) 256-0063 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-06 |
| 250 | VE-101-0147 | (805) 320-7786 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 251 | VE-101-0146 | (805) 218-3127 | | | | 36 | 96 | 3 | 36 | 96 | $ 14.40 | 2020-09 |
| 252 | VE-101-0137 | (805) 256-0150 | | | | 30 | 71 | 3 | 30 | 71 | $ 4.40 | 2020-09 |
| 253 | VE-101-0137 | (805) 256-0150 | | | | 25 | 61 | 3 | 25 | 61 | $ 0.40 | 2020-06 |
| 254 | VE-101-0136 | (805) 320-3103 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 255 | VE-101-0126 | (805) 256-0181 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 256 | VE-101-0117 | (805) 850-5067 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 257 | VE-101-0116 | (805) 850-9956 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-06 |
| 258 | VE-101-0109 | (805) 320-7853 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 259 | VE-101-0108 | (805) 850-9726 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 260 | VE-101-0108 | (805) 850-9726 | 1 | 1 | 1 | 29 | 74 | 3 | 30 | 75 | $ 6.00 | 2020-06 |
| 261 | VE-101-0106 | (805) 850-5369 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 262 | VE-101-0102 | (805) 256-0317 | | | | 31 | 81 | 3 | 31 | 81 | $ 8.40 | 2020-09 |
| 263 | VE-101-0099 | (805) 320-7405 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 264 | VE-101-0098 | (805) 256-0312 | | | | 29 | 72 | 3 | 29 | 72 | $ 4.80 | 2020-06 |
| 265 | VE-101-0098 | (805) 256-0312 | 2 | 2 | 1 | 30 | 73 | 4 | 32 | 75 | $ 6.00 | 2020-05 |
| 266 | VE-101-0098 | (805) 256-0312 | 3 | 3 | 1 | 140 | 381 | 6 | 143 | 384 | $ 129.60 | 2020-04 |
| 267 | VE-101-0098 | (805) 256-0312 | | | | 32 | 93 | 4 | 32 | 93 | $ 13.20 | 2020-03 |
| 268 | VE-101-0097 | (805) 256-0170 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-09 |
| 269 | VE-101-0096 | (805) 665-8674 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-09 |
| 270 | VE-101-0095 | (805) 256-0659 | 2 | 2 | 1 | 27 | 69 | 3 | 29 | 71 | $ 4.40 | 2020-06 |
| 271 | VE-101-0094 | (805) 850-5419 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 272 | VE-101-0094 | (805) 850-5419 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-06 |
| 273 | VE-101-0086 | (805) 665-8676 | | | | 28 | 74 | 3 | 28 | 74 | $ 5.60 | 2020-09 |
| 274 | VE-101-0086 | (805) 665-8676 | | | | 27 | 66 | 3 | 27 | 66 | $ 2.40 | 2020-06 |
| 275 | VE-101-0085 | (805) 256-0206 | | | | 35 | 86 | 3 | 35 | 86 | $ 10.40 | 2020-09 |
| 276 | VE-101-0084 | (805) 256-4764 | | | | 36 | 96 | 3 | 36 | 96 | $ 14.40 | 2020-09 |
| 277 | VE-101-0083 | (805) 218-0824 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-09 |
| 278 | VE-101-0082 | (805) 256-0311 | | | | 35 | 93 | 3 | 35 | 93 | $ 13.20 | 2020-09 |
| 279 | VE-101-0082 | (805) 256-0311 | 1 | 3 | 3 | 26 | 65 | 3 | 27 | 68 | $ 3.20 | 2020-06 |
| 280 | VE-101-0078 | (805) 850-8265 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-09 |
| 281 | VE-101-0078 | (805) 850-8265 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-06 |
| 282 | VE-101-0076 | (805) 701-5657 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 283 | VE-101-0067 | (805) 256-0203 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 284 | VE-101-0066 | (805) 850-9584 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 285 | VE-101-0056 | (805) 850-9878 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 286 | VE-101-0046 | (805) 218-0860 | | | | 32 | 84 | 3 | 32 | 84 | $ 9.60 | 2020-09 |
| 287 | VE-101-0046 | (805) 218-0860 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-04 |
| 288 | VE-101-0029 | (805) 320-8367 | 3 | 12 | 9 | 23 | 54 | 3 | 26 | 66 | $ 2.40 | 2020-12 |
| 289 | VE-101-0028 | (805) 218-6248 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 290 | VE-101-0028 | (805) 218-6248 | 1 | 1 | 1 | 28 | 70 | 4 | 29 | 71 | $ 4.40 | 2020-04 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 291 | VE-101-0017 | (805) 340-4684 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-09 |
| 292 | VE-101-0017 | (805) 340-4684 | | | | 26 | 63 | 3 | 26 | 63 | $ 1.20 | 2020-06 |
| 293 | VE-101-0016 | (805) 218-0945 | | | | 29 | 74 | 3 | 29 | 74 | $ 5.60 | 2020-09 |
| 294 | VE-101-0007 | (805) 701-5087 | | | | 32 | 85 | 3 | 32 | 85 | $ 10.00 | 2020-09 |
| 295 | VE-101-0007 | (805) 701-5087 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-04 |
| 296 | VE-034-0105 | (805) 218-0427 | 1 | 3 | 3 | 25 | 63 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 297 | VE-033-0056 | (805) 320-8319 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 298 | VE-033-0053 | (805) 320-8204 | | | | 28 | 68 | 3 | 28 | 68 | $ 3.20 | 2020-09 |
| 299 | VE-033-0053 | (805) 320-8204 | | | | 27 | 68 | 3 | 27 | 68 | $ 3.20 | 2020-06 |
| 300 | VE-033-0053 | (805) 320-8204 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-04 |
| 301 | VE-033-0033 | (805) 320-8219 | | | | 32 | 80 | 3 | 32 | 80 | $ 8.00 | 2020-09 |
| 302 | VE-033-0033 | (805) 320-8219 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-06 |
| 303 | VE-033-0032 | (805) 320-8295 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-09 |
| 304 | VE-033-0026 | (805) 320-8306 | 1 | 1 | 1 | 27 | 68 | 3 | 28 | 69 | $ 3.60 | 2020-09 |
| 305 | VE-033-0023 | (805) 320-8233 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-06 |
| 306 | VE-033-0017 | (805) 320-8234 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 307 | VE-033-0013 | (805) 320-8331 | | | | 34 | 90 | 3 | 34 | 90 | $ 12.00 | 2020-09 |
| 308 | VE-033-0002 | (805) 320-8276 | | | | 26 | 62 | 3 | 26 | 62 | $ 0.80 | 2020-04 |
| 309 | VE-023-0219 | (805) 850-9640 | | | | 42 | 115 | 4 | 42 | 115 | $ 22.00 | 2020-01 |
| 310 | VE-023-0209 | (805) 256-0179 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-09 |
| 311 | VE-023-0186 | (805) 850-9573 | | | | 30 | 78 | 3 | 30 | 78 | $ 7.20 | 2020-09 |
| 312 | VE-023-0175 | (805) 850-9597 | | | | 38 | 76 | 2 | 38 | 76 | $ 6.40 | 2020-11 |
| 313 | VE-023-0175 | (805) 850-9597 | 1 | 1 | 1 | 65 | 132 | 4 | 66 | 133 | $ 29.20 | 2020-10 |
| 314 | VE-023-0175 | (805) 850-9597 | | | | 54 | 109 | 3 | 54 | 109 | $ 19.60 | 2020-06 |
| 315 | VE-023-0116 | (805) 850-9764 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 316 | VE-023-0113 | (805) 850-9396 | | | | 26 | 66 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 317 | VE-023-0093 | (805) 850-9440 | 1 | 1 | 1 | 29 | 76 | 3 | 30 | 77 | $ 6.80 | 2020-09 |
| 318 | VE-023-0083 | (805) 218-0671 | | | | 32 | 82 | 3 | 32 | 82 | $ 8.80 | 2020-09 |
| 319 | VE-023-0073 | (805) 850-9662 | 1 | 1 | 1 | 27 | 69 | 3 | 28 | 70 | $ 4.00 | 2020-09 |
| 320 | VE-023-0063 | (805) 256-0172 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-09 |
| 321 | VE-023-0053 | (805) 850-9476 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-09 |
| 322 | VE-023-0047 | (805) 256-0699 | | | | 26 | 64 | 3 | 26 | 64 | $ 1.60 | 2020-09 |
| 323 | VE-023-0037 | (805) 850-9518 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-09 |
| 324 | VE-001-0136 | (805) 256-0395 | | | | 28 | 72 | 3 | 28 | 72 | $ 4.80 | 2020-09 |
| 325 | VE-001-0132 | (805) 256-0293 | 1 | 1 | 1 | 27 | 69 | 3 | 28 | 70 | $ 4.00 | 2020-09 |
| 326 | VE-001-0127 | (805) 218-3843 | 1 | 3 | 3 | 25 | 63 | 3 | 26 | 66 | $ 2.40 | 2020-09 |
| 327 | VE-001-0126 | (805) 256-0878 | 4 | 11 | 5 | 25 | 61 | 3 | 29 | 72 | $ 4.80 | 2020-09 |
| 328 | VE-001-0112 | (805) 256-0237 | | | | 27 | 69 | 3 | 27 | 69 | $ 3.60 | 2020-09 |
| 329 | VE-001-0107 | (805) 256-0044 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 330 | VE-001-0097 | (805) 256-0529 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-04 |
| 331 | VE-001-0087 | (805) 256-0045 | 2 | 6 | 5 | 25 | 60 | 3 | 27 | 66 | $ 2.40 | 2020-09 |
| 332 | VE-001-0087 | (805) 256-0045 | | | | 32 | 83 | 3 | 32 | 83 | $ 9.20 | 2020-06 |

| | | | CHP | | | Maintenance | | | Summary | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Call Box | Phone Number | Calls to CHP | Total Minutes_ | Longest Call_ | Calls to Maint | Total Minutes | Longest Call | Total Calls | Total Time | Usage Charge | Month |
| 333 | VE-001-0087 | (805) 256-0045 | | | | 33 | 86 | 3 | 33 | 86 | $ 10.40 | 2020-04 |
| 334 | VE-001-0083 | (805) 256-0587 | | | | 31 | 80 | 3 | 31 | 80 | $ 8.00 | 2020-09 |
| 335 | VE-001-0067 | (805) 850-9207 | 5 | 52 | 17 | 15 | 30 | 2 | 20 | 82 | $ 8.80 | 2020-10 |
| 336 | VE-001-0063 | (805) 256-0435 | 3 | 7 | 4 | 25 | 63 | 3 | 28 | 70 | $ 4.00 | 2020-09 |
| 337 | VE-001-0057 | (805) 256-0853 | | | | 26 | 65 | 3 | 26 | 65 | $ 2.00 | 2020-09 |
| 338 | VE-001-0056 | (805) 850-9218 | | | | 28 | 71 | 3 | 28 | 71 | $ 4.40 | 2020-09 |
| 339 | VE-001-0049 | (805) 256-0914 | 2 | 3 | 2 | 27 | 66 | 3 | 29 | 69 | $ 3.60 | 2020-09 |
| 340 | VE-001-0048 | (805) 850-9159 | 3 | 6 | 4 | 23 | 55 | 3 | 26 | 61 | $ 0.40 | 2020-09 |
| 341 | VE-001-0039 | (805) 218-0648 | | | | 27 | 67 | 3 | 27 | 67 | $ 2.80 | 2020-09 |
| 342 | VE-001-0035 | (805) 256-0036 | | | | 26 | 68 | 3 | 26 | 68 | $ 3.20 | 2020-09 |
| 343 | VE-001-0035 | (805) 256-0036 | | | | 25 | 63 | 3 | 25 | 63 | $ 1.20 | 2020-04 |
| 344 | VE-001-0023 | (805) 256-0183 | 2 | 6 | 4 | 26 | 67 | 3 | 28 | 73 | $ 5.20 | 2020-09 |
| 345 | VE-001-0023 | (805) 256-0183 | 1 | 2 | 2 | 27 | 68 | 3 | 28 | 70 | $ 4.00 | 2020-04 |
| 346 | VE-001-0022 | (805) 218-0618 | | | | 24 | 62 | 3 | 24 | 62 | $ 0.80 | 2020-09 |
| 347 | VE-001-0017 | (805) 256-0041 | 2 | 3 | 2 | 25 | 64 | 3 | 27 | 67 | $ 2.80 | 2020-09 |
| 348 | VE-001-0007 | (805) 256-0282 | | | | 34 | 90 | 3 | 34 | 90 | $ 12.00 | 2020-09 |
| 349 | VE-001-0006 | (805) 218-8439 | 1 | 6 | 6 | 28 | 71 | 3 | 29 | 77 | $ 6.80 | 2020-09 |
| 350 | VE-001-0006 | (805) 218-8439 | | | | 25 | 62 | 3 | 25 | 62 | $ 0.80 | 2020-04 |
| 351 | VE-001-0003 | (805) 850-8927 | 1 | 5 | 5 | 25 | 60 | 3 | 26 | 65 | $ 2.00 | 2020-11 |
| 352 | VE-001-0003 | (805) 850-8927 | 3 | 4 | 2 | 27 | 68 | 3 | 30 | 72 | $ 4.80 | 2020-09 |
| | | Summary | 132 | 488 | 43 | 10221 | 25769 | 6 | 10353 | 26257 | $ 2,054.80 | |

# Ventura Call Box Maintenance Exceptions

## Call volume exceeding 25 calls or less than 10 calls per month

## Annual Report 2020

* Fewer than 10 calls to maintenance indicates a call box is not calling the maintenance center enough.
* More than 25 calls to maintenance indicates a call box is calling the maintenance center too often.
* A copy of this list has been sent to the maintenance vendor.

| | Call Box | Number of Calls to Maintenance | Minutes Used | Month |
|---|---|---|---|---|
| 1 | VE-001-0006 | 28 | 71 | 2020-09 |
| 2 | VE-001-0023 | 27 | 68 | 2020-04 |
| 3 | VE-001-0056 | 28 | 71 | 2020-09 |
| 4 | VE-001-0073 | 8 | 16 | 2020-12 |
| 5 | VE-001-0087 | 33 | 86 | 2020-04 |
| 6 | VE-001-0087 | 32 | 83 | 2020-06 |
| 7 | VE-001-0093 | 1 | 3 | 2020-09 |
| 8 | VE-001-0107 | 26 | 65 | 2020-09 |
| 9 | VE-001-0133 | 26 | 54 | 2020-12 |
| 10 | VE-023-0042 | 27 | 48 | 2020-10 |
| 11 | VE-023-0057 | 28 | 54 | 2020-10 |
| 12 | VE-023-0062 | 6 | 11 | 2020-12 |
| 13 | VE-023-0083 | 26 | 63 | 2020-09 |
| 14 | VE-023-0093 | 26 | 66 | 2020-09 |
| 15 | VE-023-0116 | 26 | 65 | 2020-09 |
| 16 | VE-023-0175 | 63 | 128 | 2020-10 |
| 17 | VE-023-0175 | 54 | 109 | 2020-06 |
| 18 | VE-023-0175 | 41 | 82 | 2020-11 |
| 19 | VE-023-0186 | 27 | 69 | 2020-09 |
| 20 | VE-023-0219 | 42 | 114 | 2020-01 |
| 21 | VE-033-0002 | 28 | 65 | 2020-04 |
| 22 | VE-033-0013 | 29 | 75 | 2020-09 |
| 23 | VE-033-0017 | 26 | 66 | 2020-09 |
| 24 | VE-033-0023 | 26 | 66 | 2020-06 |
| 25 | VE-033-0023 | 26 | 53 | 2020-04 |
| 26 | VE-033-0023 | 26 | 51 | 2020-09 |
| 27 | VE-033-0026 | 27 | 68 | 2020-09 |
| 28 | VE-033-0033 | 30 | 73 | 2020-09 |
| 29 | VE-033-0037 | 26 | 58 | 2020-06 |
| 30 | VE-033-0053 | 27 | 68 | 2020-06 |
| 31 | VE-033-0053 | 28 | 68 | 2020-09 |
| 32 | VE-033-0056 | 26 | 65 | 2020-09 |
| 33 | VE-101-0007 | 30 | 79 | 2020-09 |
| 34 | VE-101-0016 | 29 | 74 | 2020-09 |
| 35 | VE-101-0017 | 27 | 69 | 2020-09 |
| 36 | VE-101-0017 | 26 | 63 | 2020-06 |
| 37 | VE-101-0028 | 28 | 70 | 2020-04 |
| 38 | VE-101-0046 | 29 | 75 | 2020-09 |

| | Call Box | Number of Calls to Maintenance | Minutes Used | Month |
|---|---|---|---|---|
| 39 | VE-101-0046 | 27 | 68 | 2020-04 |
| 40 | VE-101-0056 | 29 | 75 | 2020-09 |
| 41 | VE-101-0066 | 30 | 78 | 2020-09 |
| 42 | VE-101-0076 | 27 | 69 | 2020-09 |
| 43 | VE-101-0078 | 29 | 74 | 2020-06 |
| 44 | VE-101-0082 | 35 | 93 | 2020-09 |
| 45 | VE-101-0082 | 26 | 65 | 2020-06 |
| 46 | VE-101-0083 | 27 | 68 | 2020-09 |
| 47 | VE-101-0084 | 31 | 81 | 2020-09 |
| 48 | VE-101-0085 | 35 | 86 | 2020-09 |
| 49 | VE-101-0086 | 28 | 68 | 2020-06 |
| 50 | VE-101-0094 | 29 | 75 | 2020-09 |
| 51 | VE-101-0094 | 28 | 71 | 2020-06 |
| 52 | VE-101-0095 | 26 | 67 | 2020-06 |
| 53 | VE-101-0095 | 26 | 50 | 2020-10 |
| 54 | VE-101-0095 | 7 | 14 | 2020-04 |
| 55 | VE-101-0097 | 31 | 80 | 2020-09 |
| 56 | VE-101-0098 | 140 | 381 | 2020-04 |
| 57 | VE-101-0098 | 31 | 91 | 2020-03 |
| 58 | VE-101-0098 | 31 | 75 | 2020-05 |
| 59 | VE-101-0098 | 29 | 72 | 2020-06 |
| 60 | VE-101-0102 | 29 | 75 | 2020-09 |
| 61 | VE-101-0108 | 29 | 74 | 2020-06 |
| 62 | VE-101-0108 | 26 | 66 | 2020-09 |
| 63 | VE-101-0109 | 26 | 65 | 2020-09 |
| 64 | VE-101-0116 | 27 | 68 | 2020-06 |
| 65 | VE-101-0117 | 29 | 74 | 2020-09 |
| 66 | VE-101-0126 | 27 | 69 | 2020-09 |
| 67 | VE-101-0136 | 28 | 72 | 2020-09 |
| 68 | VE-101-0137 | 30 | 71 | 2020-09 |
| 69 | VE-101-0146 | 34 | 90 | 2020-09 |
| 70 | VE-101-0147 | 28 | 71 | 2020-09 |
| 71 | VE-101-0156 | 30 | 78 | 2020-09 |
| 72 | VE-101-0156 | 27 | 69 | 2020-06 |
| 73 | VE-101-0157 | 27 | 68 | 2020-09 |
| 74 | VE-101-0166 | 38 | 98 | 2020-09 |
| 75 | VE-101-0166 | 26 | 65 | 2020-06 |
| 76 | VE-101-0167 | 32 | 83 | 2020-09 |
| 77 | VE-101-0176 | 33 | 87 | 2020-09 |
| 78 | VE-101-0176 | 29 | 74 | 2020-06 |
| 79 | VE-101-0177 | 28 | 72 | 2020-09 |
| 80 | VE-101-0186 | 31 | 81 | 2020-06 |
| 81 | VE-101-0187 | 31 | 76 | 2020-09 |
| 82 | VE-101-0196 | 40 | 95 | 2020-06 |
| 83 | VE-101-0196 | 29 | 74 | 2020-09 |
| 84 | VE-101-0197 | 35 | 89 | 2020-09 |
| 85 | VE-101-0206 | 37 | 99 | 2020-09 |

| | Call Box | Number of Calls to Maintenance | Minutes Used | Month |
|---|---|---|---|---|
| 86 | VE-101-0206 | 31 | 80 | 2020-06 |
| 87 | VE-101-0207 | 32 | 85 | 2020-09 |
| 88 | VE-101-0217 | 27 | 68 | 2020-09 |
| 89 | VE-101-0226 | 31 | 81 | 2020-09 |
| 90 | VE-101-0226 | 27 | 68 | 2020-06 |
| 91 | VE-101-0227 | 34 | 85 | 2020-09 |
| 92 | VE-101-0227 | 26 | 62 | 2020-04 |
| 93 | VE-101-0236 | 26 | 66 | 2020-09 |
| 94 | VE-101-0237 | 26 | 65 | 2020-09 |
| 95 | VE-101-0246 | 34 | 90 | 2020-09 |
| 96 | VE-101-0247 | 28 | 62 | 2020-06 |
| 97 | VE-101-0247 | 27 | 62 | 2020-09 |
| 98 | VE-101-0256 | 33 | 86 | 2020-06 |
| 99 | VE-101-0256 | 30 | 78 | 2020-09 |
| 100 | VE-101-0266 | 34 | 90 | 2020-09 |
| 101 | VE-101-0266 | 29 | 74 | 2020-06 |
| 102 | VE-101-0267 | 26 | 64 | 2020-09 |
| 103 | VE-101-0276 | 30 | 78 | 2020-09 |
| 104 | VE-101-0276 | 30 | 77 | 2020-06 |
| 105 | VE-101-0277 | 33 | 86 | 2020-09 |
| 106 | VE-101-0286 | 32 | 84 | 2020-09 |
| 107 | VE-101-0286 | 31 | 81 | 2020-06 |
| 108 | VE-101-0296 | 30 | 77 | 2020-06 |
| 109 | VE-101-0296 | 26 | 66 | 2020-09 |
| 110 | VE-101-0297 | 26 | 65 | 2020-09 |
| 111 | VE-101-0306 | 31 | 81 | 2020-09 |
| 112 | VE-101-0306 | 30 | 77 | 2020-06 |
| 113 | VE-101-0322 | 27 | 70 | 2020-09 |
| 114 | VE-101-0332 | 29 | 71 | 2020-09 |
| 115 | VE-101-0337 | 27 | 64 | 2020-09 |
| 116 | VE-101-0337 | 28 | 61 | 2020-06 |
| 117 | VE-101-0342 | 34 | 86 | 2020-09 |
| 118 | VE-101-0347 | 26 | 65 | 2020-09 |
| 119 | VE-101-0352 | 29 | 75 | 2020-09 |
| 120 | VE-101-0352 | 28 | 72 | 2020-06 |
| 121 | VE-101-0357 | 36 | 91 | 2020-09 |
| 122 | VE-101-0362 | 29 | 76 | 2020-09 |
| 123 | VE-101-0362 | 27 | 66 | 2020-04 |
| 124 | VE-101-0363 | 27 | 68 | 2020-09 |
| 125 | VE-101-0367 | 26 | 57 | 2020-04 |
| 126 | VE-101-0376 | 29 | 75 | 2020-09 |
| 127 | VE-101-0383 | 28 | 71 | 2020-09 |
| 128 | VE-101-0392 | 29 | 75 | 2020-09 |
| 129 | VE-101-0402 | 26 | 66 | 2020-09 |
| 130 | VE-101-0412 | 28 | 72 | 2020-09 |
| 131 | VE-101-0417W | 26 | 66 | 2020-09 |
| 132 | VE-101-0422 | 26 | 65 | 2020-06 |

| | Call Box | Number of Calls to Maintenance | Minutes Used | Month |
|---|---|---|---|---|
| 133 | VE-101-0422 | 27 | 65 | 2020-09 |
| 134 | VE-101-0426 | 29 | 74 | 2020-06 |
| 135 | VE-101-0426 | 7 | 14 | 2020-03 |
| 136 | VE-101-0427W | 27 | 69 | 2020-09 |
| 137 | VE-118-0026 | 26 | 65 | 2020-09 |
| 138 | VE-118-0126 | 26 | 65 | 2020-09 |
| 139 | VE-118-0133 | 31 | 80 | 2020-04 |
| 140 | VE-118-0147 | 27 | 66 | 2020-09 |
| 141 | VE-118-0147 | 27 | 59 | 2020-04 |
| 142 | VE-118-0147 | 26 | 57 | 2020-06 |
| 143 | VE-118-0153 | 28 | 70 | 2020-06 |
| 144 | VE-118-0153 | 29 | 67 | 2020-09 |
| 145 | VE-118-0187 | 26 | 65 | 2020-09 |
| 146 | VE-118-0196 | 27 | 68 | 2020-09 |
| 147 | VE-118-0197 | 27 | 68 | 2020-09 |
| 148 | VE-118-0197 | 26 | 63 | 2020-10 |
| 149 | VE-118-0202 | 31 | 80 | 2020-04 |
| 150 | VE-118-0202 | 29 | 70 | 2020-09 |
| 151 | VE-118-0212 | 31 | 72 | 2020-09 |
| 152 | VE-118-0212 | 26 | 65 | 2020-04 |
| 153 | VE-118-0213 | 27 | 68 | 2020-09 |
| 154 | VE-118-0217 | 27 | 68 | 2020-09 |
| 155 | VE-118-0226 | 37 | 92 | 2020-09 |
| 156 | VE-118-0227 | 29 | 73 | 2020-06 |
| 157 | VE-118-0227 | 28 | 71 | 2020-04 |
| 158 | VE-118-0227 | 27 | 67 | 2020-09 |
| 159 | VE-118-0236 | 30 | 71 | 2020-09 |
| 160 | VE-118-0236 | 27 | 67 | 2020-04 |
| 161 | VE-118-0236 | 26 | 62 | 2020-06 |
| 162 | VE-118-0237 | 33 | 86 | 2020-09 |
| 163 | VE-118-0246 | 36 | 91 | 2020-09 |
| 164 | VE-118-0246 | 31 | 73 | 2020-04 |
| 165 | VE-118-0246 | 29 | 73 | 2020-06 |
| 166 | VE-118-0247 | 31 | 82 | 2020-09 |
| 167 | VE-118-0247 | 7 | 14 | 2020-04 |
| 168 | VE-118-0256 | 29 | 73 | 2020-04 |
| 169 | VE-118-0256 | 27 | 64 | 2020-09 |
| 170 | VE-118-0266 | 31 | 80 | 2020-09 |
| 171 | VE-118-0267 | 33 | 81 | 2020-09 |
| 172 | VE-118-0267 | 27 | 67 | 2020-04 |
| 173 | VE-118-0267 | 27 | 67 | 2020-06 |
| 174 | VE-118-0273 | 29 | 74 | 2020-09 |
| 175 | VE-118-0273 | 26 | 51 | 2020-06 |
| 176 | VE-118-0282 | 27 | 57 | 2020-06 |
| 177 | VE-118-0282 | 26 | 46 | 2020-07 |
| 178 | VE-118-0286 | 26 | 65 | 2020-09 |
| 179 | VE-118-0287 | 28 | 71 | 2020-09 |

| | Call Box | Number of Calls to Maintenance | Minutes Used | Month |
|---|---|---|---|---|
| 180 | VE-118-0312 | 26 | 65 | 2020-09 |
| 181 | VE-118-0313 | 30 | 75 | 2020-09 |
| 182 | VE-118-0316 | 27 | 68 | 2020-09 |
| 183 | VE-118-0317 | 28 | 71 | 2020-09 |
| 184 | VE-118-0323 | 30 | 73 | 2020-09 |
| 185 | VE-118-0326 | 38 | 92 | 2020-04 |
| 186 | VE-118-0326 | 31 | 75 | 2020-09 |
| 187 | VE-118-0326 | 27 | 60 | 2020-06 |
| 188 | VE-126-0012 | 29 | 73 | 2020-06 |
| 189 | VE-126-0012 | 28 | 71 | 2020-09 |
| 190 | VE-126-0012 | 26 | 64 | 2020-04 |
| 191 | VE-126-0012 | 27 | 58 | 2020-11 |
| 192 | VE-126-0013 | 31 | 80 | 2020-09 |
| 193 | VE-126-0022 | 29 | 73 | 2020-04 |
| 194 | VE-126-0022 | 27 | 67 | 2020-06 |
| 195 | VE-126-0023 | 27 | 68 | 2020-09 |
| 196 | VE-126-0032 | 28 | 71 | 2020-09 |
| 197 | VE-126-0043 | 28 | 71 | 2020-09 |
| 198 | VE-126-0052 | 29 | 74 | 2020-09 |
| 199 | VE-126-0053 | 30 | 77 | 2020-09 |
| 200 | VE-126-0062 | 29 | 74 | 2020-09 |
| 201 | VE-126-0063 | 30 | 77 | 2020-09 |
| 202 | VE-126-0072 | 27 | 68 | 2020-09 |
| 203 | VE-126-0082 | 32 | 83 | 2020-09 |
| 204 | VE-126-0083 | 28 | 71 | 2020-09 |
| 205 | VE-126-0093 | 29 | 74 | 2020-09 |
| 206 | VE-126-0103 | 28 | 71 | 2020-09 |
| 207 | VE-126-0106 | 1 | 2 | 2020-12 |
| 208 | VE-126-0123 | 26 | 65 | 2020-09 |
| 209 | VE-126-0136 | 26 | 65 | 2020-09 |
| 210 | VE-126-0136 | 26 | 64 | 2020-06 |
| 211 | VE-126-0137 | 29 | 73 | 2020-04 |
| 212 | VE-126-0142 | 29 | 74 | 2020-09 |
| 213 | VE-126-0147 | 28 | 71 | 2020-09 |
| 214 | VE-126-0156 | 26 | 65 | 2020-09 |
| 215 | VE-126-0157 | 26 | 64 | 2020-04 |
| 216 | VE-126-0162 | 26 | 65 | 2020-09 |
| 217 | VE-126-0167 | 33 | 86 | 2020-09 |
| 218 | VE-126-0186 | 31 | 80 | 2020-09 |
| 219 | VE-126-0192 | 30 | 76 | 2020-06 |
| 220 | VE-126-0192 | 31 | 76 | 2020-09 |
| 221 | VE-126-0193 | 28 | 72 | 2020-09 |
| 222 | VE-126-0196 | 26 | 65 | 2020-09 |
| 223 | VE-126-0197 | 28 | 71 | 2020-09 |
| 224 | VE-126-0226 | 28 | 71 | 2020-09 |
| 225 | VE-126-0226 | 28 | 68 | 2020-04 |
| 226 | VE-126-0226 | 27 | 55 | 2020-06 |

| | Call Box | Number of Calls to Maintenance | Minutes Used | Month |
|---|---|---|---|---|
| 227 | VE-126-0226 | 27 | 46 | 2020-07 |
| 228 | VE-126-0227 | 31 | 80 | 2020-09 |
| 229 | VE-126-0232 | 26 | 65 | 2020-09 |
| 230 | VE-126-0237 | 28 | 71 | 2020-09 |
| 231 | VE-126-0243 | 34 | 87 | 2020-06 |
| 232 | VE-126-0246 | 27 | 68 | 2020-09 |
| 233 | VE-126-0256 | 27 | 68 | 2020-09 |
| 234 | VE-126-0257 | 26 | 65 | 2020-09 |
| 235 | VE-126-0273 | 29 | 74 | 2020-06 |
| 236 | VE-126-0276 | 34 | 87 | 2020-09 |
| 237 | VE-126-0276 | 30 | 64 | 2020-06 |
| 238 | VE-126-0276 | 31 | 61 | 2020-04 |
| 239 | VE-126-0276 | 27 | 56 | 2020-10 |
| 240 | VE-126-0276 | 29 | 50 | 2020-05 |
| 241 | VE-126-0277 | 31 | 80 | 2020-09 |
| 242 | VE-126-0282 | 33 | 86 | 2020-09 |
| 243 | VE-126-0286 | 26 | 64 | 2020-04 |
| 244 | VE-126-0287 | 26 | 65 | 2020-09 |
| 245 | VE-126-0292 | 26 | 65 | 2020-09 |
| 246 | VE-126-0293 | 33 | 86 | 2020-09 |
| 247 | VE-126-0293 | 27 | 67 | 2020-06 |
| 248 | VE-126-0296 | 29 | 72 | 2020-09 |
| 249 | VE-126-0302 | 26 | 62 | 2020-09 |
| 250 | VE-126-0303 | 28 | 71 | 2020-09 |
| 251 | VE-126-0313 | 26 | 65 | 2020-09 |
| 252 | VE-126-0316 | 28 | 71 | 2020-06 |
| 253 | VE-126-0316 | 28 | 67 | 2020-09 |
| 254 | VE-126-0317 | 32 | 83 | 2020-09 |
| 255 | VE-126-0332 | 29 | 75 | 2020-09 |
| 256 | VE-126-0333 | 9 | 16 | 2020-10 |
| 257 | VE-126-0336 | 32 | 84 | 2020-06 |
| 258 | VE-126-0336 | 31 | 75 | 2020-09 |
| 259 | VE-126-0342 | 33 | 86 | 2020-09 |
| 260 | VE-126-0342 | 26 | 66 | 2020-06 |
| 261 | VE-126-0343 | 30 | 78 | 2020-09 |
| 262 | VE-150-0002 | 26 | 67 | 2020-09 |
| 263 | VE-150-0042 | 33 | 66 | 2020-11 |
| 264 | VE-150-0212 | 28 | 71 | 2020-09 |
| 265 | VE-150-0221 | 26 | 65 | 2020-09 |
| 266 | VE-150-0249 | 27 | 68 | 2020-09 |
| 267 | VE-150-0267 | 29 | 74 | 2020-09 |
| 268 | VE-150-0293 | 26 | 65 | 2020-09 |

# Ventura Call Box Calls To Other Destinations

## Besides CHP or Maintenance

## Annual Report 2020

| | Call Box | Phone Number | Number called | Date | Call Initiated | Call length |
|---|---|---|---|---|---|---|
| 1 | VE-101-0383 | (805) 320-8128 | (574) 203-6907 | 1/16/2020 | 8:22:00 AM | 60 |
| 2 | VE-150-0212 | (805) 320-8156 | (805) 477-4101 | 4/1/2020 | 7:40:00 PM | 60 |
| 3 | VE-126-0267 | (805) 320-4270 | (805) 477-4101 | 4/17/2020 | 7:31:00 PM | 60 |
| 4 | VE-101-0427W | (805) 701-8009 | (805) 477-4101 | 6/13/2020 | 7:02:00 PM | 60 |
| 5 | VE-126-0333 | (805) 850-9435 | (805) 477-4101 | 7/13/2020 | 9:09:00 PM | 60 |
| 6 | VE-001-0063 | (805) 256-0435 | (805) 477-4101 | 9/10/2020 | 11:52:00 AM | 60 |
| 7 | VE-150-0002 | (805) 256-4269 | (916) 379-9202 | 9/9/2020 | 11:05:00 AM | 120 |
| 8 | VE-150-0002 | (805) 256-4269 | (510) 421-5801 | 9/9/2020 | 11:07:00 AM | 180 |
| 9 | VE-150-0002 | (805) 256-4269 | (510) 421-5801 | 9/9/2020 | 11:15:00 AM | 60 |
| 10 | VE-101-0336 | (805) 256-5310 | (805) 477-4101 | 9/18/2020 | 4:42:00 PM | 180 |
| 11 | VE-101-0336 | (805) 256-5310 | (805) 477-4101 | 9/18/2020 | 4:45:00 PM | 60 |
| 12 | VE-001-0063 | (805) 256-0435 | (805) 477-4101 | 10/16/2020 | 5:36:00 PM | 300 |
| 13 | VE-101-0433W | (805) 701-3227 | (805) 477-4101 | 12/17/2020 | 10:41:00 PM | 60 |

# Ventura Call Box Preventive Maintenance (PM)

## Ventura call boxes receive 2 preventive maintenance visits each year

## Annual Report 2020

| 2020 Month | Active Boxes | 2020 PM Cycle #1 Scheduled Visits | Scheduled Percent | Actual Visits | Actual Percent |
|---|---|---|---|---|---|
| January | 428 | 71 | 17% | 152 | 36% |
| February | 428 | 71 | 17% | 59 | 14% |
| March | 428 | 71 | 17% | 23 | 5% |
| April | 428 | 71 | 17% | 0 | 0% |
| May | 428 | 71 | 17% | 0 | 0% |
| June | 428 | 71 | 17% | 0 | 0% |
| Totals | 428 | 428 | 100% | 234 | 55% |

| 2020 Month | Active Boxes | 2020 PM Cycle #2 Scheduled Visits | Scheduled Percent | Actual Visits | Actual Percent |
|---|---|---|---|---|---|
| July | 428 | 71 | 17% | 191 | 45% |
| August | 425 | 71 | 17% | 197 | 46% |
| September | 425 | 71 | 17% | 30 | 7% |
| October | 428 | 71 | 17% | 11 | 3% |
| November | 428 | 71 | 17% | 0 | 0% |
| December | 428 | 71 | 17% | 7 | 2% |
| Totals | 427 | 427 | 100% | 436 | 102% |

# Ventura County Transportation Commission
# Call Box Corrective Maintenance
## Annual Report 2020

Produced by: $T^3$

Report 11

Data source: CASE Systems

# Ventura Call Box Corrective Maintenance (CM)

## Annual Report 2020

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 1 | VE-001-0002 | 9/15/2020 | PR | Program Repaired |
| 2 | VE-001-0006 | 9/15/2020 | PR | Program Repaired |
| 3 | VE-001-0016 | 2/25/2020 | CE | Fail To Check In (02/25/2020) |
| 4 | VE-001-0016 | 3/3/2020 | CR | Cell Issue |
| 5 | VE-001-0016 | 9/24/2020 | NP | Fail To Check In (09/24/2020)<br>Fail To Check In (09/23/2020) |
| 6 | VE-001-0016 | 11/30/2020 | XK | Fail To Check In (11/30/2020)<br>Fail To Check In (11/29/2020) |
| 7 | VE-001-0017 | 2/25/2020 | CU | Fail To Check In (02/25/2020)<br>Fail To Check In (02/24/2020) |
| 8 | VE-001-0017 | 3/3/2020 | CR | Cell Issue |
| 9 | VE-001-0017 | 5/5/2020 | BE | Low Battery (05/04/2020)<br>Low Battery (05/03/2020)<br>Low Battery (05/02/2020)<br>Low Battery (05/01/2020)<br>Low Battery (04/30/2020)<br>Low Battery (04/29/2020)<br>Low Battery (04/28/2020) |
| 10 | VE-001-0017 | 9/24/2020 | NP | Fail To Check In (09/24/2020) |
| 11 | VE-001-0017 | 11/11/2020 | BE | Low Battery (11/11/2020)<br>Low Battery (11/10/2020)<br>Low Battery (11/09/2020) |
| 12 | VE-001-0022 | 2/25/2020 | CU | Fail To Check In (02/25/2020) |
| 13 | VE-001-0022 | 3/3/2020 | CR | Cell Issue |
| 14 | VE-001-0022 | 9/24/2020 | NP | Fail To Check In (09/24/2020)<br>Fail To Check In (09/23/2020) |
| 15 | VE-001-0023 | 2/25/2020 | CU | Fail To Check In (02/25/2020) |
| 16 | VE-001-0023 | 3/3/2020 | CR | Cell Issue |
| 17 | VE-001-0023 | 9/14/2020 | BE | Low Battery (09/14/2020)<br>Low Battery (09/13/2020) |
| 18 | VE-001-0023 | 9/24/2020 | CU | Fail To Check In (09/24/2020) |
| 19 | VE-001-0026 | 3/3/2020 | CR | Cell Issue |
| 20 | VE-001-0026 | 9/24/2020 | NP | Fail To Check In (09/24/2020)<br>Fail To Check In (09/23/2020) |
| 21 | VE-001-0027 | 2/6/2020 | OR | Back or Inner Door Alarm (02/06/2020)<br>Tilt Alarm (02/05/2020)<br>Back or Inner Door Alarm (02/05/2020)<br>Back or Inner Door Alarm (02/04/2020) |
| 22 | VE-001-0027 | 2/25/2020 | CU | Fail To Check In (02/25/2020) |
| 23 | VE-001-0027 | 3/3/2020 | CR | Cell Issue |
| 24 | VE-001-0027 | 4/2/2020 | PE | Tilt Alarm (04/01/2020)<br>Tilt Alarm (03/31/2020)<br>Tilt Alarm (03/30/2020) |
| 25 | VE-001-0027 | 5/5/2020 | XZ | Graffitti on call box. |
| 26 | VE-001-0027 | 9/24/2020 | NP | Fail To Check In (09/24/2020) |
| 27 | VE-001-0035 | 2/25/2020 | CU | Fail To Check In (02/25/2020)<br>Fail To Check In (02/24/2020) |
| 28 | VE-001-0035 | 3/3/2020 | CU | Cell Issue |
| 29 | VE-001-0035 | 9/15/2020 | PR | Program Repaired |
| 30 | VE-001-0035 | 9/24/2020 | CU | Fail To Check In (09/24/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 31 | VE-001-0049 | 1/8/2020 | CU | Fail To Check In (01/08/2020)<br>Fail To Check In (01/07/2020)<br>Fail To Check In (01/06/2020)<br>Fail To Check In (01/05/2020) |
| 32 | VE-001-0049 | 1/31/2020 | BE | Low Battery (01/31/2020)<br>Low Battery (01/30/2020) |
| 33 | VE-001-0049 | 2/25/2020 | CU | Fail To Check In (02/25/2020) |
| 34 | VE-001-0049 | 3/3/2020 | CR | Cell Issue |
| 35 | VE-001-0049 | 7/29/2020 | OR | Front or Outer Door Alarm (07/28/2020)<br>Front or Outer Door Alarm (07/27/2020)<br>Front or Outer Door Alarm (07/24/2020)<br>Front or Outer Door Alarm (07/23/2020) |
| 36 | VE-001-0056 | 5/14/2020 | OR | Front or Outer Door Alarm (05/14/2020)<br>Front or Outer Door Alarm (05/13/2020) |
| 37 | VE-001-0056 | 6/8/2020 | CR | Fail To Check In (06/08/2020)<br>Fail To Check In (06/07/2020)<br>Fail To Check In (06/06/2020)<br>Fail To Check In (06/05/2020)<br>Fail To Check In (06/04/2020)<br>Fail To Check In (06/03/2020)<br>Fail To Check In (06/02/2020)<br>Fail To Check In (06/01/2020)<br>Fail... |
| 38 | VE-001-0056 | 11/23/2020 | OR | Front or Outer Door Alarm (11/23/2020)<br>Front or Outer Door Alarm (11/22/2020) |
| 39 | VE-001-0056 | 11/30/2020 | OR | Front or Outer Door Alarm (11/30/2020)<br>Front or Outer Door Alarm (11/29/2020) |
| 40 | VE-001-0056 | 12/10/2020 | BE | Low Battery (12/10/2020)<br>Low Battery (12/09/2020) |
| 41 | VE-001-0057 | 9/15/2020 | PR | Program Repaired |
| 42 | VE-001-0057 | 11/12/2020 | SE | Solar Panel Issue |
| 43 | VE-001-0057 | 11/30/2020 | LE | Lamp Alarm (11/30/2020)<br>Lamp Alarm (11/29/2020)<br>Lamp Alarm (11/28/2020)<br>Lamp Alarm (11/27/2020) |
| 44 | VE-001-0057 | 12/8/2020 | BE | Low Battery (12/08/2020)<br>Low Battery (12/07/2020)<br>Low Battery (12/06/2020) |
| 45 | VE-001-0057 | 12/10/2020 | BE | Low Battery (12/10/2020)<br>Low Battery (12/09/2020) |
| 46 | VE-001-0057 | 12/16/2020 | BE | Low Battery (12/16/2020)<br>Low Battery (12/15/2020)<br>Low Battery (12/14/2020) |
| 47 | VE-001-0067 | 4/15/2020 | OR | Front or Outer Door Alarm (04/15/2020)<br>Front or Outer Door Alarm (04/14/2020)<br>Front or Outer Door Alarm (04/13/2020)<br>Front or Outer Door Alarm (04/12/2020)<br>Front or Outer Door Alarm (04/11/2020)<br>Front or Outer Door Alarm (04/10/2020)<br>Front or Out... |
| 48 | VE-001-0067 | 6/8/2020 | XS | See answering service |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 49 | VE-001-0067 | 12/8/2020 | OR | Front or Outer Door Alarm (12/08/2020)<br>Front or Outer Door Alarm (12/07/2020)<br>Front or Outer Door Alarm (12/06/2020)<br>Front or Outer Door Alarm (12/05/2020) |
| 50 | VE-001-0073 | 9/17/2020 | PR | Program Issue |
| 51 | VE-001-0073 | 11/23/2020 | XT | Power/Solar Alarm (11/23/2020)<br>Power/Solar Alarm (11/22/2020)<br>Power/Solar Alarm (11/21/2020) |
| 52 | VE-001-0073 | 12/18/2020 | XI | See answering service |
| 53 | VE-001-0087 | 9/24/2020 | NP | See answering service |
| 54 | VE-001-0097 | 9/24/2020 | NP | See answering service |
| 55 | VE-001-0102 | 5/7/2020 | BE | Low Battery (05/07/2020)<br>Low Battery (05/05/2020)<br>Low Battery (05/06/2020) |
| 56 | VE-001-0113 | 9/17/2020 | PR | Program Issue |
| 57 | VE-001-0116 | 8/10/2020 | BE | Low Battery (08/10/2020)<br>Low Battery (08/09/2020) |
| 58 | VE-001-0117 | 9/15/2020 | PR | Program Repaired |
| 59 | VE-001-0117 | 9/15/2020 | PR | Program Repaired |
| 60 | VE-001-0122 | 1/8/2020 | CR | TTY ISSUE |
| 61 | VE-001-0122 | 1/31/2020 | BE | Low Battery (01/31/2020)<br>Low Battery (01/30/2020)<br>Low Battery (01/29/2020) |
| 62 | VE-001-0126 | 8/10/2020 | BE | Low Battery (08/10/2020)<br>Low Battery (08/09/2020)<br>Low Battery (08/08/2020)<br>Low Battery (08/07/2020)<br>Low Battery (08/06/2020) |
| 63 | VE-001-0126 | 9/3/2020 | BE | Low Battery (09/03/2020)<br>Low Battery (09/02/2020)<br>Low Battery (09/01/2020)<br>Low Battery (08/31/2020)<br>Low Battery (08/30/2020)<br>Low Battery (08/29/2020)<br>Low Battery (08/28/2020)<br>Low Battery (08/27/2020)<br>Low Battery (08/26/2020)<br>Low Battery (08/25... |
| 64 | VE-001-0126 | 9/17/2020 | PR | Program Issue |
| 65 | VE-001-0126 | 10/29/2020 | OR | Front or Outer Door Alarm (10/28/2020)<br>Front or Outer Door Alarm (10/27/2020) |
| 66 | VE-001-0132 | 11/12/2020 | ZR | Sign issue |
| 67 | VE-001-0133 | 9/17/2020 | PR | Program Issue |
| 68 | VE-001-0133 | 12/16/2020 | BE | Low Battery (12/16/2020)<br>Low Battery (12/15/2020)<br>Low Battery (12/14/2020)<br>Low Battery (12/13/2020)<br>Low Battery (12/12/2020)<br>Low Battery (12/11/2020) |
| 69 | VE-001-0137 | 2/25/2020 | BE | Low Battery (02/25/2020)<br>Low Battery (02/24/2020)<br>Low Battery (02/23/2020)<br>Low Battery (02/22/2020)<br>Front or Outer Door Alarm (02/22/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 70 | VE-001-0143 | 1/31/2020 | BE | Low Battery (01/31/2020)<br>Low Battery (01/30/2020)<br>Low Battery (01/29/2020)<br>Low Battery (01/28/2020)<br>Low Battery (01/27/2020)<br>Low Battery (01/26/2020)<br>Low Battery (01/25/2020)<br>Low Battery (01/24/2020) |
| 71 | VE-001-0143 | 2/11/2020 | XK | Tilt Alarm (02/11/2020) |
| 72 | VE-001-0143 | 9/15/2020 | PR | Program Repaired |
| 73 | VE-001-0146 | 9/17/2020 | PR | Program Issue |
| 74 | VE-001-0146 | 11/25/2020 | HR | Handset Alarm (11/25/2020) |
| 75 | VE-001-0147 | 9/17/2020 | PR | Program Issue |
| 76 | VE-023-0036 | 1/3/2020 | XK | Xk- Reported by chp |
| 77 | VE-023-0036 | 1/7/2020 | IR | Back or Inner Door Alarm (01/07/2020)<br>Back or Inner Door Alarm (01/06/2020)<br>Back or Inner Door Alarm (01/05/2020) |
| 78 | VE-023-0042 | 4/1/2020 | CR | Fail To Check In (03/31/2020)<br>Fail To Check In (03/30/2020)<br>Fail To Check In (03/29/2020)<br>Fail To Check In (03/28/2020)<br>Fail To Check In (03/27/2020)<br>Fail To Check In (03/26/2020)<br>Fail To Check In (03/25/2020) |
| 79 | VE-023-0042 | 10/15/2020 | CR | Programing Error (10/15/2020)<br>Programing Error (10/14/2020) |
| 80 | VE-023-0047 | 10/29/2020 | BE | Battery issue |
| 81 | VE-023-0047 | 12/21/2020 | BE | Low Battery (12/21/2020)<br>Low Battery (12/20/2020)<br>Low Battery (12/19/2020)<br>Low Battery (12/18/2020) |
| 82 | VE-023-0053 | 7/29/2020 | BE | Low Battery (07/29/2020) |
| 83 | VE-023-0053 | 8/3/2020 | BE | Low Battery (08/03/2020)<br>Low Battery (08/02/2020)<br>Low Battery (08/01/2020)<br>Low Battery (07/31/2020) |
| 84 | VE-023-0057 | 3/3/2020 | XK | XK |
| 85 | VE-023-0057 | 10/8/2020 | BE | Low Battery (10/08/2020) |
| 86 | VE-023-0057 | 10/29/2020 | BE | Low Battery (10/28/2020) |
| 87 | VE-023-0057 | 12/2/2020 | ZR | Sign Vandalizim |
| 88 | VE-023-0057 | 12/4/2020 | BE | Low Battery (12/03/2020) |
| 89 | VE-023-0062 | 12/10/2020 | XT | Tilt Alarm (12/10/2020) |
| 90 | VE-023-0063 | 10/8/2020 | XZ | Sign repair |
| 91 | VE-023-0066 | 11/24/2020 | BE | Low Battery (11/24/2020)<br>Low Battery (11/23/2020) |
| 92 | VE-023-0072 | 4/14/2020 | BE | Low Battery (04/14/2020)<br>Low Battery (04/13/2020)<br>Low Battery (04/12/2020)<br>Low Battery (04/11/2020)<br>Low Battery (04/10/2020)<br>Low Battery (04/09/2020) |
| 93 | VE-023-0072 | 8/5/2020 | BE | Low Battery (08/05/2020) |
| 94 | VE-023-0072 | 12/4/2020 | BE | Low Battery (12/04/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 95 | VE-023-0077 | 4/14/2020 | LE | Lamp Alarm (04/13/2020)<br>Lamp Alarm (04/12/2020) |
| 96 | VE-023-0086 | 12/7/2020 | BE | Low Battery (12/07/2020)<br>Low Battery (12/06/2020)<br>Low Battery (12/05/2020) |
| 97 | VE-023-0097 | 8/3/2020 | XK | Tilt Alarm (08/03/2020)<br>Tilt Alarm (08/02/2020)<br>Tilt Alarm (08/01/2020)<br>Tilt Alarm (07/31/2020) |
| 98 | VE-023-0097 | 10/15/2020 | XI | Install pole |
| 99 | VE-023-0097 | 10/16/2020 | XI | Install call box<br>Was temp removal |
| 100 | VE-023-0116 | 1/29/2020 | BE | Low Battery (01/29/2020)<br>Low Battery (01/28/2020)<br>Low Battery (01/27/2020)<br>Low Battery (01/26/2020)<br>Low Battery (01/25/2020)<br>Low Battery (01/24/2020)<br>Low Battery (01/23/2020)<br>Low Battery (01/22/2020)<br>Low Battery (01/21/2020)<br>Low Battery (01/20/2020)<br>Lo... |
| 101 | VE-023-0153 | 2/24/2020 | BE | Low Battery (02/24/2020)<br>Low Battery (02/23/2020)<br>Low Battery (02/22/2020)<br>Low Battery (02/21/2020)<br>Low Battery (02/20/2020)<br>Low Battery (02/19/2020) |
| 102 | VE-023-0153 | 3/17/2020 | BE | Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020)<br>Low Battery (03/14/2020)<br>Low Battery (03/13/2020)<br>Low Battery (03/12/2020)<br>Low Battery (03/11/2020)<br>Low Battery (03/10/2020)<br>Low Battery (03/09/2020)<br>Low Battery (03/08... |
| 103 | VE-023-0165 | 2/27/2020 | OR | Low Battery (02/27/2020)<br>Power/Solar Alarm (02/27/2020)<br>TTY Alarm (02/27/2020)<br>TTY Display Error (02/27/2020)<br>Low Battery (02/26/2020) |
| 104 | VE-023-0165 | 10/5/2020 | BE | Low Battery (10/05/2020)<br>Low Battery (10/04/2020)<br>Low Battery (10/03/2020)<br>Fail To Check In (10/02/2020)<br>Fail To Check In (10/01/2020) |
| 105 | VE-023-0165 | 11/6/2020 | BE | Low Battery (11/06/2020)<br>Low Battery (11/05/2020)<br>Low Battery (11/04/2020) |
| 106 | VE-023-0175 | 7/29/2020 | CR | Cell issue |
| 107 | VE-023-0175 | 10/14/2020 | CU | See answering service |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 108 | VE-023-0175 | 10/19/2020 | CR | Back or Inner Door Alarm (10/16/2020)<br>Front or Outer Door Alarm (10/16/2020)<br>Fail To Check In (10/15/2020) |
| 109 | VE-023-0196 | 1/7/2020 | CR | Fail To Check In (01/07/2020)<br>Fail To Check In (01/06/2020)<br>Fail To Check In (01/05/2020)<br>Fail To Check In (01/04/2020)<br>Fail To Check In (01/03/2020)<br>Fail To Check In (01/02/2020)<br>Fail To Check In (01/01/2020)<br>Fail To Check In (12/31/2019)<br>Fail... |
| 110 | VE-023-0196 | 12/2/2020 | OR | Front or Outer Door Alarm (12/02/2020)<br>Front or Outer Door Alarm (12/01/2020)<br>Front or Outer Door Alarm (11/30/2020)<br>Front or Outer Door Alarm (11/29/2020) |
| 111 | VE-023-0219 | 2/10/2020 | CR | Cell Issue |
| 112 | VE-023-0233 | 8/5/2020 | BE | Low Battery (08/05/2020)<br>Low Battery (08/04/2020) |
| 113 | VE-023-0233 | 12/9/2020 | ZR | Sign repair |
| 114 | VE-033-0002 | 4/7/2020 | BE | Low Battery (04/07/2020)<br>Low Battery (04/06/2020)<br>Low Battery (04/05/2020)<br>Low Battery (04/03/2020)<br>Low Battery (04/04/2020) |
| 115 | VE-033-0002 | 10/8/2020 | BE | Low Battery (10/08/2020) |
| 116 | VE-033-0012 | 4/7/2020 | OR | Front or Outer Door Alarm (04/07/2020)<br>Front or Outer Door Alarm (04/06/2020)<br>Front or Outer Door Alarm (04/05/2020) |
| 117 | VE-033-0012 | 4/8/2020 | OR | Front or Outer Door Alarm (04/08/2020) |
| 118 | VE-033-0012 | 11/20/2020 | CR | Fail To Check In (11/20/2020) |
| 119 | VE-033-0017 | 11/11/2020 | OR | Front or Outer Door Alarm (11/11/2020)<br>Front or Outer Door Alarm (11/10/2020) |
| 120 | VE-033-0022 | 5/19/2020 | CR | Cell issue repaired |
| 121 | VE-033-0023 | 1/13/2020 | BE | Low Battery (01/13/2020) |
| 122 | VE-033-0023 | 1/20/2020 | BE | Low Battery (01/20/2020)<br>Low Battery (01/19/2020)<br>Low Battery (01/18/2020) |
| 123 | VE-033-0023 | 4/7/2020 | PE | Programing Error (04/07/2020)<br>Programing Error (04/06/2020) |
| 124 | VE-033-0023 | 8/27/2020 | PR | Programing Error (08/27/2020)<br>Programing Error (08/26/2020) |
| 125 | VE-033-0023 | 9/23/2020 | CR | Cell Issue |
| 126 | VE-033-0033 | 9/23/2020 | CR | Cell Issue |
| 127 | VE-033-0037 | 6/8/2020 | BE | Low Battery (06/08/2020)<br>Low Battery (06/07/2020)<br>Low Battery (06/06/2020)<br>Low Battery (06/05/2020)<br>Low Battery (06/02/2020)<br>Low Battery (06/01/2020)<br>Low Battery (05/31/2020)<br>Low Battery (05/30/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 128 | VE-033-0037 | 7/10/2020 | BE | Low Battery (07/10/2020)<br>Low Battery (07/09/2020)<br>Low Battery (07/08/2020)<br>Low Battery (07/07/2020)<br>Low Battery (07/06/2020)<br>Low Battery (07/05/2020) |
| 129 | VE-033-0043 | 4/15/2020 | CE | Fail To Check In (04/15/2020) |
| 130 | VE-033-0047 | 3/17/2020 | OR | Front or Outer Door Alarm (03/18/2020)<br>Front or Outer Door Alarm (03/17/2020)<br>Front or Outer Door Alarm (03/16/2020)<br>Front or Outer Door Alarm (03/15/2020)<br>Front or Outer Door Alarm (03/14/2020)<br>Front or Outer Door Alarm (03/13/2020)<br>Front or Out... |
| 131 | VE-033-0047 | 3/18/2020 | IR | Front or Outer Door Alarm (03/18/2020)<br>Front or Outer Door Alarm (03/17/2020)<br>Front or Outer Door Alarm (03/16/2020)<br>Front or Outer Door Alarm (03/15/2020)<br>Front or Outer Door Alarm (03/14/2020)<br>Front or Outer Door Alarm (03/13/2020)<br>Front or Out... |
| 132 | VE-033-0052 | 3/18/2020 | BE | Low Battery (03/18/2020) |
| 133 | VE-033-0052 | 11/18/2020 | HE | Handset Alarm (11/16/2020) |
| 134 | VE-033-0052 | 11/20/2020 | BE | Low Battery (11/20/2020)<br>Low Battery (11/19/2020) |
| 135 | VE-033-0052 | 11/24/2020 | HE | Handset Alarm (11/24/2020) |
| 136 | VE-033-0053 | 3/17/2020 | OR | Front or Outer Door Alarm (03/17/2020)<br>Front or Outer Door Alarm (03/16/2020)<br>Front or Outer Door Alarm (03/15/2020)<br>Front or Outer Door Alarm (03/14/2020)<br>Front or Outer Door Alarm (03/13/2020)<br>Front or Outer Door Alarm (03/12/2020)<br>Front or Out... |
| 137 | VE-033-0053 | 3/18/2020 | OR | Front or Outer Door Alarm (03/18/2020) |
| 138 | VE-033-0053 | 5/19/2020 | CR | Cell issue repaired |
| 139 | VE-033-0053 | 9/23/2020 | CR | Cell Issue |
| 140 | VE-033-0053 | 11/18/2020 | BE | Low Battery (11/18/2020) |
| 141 | VE-033-0057 | 2/7/2020 | PE | sign repair |
| 142 | VE-033-0063 | 1/13/2020 | BE | Low Battery (01/13/2020) |
| 143 | VE-033-0063 | 1/20/2020 | BE | Low Battery (01/20/2020)<br>Low Battery (01/19/2020)<br>Low Battery (01/18/2020)<br>Low Battery (01/17/2020) |
| 144 | VE-033-0063 | 1/24/2020 | BE | Low Battery (01/24/2020)<br>Low Battery (01/23/2020)<br>Low Battery (01/22/2020)<br>Low Battery (01/21/2020) |
| 145 | VE-101-0028 | 4/10/2020 | PE | Programing issue |
| 146 | VE-101-0036 | 10/15/2020 | OR | Front or Outer Door Alarm (10/14/2020)<br>Front or Outer Door Alarm (10/13/2020)<br>Front or Outer Door Alarm (10/12/2020)<br>Front or Outer Door Alarm (10/11/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 147 | VE-101-0037 | 6/8/2020 | BE | Low Battery (06/08/2020)<br>Low Battery (06/07/2020)<br>Low Battery (06/06/2020) |
| 148 | VE-101-0047 | 7/21/2020 | LE | Lamp Alarm (07/21/2020) |
| 149 | VE-101-0047 | 7/29/2020 | LR | Lamp Alarm (07/29/2020)<br>Lamp Alarm (07/28/2020)<br>Lamp Alarm (07/27/2020)<br>Lamp Alarm (07/26/2020)<br>Lamp Alarm (07/25/2020)<br>Lamp Alarm (07/24/2020)<br>Lamp Alarm (07/23/2020)<br>Lamp Alarm (07/22/2020) |
| 150 | VE-101-0057 | 9/3/2020 | BE | Low Battery (09/03/2020)<br>Low Battery (09/02/2020)<br>Low Battery (09/01/2020)<br>Low Battery (08/31/2020)<br>Low Battery (08/30/2020)<br>Low Battery (08/29/2020) |
| 151 | VE-101-0066 | 10/23/2020 | BE | Low Battery (10/23/2020) |
| 152 | VE-101-0067 | 1/8/2020 | Aw | CELL ISSUE |
| 153 | VE-101-0077 | 4/10/2020 | PE | Programing issue |
| 154 | VE-101-0085 | 9/14/2020 | BE | Low Battery (09/14/2020)<br>Low Battery (09/13/2020)<br>Low Battery (09/12/2020) |
| 155 | VE-101-0085 | 9/17/2020 | BE | Low Battery (09/17/2020)<br>Low Battery (09/16/2020)<br>Low Battery (09/15/2020) |
| 156 | VE-101-0086 | 4/2/2020 | CR | Fail To Check In (04/01/2020)<br>Fail To Check In (04/02/2020) |
| 157 | VE-101-0086 | 4/13/2020 | CR | Fail To Check In (04/13/2020) |
| 158 | VE-101-0086 | 5/5/2020 | CR | Fail To Check In (05/04/2020)<br>Fail To Check In (05/03/2020)<br>Fail To Check In (05/02/2020)<br>Fail To Check In (05/01/2020)<br>Fail To Check In (04/30/2020)<br>Fail To Check In (04/29/2020)<br>Fail To Check In (04/28/2020)<br>Fail To Check In (04/27/2020)<br>Fail... |
| 159 | VE-101-0086 | 5/12/2020 | CU | Fail To Check In (05/12/2020)<br>Fail To Check In (05/11/2020) |
| 160 | VE-101-0086 | 5/14/2020 | CR | CELL ISSUE |
| 161 | VE-101-0086 | 6/8/2020 | CR | Fail To Check In (06/08/2020) |
| 162 | VE-101-0086 | 11/19/2020 | ZR | Sign Exchange |
| 163 | VE-101-0087 | 10/20/2020 | BE | Low Battery (10/20/2020)<br>Low Battery (10/19/2020)<br>Low Battery (10/18/2020)<br>Low Battery (10/17/2020)<br>Low Battery (10/16/2020) |
| 164 | VE-101-0094 | 2/28/2020 | CR | Fail To Check In (02/28/2020)<br>Fail To Check In (02/27/2020) |
| 165 | VE-101-0094 | 3/2/2020 | SR | Power/Solar Alarm (03/02/2020)<br>Power/Solar Alarm (03/01/2020)<br>Power/Solar Alarm (02/29/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 166 | VE-101-0094 | 4/2/2020 | CR | Fail To Check In (04/01/2020)<br>Fail To Check In (04/02/2020)<br>Fail To Check In (03/31/2020)<br>Fail To Check In (03/30/2020)<br>Fail To Check In (03/29/2020)<br>Fail To Check In (03/28/2020) |
| 167 | VE-101-0095 | 1/29/2020 | CR | Fail To Check In (01/29/2020) |
| 168 | VE-101-0095 | 4/13/2020 | BE | Low Battery (04/13/2020) |
| 169 | VE-101-0095 | 5/5/2020 | CR | Fail To Check In (05/04/2020)<br>Fail To Check In (05/03/2020)<br>Fail To Check In (05/02/2020)<br>Fail To Check In (05/01/2020)<br>Fail To Check In (04/30/2020)<br>Fail To Check In (04/29/2020)<br>Fail To Check In (04/28/2020)<br>Fail To Check In (04/27/2020)<br>Fail... |
| 170 | VE-101-0095 | 5/12/2020 | CR | Fail To Check In (05/12/2020)<br>Fail To Check In (05/11/2020) |
| 171 | VE-101-0095 | 6/8/2020 | OR | Front or Outer Door Alarm (06/08/2020)<br>Front or Outer Door Alarm (06/07/2020)<br>Front or Outer Door Alarm (06/06/2020)<br>Fail To Check In (06/05/2020)<br>Fail To Check In (06/04/2020)<br>Fail To Check In (06/03/2020)<br>Fail To Check In (06/02/2020)<br>Fail To ... |
| 172 | VE-101-0095 | 7/20/2020 | XK | Xk-Xi |
| 173 | VE-101-0095 | 7/21/2020 | BE | Low Battery (07/21/2020) |
| 174 | VE-101-0095 | 9/3/2020 | PR | Fail To Check In (09/03/2020) |
| 175 | VE-101-0095 | 10/29/2020 | BE | Low Battery (10/27/2020)<br>Low Battery (10/25/2020)<br>Low Battery (10/26/2020)<br>Low Battery (10/24/2020) |
| 176 | VE-101-0095 | 10/30/2020 | PR | Low Battery (10/30/2020) |
| 177 | VE-101-0095 | 11/4/2020 | PE | Low Battery (11/04/2020)<br>Low Battery (11/03/2020)<br>Low Battery (11/02/2020) |
| 178 | VE-101-0095 | 11/6/2020 | SR | Low Battery (11/06/2020)<br>Low Battery (11/05/2020) |
| 179 | VE-101-0096 | 1/23/2020 | XZ | Sign Vandalism |
| 180 | VE-101-0098 | 1/3/2020 | CR | Fail To Check In (01/03/2020)<br>Fail To Check In (01/02/2020)<br>Fail To Check In (01/01/2020)<br>Fail To Check In (12/31/2019) |
| 181 | VE-101-0098 | 1/20/2020 | CR | Fail To Check In (01/20/2020)<br>Fail To Check In (01/19/2020)<br>Fail To Check In (01/18/2020)<br>Fail To Check In (01/17/2020)<br>Fail To Check In (01/16/2020)<br>Fail To Check In (01/15/2020)<br>Fail To Check In (01/14/2020)<br>Fail To Check In (01/13/2020)<br>Fail... |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 182 | VE-101-0098 | 4/10/2020 | PE | programing issue |
| 183 | VE-101-0098 | 4/13/2020 | PE | programing issue |
| 184 | VE-101-0098 | 5/11/2020 | CU | CELL ISSUE |
| 185 | VE-101-0098 | 5/14/2020 | CR | Front or Outer Door Alarm (05/14/2020) |
| 186 | VE-101-0098 | 6/8/2020 | NP | Tilt Alarm (06/08/2020) |
| 187 | VE-101-0098 | 7/13/2020 | NP | Tilt Alarm (07/10/2020) |
| 188 | VE-101-0098 | 8/6/2020 | PE | Tilt Alarm (08/06/2020) |
| 189 | VE-101-0099 | 8/21/2020 | XK | Fail To Check In (08/21/2020)<br>Fail To Check In (08/20/2020)<br>Fail To Check In (08/19/2020)<br>Fail To Check In (08/18/2020) |
| 190 | VE-101-0099 | 10/20/2020 | XK | Fail To Check In (10/20/2020)<br>Fail To Check In (10/19/2020)<br>Fail To Check In (10/18/2020)<br>Fail To Check In (10/17/2020)<br>Fail To Check In (10/16/2020)<br>Fail To Check In (10/15/2020) |
| 191 | VE-101-0099 | 10/29/2020 | PR | program repaired |
| 192 | VE-101-0099 | 11/6/2020 | PE | Tilt Alarm (11/06/2020)<br>Tilt Alarm (11/05/2020) |
| 193 | VE-101-0106 | 12/7/2020 | OM | Outer door issue |
| 194 | VE-101-0117 | 3/16/2020 | NP | Tilt Alarm (03/11/2020)<br>Tilt Alarm (03/10/2020) |
| 195 | VE-101-0117 | 4/15/2020 | PE | Tilt Alarm (04/15/2020) |
| 196 | VE-101-0126 | 4/2/2020 | BE | Low Battery (04/01/2020)<br>Low Battery (04/02/2020)<br>Low Battery (03/31/2020)<br>Low Battery (03/30/2020)<br>Low Battery (03/29/2020)<br>Low Battery (03/28/2020)<br>Low Battery (03/27/2020)<br>Low Battery (03/26/2020) |
| 197 | VE-101-0126 | 5/8/2020 | BE | Low Battery (05/08/2020) |
| 198 | VE-101-0127 | 1/2/2020 | XK | Fail To Check In (01/02/2020)<br>Fail To Check In (01/01/2020)<br>Fail To Check In (12/31/2019)<br>Fail To Check In (12/30/2019)<br>Fail To Check In (12/29/2019)<br>Fail To Check In (12/28/2019)<br>Fail To Check In (12/27/2019)<br>Fail To Check In (12/26/2019) |
| 199 | VE-101-0137 | 9/24/2020 | CR | See answering service |
| 200 | VE-101-0146 | 11/12/2020 | ZE | Sign Issue |
| 201 | VE-101-0156 | 2/4/2020 | OU | Front or Outer Door Alarm (02/04/2020) |
| 202 | VE-101-0156 | 2/6/2020 | OM | Front or Outer Door Alarm (02/06/2020)<br>Front or Outer Door Alarm (02/05/2020) |
| 203 | VE-101-0156 | 11/24/2020 | BE | Low Battery (11/24/2020) |
| 204 | VE-101-0156 | 12/7/2020 | XK | Fail To Check In (12/07/2020) |
| 205 | VE-101-0156 | 12/8/2020 | XK | Fail To Check In (12/08/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 206 | VE-101-0166 | 4/2/2020 | BE | Low Battery (04/01/2020)<br>Low Battery (04/02/2020)<br>Low Battery (03/31/2020)<br>Low Battery (03/30/2020)<br>Low Battery (03/29/2020)<br>Low Battery (03/28/2020)<br>Low Battery (03/27/2020)<br>Low Battery (03/26/2020)<br>Low Battery (03/25/2020) |
| 207 | VE-101-0166 | 9/24/2020 | CR | See answering service |
| 208 | VE-101-0167 | 11/4/2020 | KE | TTY Alarm (11/04/2020)<br>TTY Display Error (11/04/2020)<br>TTY Alarm (11/03/2020)<br>TTY Display Error (11/03/2020) |
| 209 | VE-101-0186 | 10/12/2020 | XK | XK-XI |
| 210 | VE-101-0186 | 12/1/2020 | XK | Handset Alarm (12/01/2020)<br>Lamp Alarm (12/01/2020)<br>Front or Outer Door Alarm (12/01/2020) |
| 211 | VE-101-0187 | 9/24/2020 | CR | See answering service |
| 212 | VE-101-0196 | 7/10/2020 | BE | Low Battery (07/10/2020)<br>Low Battery (07/09/2020) |
| 213 | VE-101-0197 | 9/23/2020 | CR | Cell Issue |
| 214 | VE-101-0197 | 10/21/2020 | AV | RE-drill to speck |
| 215 | VE-101-0206 | 11/25/2020 | CR | Cell issue |
| 216 | VE-101-0207 | 10/21/2020 | CR | Cell issue |
| 217 | VE-101-0217 | 1/2/2020 | BE | Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30/2019)<br>Low Battery (12/29/2019) |
| 218 | VE-101-0217 | 1/7/2020 | BE | Low Battery (01/07/2020)<br>Low Battery (01/06/2020)<br>Low Battery (01/05/2020)<br>Low Battery (01/04/2020) |
| 219 | VE-101-0217 | 10/7/2020 | BE | Low Battery (10/07/2020) |
| 220 | VE-101-0217 | 10/12/2020 | BE | Low Battery (10/12/2020)<br>Low Battery (10/11/2020) |
| 221 | VE-101-0217 | 11/20/2020 | BE | Low Battery (11/20/2020) |
| 222 | VE-101-0217 | 12/15/2020 | SR | Low Battery (12/15/2020)<br>Low Battery (12/14/2020)<br>Low Battery (12/13/2020)<br>Low Battery (12/12/2020) |
| 223 | VE-101-0217 | 12/16/2020 | BE | Low Battery (12/16/2020) |
| 224 | VE-101-0226 | 4/8/2020 | OR | Front or Outer Door Alarm (04/08/2020) |
| 225 | VE-101-0226 | 8/7/2020 | CR | Cell Issue |
| 226 | VE-101-0226 | 9/2/2020 | BE | Low Battery (09/02/2020)<br>Low Battery (09/01/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 227 | VE-101-0227 | 1/2/2020 | BE | Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30/2019)<br>Low Battery (12/29/2019)<br>Low Battery (12/28/2019)<br>Low Battery (12/27/2019)<br>Low Battery (12/26/2019)<br>Low Battery (12/25/2019)<br>Low Battery (12/24... |
| 228 | VE-101-0227 | 1/14/2020 | BE | Low Battery (01/14/2020)<br>Low Battery (01/13/2020)<br>Low Battery (01/12/2020) |
| 229 | VE-101-0227 | 4/13/2020 | BE | Low Battery (04/13/2020) |
| 230 | VE-101-0227 | 9/16/2020 | PR | Program Issue |
| 231 | VE-101-0227 | 9/23/2020 | CR | Cell Issue |
| 232 | VE-101-0247 | 6/10/2020 | BE | Low Battery (06/10/2020)<br>Low Battery (06/09/2020)<br>Low Battery (06/08/2020)<br>Low Battery (06/07/2020)<br>Low Battery (06/06/2020)<br>Low Battery (06/05/2020)<br>Low Battery (06/04/2020)<br>Low Battery (06/03/2020)<br>Low Battery (06/02/2020)<br>Low Battery (06/01... |
| 233 | VE-101-0247 | 8/7/2020 | CR | Cell Issue |
| 234 | VE-101-0247 | 9/23/2020 | CR | Cell Issue |
| 235 | VE-101-0256 | 2/3/2020 | BE | Low Battery (02/03/2020)<br>Low Battery (02/02/2020)<br>Low Battery (02/01/2020) |
| 236 | VE-101-0256 | 2/10/2020 | BE | Low Battery (02/10/2020)<br>Low Battery (02/09/2020)<br>Low Battery (02/08/2020) |
| 237 | VE-101-0256 | 8/7/2020 | CR | Cell Issue |
| 238 | VE-101-0256 | 12/1/2020 | OR | Front or Outer Door Alarm (12/01/2020)<br>Front or Outer Door Alarm (11/30/2020)<br>Front or Outer Door Alarm (11/29/2020)<br>Front or Outer Door Alarm (11/28/2020) |
| 239 | VE-101-0257 | 1/2/2020 | OR | Front or Outer Door Alarm (01/02/2020)<br>Front or Outer Door Alarm (01/01/2020)<br>Front or Outer Door Alarm (12/31/2019)<br>Front or Outer Door Alarm (12/30/2019)<br>Front or Outer Door Alarm (12/29/2019)<br>Front or Outer Door Alarm (12/28/2019)<br>Front or Out... |
| 240 | VE-101-0257 | 11/11/2020 | HE | Handset Alarm (11/11/2020)<br>Handset Alarm (11/10/2020)<br>Handset Alarm (11/09/2020) |
| 241 | VE-101-0266 | 8/7/2020 | CR | Cell Issue |
| 242 | VE-101-0276 | 8/7/2020 | CR | Cell Issue |
| 243 | VE-101-0276 | 11/16/2020 | XK | XK |
| 244 | VE-101-0276 | 11/20/2020 | BE | Low Battery (11/20/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 245 | VE-101-0277 | 10/12/2020 | BE | Low Battery (10/12/2020)<br>Low Battery (10/11/2020)<br>Low Battery (10/10/2020) |
| 246 | VE-101-0286 | 1/6/2020 | BE | Low Battery (01/06/2020)<br>Low Battery (01/05/2020)<br>Low Battery (01/04/2020)<br>Low Battery (01/03/2020)<br>Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30/2019)<br>Low Battery (12/29/2019)<br>Low Battery (12/28... |
| 247 | VE-101-0286 | 2/10/2020 | BE | Low Battery (02/10/2020) |
| 248 | VE-101-0286 | 2/12/2020 | LE | Lamp Alarm (02/12/2020)<br>Lamp Alarm (02/11/2020) |
| 249 | VE-101-0286 | 8/7/2020 | CR | Cell Issue |
| 250 | VE-101-0287 | 7/28/2020 | BE | Power/Solar Alarm (07/28/2020)<br>Power/Solar Alarm (07/27/2020)<br>Power/Solar Alarm (07/26/2020)<br>Power/Solar Alarm (07/25/2020)<br>Power/Solar Alarm (07/24/2020) |
| 251 | VE-101-0287 | 7/29/2020 | SE | Power/Solar Alarm (07/29/2020) |
| 252 | VE-101-0287 | 7/30/2020 | PE | Power/Solar Alarm (07/30/2020) |
| 253 | VE-101-0287 | 8/7/2020 | BE | Low Battery (08/07/2020)<br>Low Battery (08/06/2020) |
| 254 | VE-101-0306 | 2/18/2020 | BE | Low Battery (02/18/2020) |
| 255 | VE-101-0326 | 1/24/2020 | XZ | Sign Vandalism |
| 256 | VE-101-0326 | 10/6/2020 | CU | Fail To Check In (10/06/2020)<br>Fail To Check In (10/05/2020)<br>Fail To Check In (10/04/2020)<br>Fail To Check In (10/03/2020)<br>Fail To Check In (10/02/2020)<br>Fail To Check In (10/01/2020) |
| 257 | VE-101-0327 | 9/14/2020 | KE | TTY issue |
| 258 | VE-101-0332 | 5/15/2020 | CR | Cell issue |
| 259 | VE-101-0332 | 9/16/2020 | CR | Program Issue |
| 260 | VE-101-0337 | 7/10/2020 | BE | Low Battery (07/10/2020)<br>Low Battery (07/09/2020)<br>Low Battery (07/08/2020)<br>Low Battery (07/07/2020)<br>Low Battery (07/06/2020)<br>Low Battery (07/05/2020)<br>Low Battery (07/04/2020)<br>Low Battery (07/03/2020)<br>Low Battery (07/02/2020) |
| 261 | VE-101-0337 | 9/23/2020 | CR | Cell Issue |
| 262 | VE-101-0342 | 9/23/2020 | CR | Cell Issue |
| 263 | VE-101-0343 | 11/4/2020 | BE | Low Battery (11/04/2020) |
| 264 | VE-101-0357 | 9/23/2020 | CR | Cell Issue |
| 265 | VE-101-0357 | 9/24/2020 | BE | Low Battery (09/24/2020) |
| 266 | VE-101-0362 | 2/3/2020 | BE | Low Battery (02/03/2020) |
| 267 | VE-101-0362 | 3/18/2020 | BE | Low Battery (03/18/2020)<br>Low Battery (03/17/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 268 | VE-101-0362 | 4/7/2020 | BE | Low Battery (04/07/2020)<br>Low Battery (04/06/2020) |
| 269 | VE-101-0362 | 4/8/2020 | OR | Front or Outer Door Alarm (04/08/2020) |
| 270 | VE-101-0362 | 4/14/2020 | CR | Cell issue |
| 271 | VE-101-0362 | 5/15/2020 | PE | Cell issue |
| 272 | VE-101-0362 | 11/9/2020 | OR | Front or Outer Door Alarm (11/09/2020)<br>Front or Outer Door Alarm (11/08/2020) |
| 273 | VE-101-0372 | 4/3/2020 | OR | Front or Outer Door Alarm (04/01/2020)<br>Front or Outer Door Alarm (04/02/2020)<br>Front or Outer Door Alarm (03/31/2020)<br>Front or Outer Door Alarm (03/30/2020)<br>Front or Outer Door Alarm (03/29/2020)<br>Front or Outer Door Alarm (03/28/2020)<br>Front or Out... |
| 274 | VE-101-0372 | 4/7/2020 | BE | Low Battery (04/07/2020)<br>Low Battery (04/06/2020) |
| 275 | VE-101-0372 | 7/9/2020 | XK | Fail To Check In (07/02/2020)<br>Fail To Check In (07/01/2020)<br>Fail To Check In (06/30/2020)<br>Fail To Check In (06/29/2020)<br>Fail To Check In (06/28/2020) |
| 276 | VE-101-0373 | 5/5/2020 | BE | Low Battery (05/04/2020)<br>Low Battery (05/03/2020)<br>Low Battery (05/02/2020)<br>Low Battery (05/01/2020) |
| 277 | VE-101-0376 | 7/9/2020 | XK | Tilt Alarm (06/25/2020)<br>Fail To Check In (06/25/2020)<br>Power/Solar Alarm (06/25/2020)<br>Front or Outer Door Alarm (06/25/2020)<br>Tilt Alarm (06/24/2020)<br>Power/Solar Alarm (06/24/2020)<br>Front or Outer Door Alarm (06/24/2020)<br>Tilt Alarm (06/23/2020)<br>Po... |
| 278 | VE-101-0376 | 7/10/2020 | PE | CEll Issue |
| 279 | VE-101-0382 | 8/17/2020 | OR | Front or Outer Door Alarm (08/17/2020)<br>Front or Outer Door Alarm (08/16/2020)<br>Front or Outer Door Alarm (08/15/2020)<br>Front or Outer Door Alarm (08/14/2020)<br>Front or Outer Door Alarm (08/13/2020)<br>Front or Outer Door Alarm (08/12/2020) |
| 280 | VE-101-0386 | 11/9/2020 | OE | Front or Outer Door Alarm (11/09/2020)<br>Front or Outer Door Alarm (11/08/2020) |
| 281 | VE-101-0393 | 11/9/2020 | BE | Low Battery (11/09/2020)<br>Low Battery (11/08/2020)<br>Low Battery (11/07/2020) |
| 282 | VE-101-0396 | 8/17/2020 | BE | Low Battery (08/17/2020)<br>Low Battery (08/16/2020)<br>Low Battery (08/15/2020)<br>Low Battery (08/14/2020)<br>Low Battery (08/13/2020)<br>Low Battery (08/12/2020) |
| 283 | VE-101-0396 | 9/2/2020 | BE | Low Battery (09/02/2020)<br>Low Battery (08/31/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 284 | VE-101-0396 | 12/16/2020 | OR | Front or Outer Door Alarm (12/16/2020) |
| 285 | VE-101-0402 | 1/28/2020 | BE | Low Battery (01/28/2020)<br>Low Battery (01/27/2020) |
| 286 | VE-101-0402 | 4/7/2020 | BE | Low Battery (04/07/2020)<br>Low Battery (04/06/2020) |
| 287 | VE-101-0403 | 3/18/2020 | BE | Low Battery (03/18/2020)<br>Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020) |
| 288 | VE-101-0403 | 11/20/2020 | BE | Low Battery (11/20/2020)<br>Low Battery (11/19/2020) |
| 289 | VE-101-0403W | 3/18/2020 | BE | Low Battery (03/18/2020)<br>Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020) |
| 290 | VE-101-0403W | 11/20/2020 | BE | Low Battery (11/20/2020)<br>Low Battery (11/19/2020) |
| 291 | VE-101-0406 | 10/21/2020 | BE | Low Battery (10/21/2020) |
| 292 | VE-101-0412 | 5/15/2020 | CR | Cell issue |
| 293 | VE-101-0413 | 12/7/2020 | BE | Low Battery (12/07/2020)<br>Low Battery (12/06/2020)<br>Low Battery (12/05/2020) |
| 294 | VE-101-0413W | 12/7/2020 | BE | Low Battery (12/07/2020)<br>Low Battery (12/06/2020)<br>Low Battery (12/05/2020) |
| 295 | VE-101-0417W | 8/26/2020 | OR | Front or Outer Door Alarm (08/26/2020) |
| 296 | VE-101-0417W | 9/2/2020 | OR | Front or Outer Door Alarm (09/02/2020)<br>Front or Outer Door Alarm (09/01/2020) |
| 297 | VE-101-0422 | 9/23/2020 | CR | Cell Issue |
| 298 | VE-101-0422 | 12/21/2020 | PE | Cell issue |
| 299 | VE-101-0426 | 4/3/2020 | XK | Fail To Check In (04/01/2020)<br>Fail To Check In (04/02/2020)<br>Fail To Check In (03/31/2020)<br>Fail To Check In (03/30/2020)<br>Fail To Check In (03/29/2020)<br>Fail To Check In (03/28/2020)<br>Fail To Check In (03/27/2020)<br>Fail To Check In (03/26/2020)<br>Fail... |
| 300 | VE-101-0426 | 4/14/2020 | OR | Front or Outer Door Alarm (04/14/2020) |
| 301 | VE-101-0426 | 5/8/2020 | OR | Front or Outer Door Alarm (05/08/2020) |
| 302 | VE-101-0426 | 5/15/2020 | CR | Cell issue |
| 303 | VE-101-0426 | 5/19/2020 | OR | Front or Outer Door Alarm (05/19/2020)<br>Front or Outer Door Alarm (05/18/2020)<br>Front or Outer Door Alarm (05/17/2020)<br>Front or Outer Door Alarm (05/16/2020) |
| 304 | VE-101-0427 | 8/26/2020 | BE | Low Battery (08/24/2020) |
| 305 | VE-101-0427W | 8/26/2020 | BE | Low Battery (08/25/2020)<br>Low Battery (08/24/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 306 | VE-101-0433 | 3/18/2020 | BE | Low Battery (03/18/2020)<br>Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020)<br>Low Battery (03/14/2020)<br>Low Battery (03/13/2020)<br>Low Battery (03/12/2020)<br>Low Battery (03/11/2020)<br>Low Battery (03/10/2020)<br>Low Battery (03/09... |
| 307 | VE-101-0433 | 4/7/2020 | BE | Low Battery (04/07/2020)<br>TTY Alarm (04/07/2020)<br>TTY Display Error (04/07/2020)<br>Low Battery (04/06/2020)<br>TTY Alarm (04/06/2020)<br>TTY Display Error (04/06/2020)<br>Low Battery (04/05/2020)<br>TTY Alarm (04/05/2020)<br>TTY Display Error (04/05/2020)<br>TTY Al... |
| 308 | VE-101-0433W | 3/18/2020 | BE | Low Battery (03/18/2020)<br>Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020)<br>Low Battery (03/14/2020)<br>Low Battery (03/13/2020)<br>Low Battery (03/12/2020)<br>Low Battery (03/11/2020)<br>Low Battery (03/10/2020)<br>Low Battery (03/09... |
| 309 | VE-101-0433W | 4/7/2020 | BE | Low Battery (04/07/2020)<br>Low Battery (04/06/2020)<br>Low Battery (04/05/2020)<br>Low Battery (04/03/2020)<br>Low Battery (04/04/2020)<br>Low Battery (04/01/2020)<br>Low Battery (04/02/2020)<br>Low Battery (03/31/2020)<br>Low Battery (03/30/2020)<br>Low Battery (03/29... |
| 310 | VE-101-0433W | 12/21/2020 | OR | Front or Outer Door Alarm (12/21/2020)<br>Front or Outer Door Alarm (12/20/2020)<br>Front or Outer Door Alarm (12/19/2020) |
| 311 | VE-101-0433W | 12/22/2020 | OR | Front or Outer Door Alarm (12/22/2020) |
| 312 | VE-118-0002 | 7/13/2020 | BE | Low Battery (07/13/2020)<br>Low Battery (07/12/2020)<br>Low Battery (07/11/2020)<br>Low Battery (07/10/2020)<br>Low Battery (07/09/2020)<br>Low Battery (07/08/2020)<br>Low Battery (07/07/2020)<br>Low Battery (07/06/2020)<br>Low Battery (07/05/2020)<br>Low Battery (07/04... |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 313 | VE-118-0002 | 10/6/2020 | BE | Low Battery (10/06/2020) |
| 314 | VE-118-0002 | | | Front or Outer Door Alarm (12/15/2020) |
| | | 12/15/2020 | OR | Front or Outer Door Alarm (12/14/2020) |
| 315 | VE-118-0003 | | | Low Battery (05/05/2020) |
| | | | | Low Battery (05/06/2020) |
| | | | | Low Battery (05/04/2020) |
| | | | | Low Battery (05/03/2020) |
| | | | | Low Battery (05/02/2020) |
| | | | | Low Battery (05/01/2020) |
| | | | | Low Battery (04/30/2020) |
| | | | | Low Battery (04/29/2020) |
| | | | | Low Battery (04/28/2020) |
| | | 5/6/2020 | BE | Low Battery (04/27... |
| 316 | VE-118-0052 | 8/3/2020 | OR | Front or Outer Door Alarm (08/03/2020) |
| 317 | VE-118-0052 | 12/4/2020 | OR | Front Outer door |
| 318 | VE-118-0058 | | | Low Battery (07/22/2020) |
| | | | | Low Battery (07/21/2020) |
| | | | | Low Battery (07/20/2020) |
| | | 7/22/2020 | BE | Low Battery (07/19/2020) |
| 319 | VE-118-0058 | | | Low Battery (07/30/2020) |
| | | | | Low Battery (07/29/2020) |
| | | | | Low Battery (07/28/2020) |
| | | | | Low Battery (07/27/2020) |
| | | | | Low Battery (07/26/2020) |
| | | | | Low Battery (07/25/2020) |
| | | | | Low Battery (07/24/2020) |
| | | 7/30/2020 | BE | Low Battery (07/23/2020) |
| 320 | VE-118-0058 | | | Front or Outer Door Alarm (12/04/2020) |
| | | 12/4/2020 | OR | Front or Outer Door Alarm (12/03/2020) |
| 321 | VE-118-0066 | 2/12/2020 | BE | Low Battery (02/12/2020) |
| 322 | VE-118-0068 | | | Low Battery (08/03/2020) |
| | | | | Low Battery (08/02/2020) |
| | | | | Low Battery (08/01/2020) |
| | | 8/3/2020 | BE | Low Battery (07/31/2020) |
| 323 | VE-118-0068 | | | TTY Alarm (09/04/2020) |
| | | | | TTY Display Error (09/04/2020) |
| | | | | TTY Alarm (09/03/2020) |
| | | 9/4/2020 | PR | TTY Display Error (09/03/2020) |
| 324 | VE-118-0096 | | | Low Battery (01/21/2020) |
| | | | | Low Battery (01/20/2020) |
| | | | | Low Battery (01/19/2020) |
| | | | | Low Battery (01/18/2020) |
| | | | | Power/Solar Alarm (01/18/2020) |
| | | | | Low Battery (01/17/2020) |
| | | | | Power/Solar Alarm (01/17/2020) |
| | | | | Low Battery (01/16/2020) |
| | | | | Power/Solar Alarm (01/16/2020) |
| | | 1/21/2020 | BE | ... |
| 325 | VE-118-0096 | | | Low Battery (12/01/2020) |
| | | | | Low Battery (11/30/2020) |
| | | | | Low Battery (11/29/2020) |
| | | | | Low Battery (11/28/2020) |
| | | 12/1/2020 | BR | Low Battery (11/27/2020) |
| 326 | VE-118-0096 | 12/4/2020 | BR | Low Battery (12/04/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 327 | VE-118-0106 | 11/19/2020 | XZ | Sign Vandalism |
| 328 | VE-118-0126 | 1/7/2020 | OR | Front or Outer Door Alarm (01/07/2020)<br>Front or Outer Door Alarm (01/06/2020)<br>Front or Outer Door Alarm (01/05/2020) |
| 329 | VE-118-0133 | 9/22/2020 | CR | Cell Issue |
| 330 | VE-118-0144 | 10/5/2020 | XK | Fail To Check In (10/05/2020)<br>Fail To Check In (10/04/2020)<br>Fail To Check In (10/03/2020)<br>Fail To Check In (10/02/2020)<br>Fail To Check In (10/01/2020) |
| 331 | VE-118-0147 | 1/21/2020 | LE | Lamp Alarm (01/21/2020) |
| 332 | VE-118-0147 | 6/11/2020 | LE | Lamp Alarm (06/09/2020)<br>Lamp Alarm (06/08/2020) |
| 333 | VE-118-0147 | 10/22/2020 | OR | Lamp Alarm (10/21/2020) |
| 334 | VE-118-0153 | 1/21/2020 | BE | Low Battery (01/21/2020)<br>Low Battery (01/20/2020)<br>Low Battery (01/19/2020)<br>Low Battery (01/18/2020)<br>Low Battery (01/17/2020)<br>Low Battery (01/16/2020)<br>Low Battery (01/15/2020)<br>Low Battery (01/14/2020)<br>Low Battery (01/13/2020)<br>Low Battery (01/12... |
| 335 | VE-118-0153 | 9/3/2020 | XK | Tilt Alarm (09/03/2020)<br>Power/Solar Alarm (09/03/2020)<br>Tilt Alarm (09/02/2020)<br>Power/Solar Alarm (09/02/2020)<br>Tilt Alarm (09/01/2020) |
| 336 | VE-118-0153 | 9/22/2020 | CR | Cell Issue |
| 337 | VE-118-0192 | 12/15/2020 | BE | Low Battery (12/15/2020)<br>Low Battery (12/14/2020) |
| 338 | VE-118-0196 | 2/24/2020 | BE | Low Battery (02/24/2020) |
| 339 | VE-118-0202 | 9/22/2020 | CR | Cell Issue |
| 340 | VE-118-0203 | 4/14/2020 | LE | Lamp Alarm (04/13/2020) |
| 341 | VE-118-0206 | 10/22/2020 | BE | Low Battery (10/22/2020)<br>Low Battery (10/21/2020)<br>Low Battery (10/20/2020) |
| 342 | VE-118-0212 | 9/22/2020 | CR | Cell Issue |
| 343 | VE-118-0212 | 10/5/2020 | BE | Low Battery (10/05/2020)<br>Low Battery (10/04/2020)<br>Low Battery (10/03/2020)<br>Low Battery (10/02/2020)<br>Fail To Check In (10/01/2020)<br>Low Battery (10/01/2020) |
| 344 | VE-118-0213 | 12/2/2020 | CR | Fail To Check In (12/02/2020)<br>Fail To Check In (12/01/2020)<br>Fail To Check In (11/30/2020)<br>Fail To Check In (11/29/2020)<br>Fail To Check In (11/28/2020) |
| 345 | VE-118-0216 | 3/17/2020 | BE | Low Battery (03/17/2020) |
| 346 | VE-118-0216 | 12/15/2020 | HE | Hand set issue |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 347 | VE-118-0222 | 3/17/2020 | BE | Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020)<br>Low Battery (03/14/2020)<br>Low Battery (03/13/2020) |
| 348 | VE-118-0222 | 11/19/2020 | BE | Low Battery (11/19/2020)<br>Low Battery (11/18/2020)<br>Low Battery (11/17/2020)<br>Low Battery (11/16/2020)<br>Low Battery (11/15/2020)<br>Low Battery (11/14/2020)<br>Low Battery (11/13/2020)<br>Low Battery (11/12/2020)<br>Low Battery (11/11/2020)<br>Low Battery (11/10... |
| 349 | VE-118-0226 | 1/8/2020 | OR | Front or Outer Door Alarm (01/08/2020)<br>Front or Outer Door Alarm (01/07/2020) |
| 350 | VE-118-0226 | 2/24/2020 | OR | Front or Outer Door Alarm (02/24/2020)<br>Front or Outer Door Alarm (02/23/2020)<br>Front or Outer Door Alarm (02/22/2020)<br>Front or Outer Door Alarm (02/21/2020)<br>Front or Outer Door Alarm (02/18/2020)<br>Front or Outer Door Alarm (02/17/2020) |
| 351 | VE-118-0226 | 9/22/2020 | CR | Cell Issue |
| 352 | VE-118-0226 | 12/9/2020 | OR | Front or Outer Door Alarm (12/09/2020)<br>Front or Outer Door Alarm (12/08/2020) |
| 353 | VE-118-0227 | 9/17/2020 | CR | Program issue |
| 354 | VE-118-0227 | 12/15/2020 | OR | Front or Outer Door Alarm (12/15/2020)<br>Front or Outer Door Alarm (12/14/2020)<br>Front or Outer Door Alarm (12/13/2020) |
| 355 | VE-118-0236 | 9/22/2020 | CR | Cell Issue |
| 356 | VE-118-0246 | 3/17/2020 | BE | Low Battery (03/17/2020)<br>Low Battery (03/16/2020)<br>Low Battery (03/15/2020)<br>Low Battery (03/14/2020) |
| 357 | VE-118-0246 | 4/14/2020 | BE | Low Battery (04/14/2020) |
| 358 | VE-118-0246 | 5/7/2020 | BE | Low Battery (05/05/2020)<br>Low Battery (05/04/2020) |
| 359 | VE-118-0246 | 9/22/2020 | CR | Cell Issue |
| 360 | VE-118-0247 | 2/24/2020 | PE | Fail To Check In (02/24/2020) |
| 361 | VE-118-0247 | 5/7/2020 | PE | Fail To Check In (05/07/2020)<br>Fail To Check In (05/05/2020)<br>Fail To Check In (05/06/2020)<br>Fail To Check In (05/04/2020)<br>Fail To Check In (05/03/2020)<br>Fail To Check In (05/02/2020)<br>Fail To Check In (05/01/2020)<br>Fail To Check In (04/30/2020)<br>Fail... |
| 362 | VE-118-0256 | 9/22/2020 | CR | Cell Issue |
| 363 | VE-118-0267 | 9/17/2020 | CR | Program issue |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 364 | VE-118-0273 | 7/13/2020 | BE | Low Battery (07/13/2020)<br>Low Battery (07/12/2020)<br>Low Battery (07/11/2020)<br>Low Battery (07/10/2020)<br>Low Battery (07/09/2020)<br>Low Battery (07/08/2020)<br>Low Battery (07/07/2020)<br>Low Battery (07/06/2020)<br>Low Battery (07/05/2020)<br>Low Battery (07/04... |
| 365 | VE-118-0273 | 10/5/2020 | BE | Low Battery (10/05/2020)<br>Low Battery (10/04/2020) |
| 366 | VE-118-0282 | 1/29/2020 | BE | Low Battery (01/29/2020)<br>Low Battery (01/28/2020)<br>Low Battery (01/27/2020)<br>Low Battery (01/26/2020) |
| 367 | VE-118-0282 | 7/13/2020 | BE | Low Battery (07/13/2020)<br>Low Battery (07/12/2020)<br>Low Battery (07/11/2020)<br>Low Battery (07/10/2020)<br>Low Battery (07/09/2020)<br>Lamp Alarm (07/08/2020)<br>Low Battery (07/08/2020)<br>Low Battery (07/07/2020)<br>Low Battery (07/06/2020)<br>Low Battery (07/05/... |
| 368 | VE-118-0283 | 9/22/2020 | CR | Cell Issue |
| 369 | VE-118-0287 | 1/8/2020 | BE | Low Battery (01/08/2020)<br>Low Battery (01/07/2020)<br>Low Battery (01/06/2020)<br>Low Battery (01/05/2020)<br>Low Battery (01/04/2020)<br>Low Battery (01/03/2020)<br>Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30... |
| 370 | VE-118-0296 | 12/4/2020 | OR | Front or Outer Door Alarm (12/04/2020)<br>Front or Outer Door Alarm (12/03/2020) |
| 371 | VE-118-0297 | 9/17/2020 | BE | Low Battery (09/17/2020)<br>Low Battery (09/16/2020) |
| 372 | VE-118-0307 | 12/10/2020 | ZE | Sign replaced |
| 373 | VE-118-0313 | 9/10/2020 | KE | TTY Alarm (09/10/2020)<br>TTY Display Error (09/10/2020) |
| 374 | VE-118-0313 | 12/9/2020 | OR | Front or Outer Door Alarm (12/09/2020)<br>Front or Outer Door Alarm (12/08/2020) |
| 375 | VE-118-0323 | 9/22/2020 | CR | Cell Issue |
| 376 | VE-118-0326 | 3/17/2020 | XK | Fail To Check In (03/17/2020)<br>Fail To Check In (03/16/2020)<br>Fail To Check In (03/15/2020)<br>Fail To Check In (03/14/2020)<br>Fail To Check In (03/13/2020)<br>Fail To Check In (03/12/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 377 | VE-118-0326 | 4/1/2020 | XK | Power/Solar Alarm (03/31/2020)<br>Front or Outer Door Alarm (03/31/2020)<br>Power/Solar Alarm (03/30/2020)<br>Front or Outer Door Alarm (03/30/2020)<br>Power/Solar Alarm (03/29/2020)<br>Front or Outer Door Alarm (03/29/2020)<br>Power/Solar Alarm (03/28/2020)<br>Fron... |
| 378 | VE-118-0326 | 6/11/2020 | CR | Handset Alarm (06/10/2020) |
| 379 | VE-118-0326 | 9/17/2020 | CR | Program issue |
| 380 | VE-118-0326 | 12/4/2020 | OR | Front or Outer Door Alarm (12/04/2020)<br>Front or Outer Door Alarm (12/03/2020) |
| 381 | VE-126-0012 | 1/21/2020 | BE | Low Battery (01/21/2020) |
| 382 | VE-126-0012 | 2/3/2020 | XK | XK-Reported by CHP |
| 383 | VE-126-0012 | 5/7/2020 | LR | Lamp Alarm (05/07/2020) |
| 384 | VE-126-0012 | 5/19/2020 | CR | Cell issue repaired |
| 385 | VE-126-0012 | 11/16/2020 | XK | Handset Alarm (11/16/2020)<br>Tilt Alarm (11/16/2020)<br>Low Battery (11/16/2020)<br>Handset Alarm (11/15/2020)<br>Tilt Alarm (11/15/2020)<br>Low Battery (11/15/2020)<br>Handset Alarm (11/14/2020)<br>Tilt Alarm (11/14/2020)<br>Low Battery (11/14/2020) |
| 386 | VE-126-0012 | 11/17/2020 | HR | Handset Alarm (11/17/2020) |
| 387 | VE-126-0012 | 11/18/2020 | BU | Low Battery (11/18/2020) |
| 388 | VE-126-0012 | 11/19/2020 | BE | Low Battery (11/19/2020) |
| 389 | VE-126-0012 | 12/3/2020 | LE | Lamp Alarm (12/03/2020) |
| 390 | VE-126-0022 | 5/19/2020 | CR | Cell issue repaired |
| 391 | VE-126-0032 | 5/19/2020 | CR | Cell issue repaired |
| 392 | VE-126-0032 | 12/9/2020 | BE | Low Battery (12/09/2020) |
| 393 | VE-126-0042 | 12/9/2020 | LE | Lamp Alarm (12/09/2020)<br>Lamp Alarm (12/08/2020) |
| 394 | VE-126-0052 | 5/19/2020 | CR | Cell issue repaired |
| 395 | VE-126-0063 | 1/6/2020 | BE | Low Battery (01/06/2020)<br>Low Battery (01/05/2020)<br>Low Battery (01/04/2020)<br>Low Battery (01/03/2020)<br>Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30/2019)<br>Low Battery (12/29/2019)<br>Low Battery (12/28... |
| 396 | VE-126-0063 | 1/28/2020 | BE | Low Battery (01/28/2020)<br>Low Battery (01/27/2020)<br>Low Battery (01/26/2020)<br>Low Battery (01/25/2020)<br>Low Battery (01/24/2020)<br>Low Battery (01/23/2020)<br>Low Battery (01/22/2020)<br>Low Battery (01/13/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 397 | VE-126-0093 | 1/6/2020 | XK | Fail To Check In (01/06/2020)<br>Fail To Check In (01/05/2020)<br>Fail To Check In (01/04/2020) |
| 398 | VE-126-0102 | 11/17/2020 | BE | Low Battery (11/17/2020)<br>Low Battery (11/16/2020)<br>Low Battery (11/15/2020) |
| 399 | VE-126-0103 | 4/10/2020 | PE | Programing issue |
| 400 | VE-126-0103 | 10/9/2020 | BE | Low Battery (10/09/2020)<br>Low Battery (10/08/2020) |
| 401 | VE-126-0113 | 12/10/2020 | BE | Low Battery (12/10/2020) |
| 402 | VE-126-0122 | 10/30/2020 | BE | Low Battery (10/30/2020)<br>Low Battery (10/29/2020)<br>Low Battery (10/28/2020)<br>Low Battery (10/27/2020) |
| 403 | VE-126-0132 | 4/8/2020 | KE | TTY Alarm (04/07/2020)<br>TTY Keypad Error (04/07/2020)<br>TTY Alarm (04/06/2020)<br>TTY Keypad Error (04/06/2020) |
| 404 | VE-126-0133 | 9/9/2020 | CR | Fail To Check In (09/09/2020) |
| 405 | VE-126-0133 | 10/30/2020 | BE | Low Battery (10/27/2020) |
| 406 | VE-126-0136 | 3/31/2020 | BE | Low Battery (03/31/2020)<br>Low Battery (03/30/2020)<br>Low Battery (03/29/2020)<br>Low Battery (03/28/2020)<br>Low Battery (03/27/2020)<br>Low Battery (03/26/2020) |
| 407 | VE-126-0137 | 5/18/2020 | CR | Cell issue |
| 408 | VE-126-0142 | 3/31/2020 | XK | Fail To Check In (03/31/2020)<br>Fail To Check In (03/30/2020)<br>Fail To Check In (03/29/2020)<br>Fail To Check In (03/28/2020)<br>Fail To Check In (03/27/2020) |
| 409 | VE-126-0142 | 4/8/2020 | BE | Low Battery (04/08/2020) |
| 410 | VE-126-0142 | 5/6/2020 | BE | Low Battery (05/05/2020)<br>Low Battery (05/06/2020)<br>Low Battery (05/04/2020)<br>Low Battery (05/03/2020)<br>Low Battery (05/02/2020)<br>Low Battery (05/01/2020)<br>Low Battery (04/30/2020)<br>Low Battery (04/29/2020)<br>Low Battery (04/28/2020)<br>Low Battery (04/27... |
| 411 | VE-126-0142 | 12/3/2020 | XS | Site Vandalism |
| 412 | VE-126-0147 | 1/21/2020 | BE | Low Battery (01/21/2020) |
| 413 | VE-126-0152 | 11/17/2020 | OR | Front or Outer Door Alarm (11/17/2020)<br>Front or Outer Door Alarm (11/16/2020)<br>Front or Outer Door Alarm (11/15/2020) |
| 414 | VE-126-0153 | 1/21/2020 | BE | Low Battery (01/21/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 415 | VE-126-0156 | 12/21/2020 | LE | Lamp Alarm (12/21/2020)<br>Lamp Alarm (12/20/2020)<br>Lamp Alarm (12/19/2020)<br>Lamp Alarm (12/18/2020)<br>Lamp Alarm (12/17/2020)<br>Lamp Alarm (12/16/2020)<br>Lamp Alarm (12/15/2020)<br>Lamp Alarm (12/14/2020)<br>Lamp Alarm (12/13/2020)<br>Lamp Alarm (12/12/2020) |
| 416 | VE-126-0157 | 1/29/2020 | OR | See answering service |
| 417 | VE-126-0157 | 5/18/2020 | CR | Cell issue |
| 418 | VE-126-0162 | 10/13/2020 | BE | Low Battery (10/13/2020) |
| 419 | VE-126-0163 | 3/31/2020 | BE | Low Battery (03/31/2020) |
| 420 | VE-126-0167 | 3/17/2020 | BE | Low Battery (03/17/2020) |
| 421 | VE-126-0167 | 8/12/2020 | CE | Fail To Check In (08/12/2020)<br>Fail To Check In (08/11/2020)<br>Fail To Check In (08/10/2020)<br>Fail To Check In (08/09/2020)<br>Fail To Check In (08/08/2020)<br>Fail To Check In (08/07/2020)<br>Fail To Check In (08/06/2020) |
| 422 | VE-126-0172 | 9/10/2020 | CR | Fail To Check In (09/10/2020) |
| 423 | VE-126-0172 | 10/6/2020 | CR | Fail To Check In (10/06/2020)<br>Fail To Check In (10/05/2020)<br>Fail To Check In (10/04/2020)<br>Fail To Check In (10/03/2020)<br>Fail To Check In (10/02/2020)<br>Fail To Check In (10/01/2020)<br>Fail To Check In (09/25/2020)<br>Fail To Check In (09/24/2020)<br>Fail... |
| 424 | VE-126-0172 | 10/19/2020 | PE | Fail To Check In (10/19/2020)<br>Fail To Check In (10/18/2020) |
| 425 | VE-126-0176 | 12/9/2020 | OR | Front or Outer Door Alarm (12/09/2020)<br>Front or Outer Door Alarm (12/08/2020)<br>Front or Outer Door Alarm (12/07/2020)<br>Front or Outer Door Alarm (12/06/2020)<br>Front or Outer Door Alarm (12/05/2020) |
| 426 | VE-126-0178 | 1/29/2020 | BE | Low Battery (01/29/2020) |
| 427 | VE-126-0178 | 4/8/2020 | BE | Low Battery (04/08/2020)<br>Low Battery (04/07/2020)<br>Low Battery (04/06/2020)<br>Low Battery (04/05/2020)<br>Low Battery (04/03/2020)<br>Low Battery (04/04/2020) |
| 428 | VE-126-0192 | 6/10/2020 | OR | Front or Outer Door Alarm (06/10/2020) |
| 429 | VE-126-0192 | 9/21/2020 | CR | Cell Issue |
| 430 | VE-126-0192 | 12/2/2020 | OR | Front or Outer Door Alarm (12/02/2020)<br>Front or Outer Door Alarm (12/01/2020)<br>Front or Outer Door Alarm (11/30/2020)<br>Front or Outer Door Alarm (11/29/2020)<br>Front or Outer Door Alarm (11/28/2020)<br>Front or Outer Door Alarm (11/27/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 431 | VE-126-0197 | 10/9/2020 | CR | Cell issue |
| 432 | VE-126-0226 | 5/18/2020 | CR | Cell issue |
| 433 | VE-126-0226 | 7/29/2020 | BE | Low Battery (07/29/2020)<br>Low Battery (07/28/2020)<br>Low Battery (07/27/2020)<br>Low Battery (07/26/2020)<br>Low Battery (07/25/2020)<br>Low Battery (07/24/2020)<br>Low Battery (07/23/2020)<br>Low Battery (07/22/2020)<br>Low Battery (07/21/2020)<br>Low Battery (07/20... |
| 434 | VE-126-0227 | 10/19/2020 | HE | Handset Alarm (10/19/2020)<br>Handset Alarm (10/18/2020)<br>Handset Alarm (10/17/2020)<br>Handset Alarm (10/16/2020)<br>Handset Alarm (10/15/2020)<br>Handset Alarm (10/14/2020)<br>Handset Alarm (10/13/2020) |
| 435 | VE-126-0242 | 1/7/2020 | BE | Low Battery (01/07/2020)<br>Low Battery (01/06/2020)<br>Low Battery (01/05/2020)<br>Low Battery (01/04/2020)<br>Low Battery (01/03/2020)<br>Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30/2019) |
| 436 | VE-126-0242 | 2/10/2020 | LE | Lamp Alarm (02/10/2020) |
| 437 | VE-126-0243 | 1/21/2020 | BE | Low Battery (01/21/2020) |
| 438 | VE-126-0243 | 9/18/2020 | CR | Cell Issue |
| 439 | VE-126-0246 | 2/10/2020 | OR | door issue |
| 440 | VE-126-0246 | 12/3/2020 | KE | TTY Alarm (12/03/2020)<br>TTY Display Error (12/03/2020) |
| 441 | VE-126-0257 | 9/21/2020 | ZR | Sign Repair |
| 442 | VE-126-0262 | 6/10/2020 | KR | TTY Alarm (06/09/2020)<br>TTY Display Error (06/09/2020)<br>TTY Alarm (06/08/2020)<br>TTY Display Error (06/08/2020) |
| 443 | VE-126-0262 | 7/13/2020 | HE | Handset Alarm (07/13/2020)<br>Lamp Alarm (07/13/2020)<br>Handset Alarm (07/12/2020)<br>Lamp Alarm (07/12/2020)<br>Handset Alarm (07/11/2020)<br>Lamp Alarm (07/11/2020)<br>Handset Alarm (07/10/2020)<br>Lamp Alarm (07/10/2020)<br>Handset Alarm (07/09/2020)<br>Lamp Alarm (... |
| 444 | VE-126-0263 | 8/20/2020 | BE | Low Battery (08/20/2020)<br>Low Battery (08/19/2020)<br>Low Battery (08/18/2020) |
| 445 | VE-126-0267 | 5/18/2020 | CR | Cell Issue |
| 446 | VE-126-0267 | 7/13/2020 | HE | Handset Alarm (07/13/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 447 | VE-126-0273 | 9/18/2020 | CR | Cell Issue |
| 448 | VE-126-0273 | 9/21/2020 | ZE | Sign and housing repair |
| 449 | VE-126-0276 | 2/27/2020 | SR | Low Battery (02/27/2020)<br>Low Battery (02/26/2020)<br>Low Battery (02/24/2020)<br>Low Battery (02/23/2020) |
| 450 | VE-126-0276 | 5/6/2020 | HE | Handset Alarm (05/05/2020)<br>Handset Alarm (05/06/2020) |
| 451 | VE-126-0276 | 5/18/2020 | CR | Low Battery (05/18/2020)<br>Low Battery (05/17/2020)<br>Handset Alarm (05/16/2020)<br>Handset Alarm (05/15/2020) |
| 452 | VE-126-0276 | 6/10/2020 | HE | Handset Alarm (06/10/2020) |
| 453 | VE-126-0276 | 7/13/2020 | HE | Handset Alarm (07/13/2020)<br>Handset Alarm (07/12/2020) |
| 454 | VE-126-0276 | 10/22/2020 | BE | Low Battery (10/22/2020) |
| 455 | VE-126-0276 | 11/17/2020 | HE | Handset Alarm (11/17/2020)<br>Handset Alarm (11/16/2020) |
| 456 | VE-126-0283 | 8/20/2020 | XT | Temp Removal |
| 457 | VE-126-0283 | 10/9/2020 | AV | Survey |
| 458 | VE-126-0283 | 10/14/2020 | XI | Install call box was temp removal. |
| 459 | VE-126-0286 | 1/7/2020 | BE | Low Battery (01/07/2020)<br>Low Battery (01/06/2020)<br>Low Battery (01/05/2020)<br>Low Battery (01/04/2020)<br>Low Battery (01/03/2020)<br>Low Battery (01/02/2020)<br>Low Battery (01/01/2020)<br>Low Battery (12/31/2019)<br>Low Battery (12/30/2019)<br>Low Battery (12/29... |
| 460 | VE-126-0286 | 5/18/2020 | CR | Cell Issue |
| 461 | VE-126-0296 | 9/18/2020 | AV | Housing repair and sign repair |
| 462 | VE-126-0297 | 9/21/2020 | XZ | Sign Vandalism |
| 463 | VE-126-0302 | 5/6/2020 | ZR | ZR-Sign Repaired |
| 464 | VE-126-0302 | 6/10/2020 | OR | Front or Outer Door Alarm (06/08/2020)<br>Front or Outer Door Alarm (06/07/2020) |
| 465 | VE-126-0302 | 9/10/2020 | BE | Low Battery (09/10/2020)<br>Low Battery (09/09/2020) |
| 466 | VE-126-0302 | 9/18/2020 | CR | Cell Issue |
| 467 | VE-126-0316 | 9/18/2020 | CR | Cell Issue |
| 468 | VE-126-0333 | 8/20/2020 | XT | Temp Removal |
| 469 | VE-126-0333 | 10/9/2020 | AV | Survey |
| 470 | VE-126-0333 | 10/23/2020 | XI | Call box Install<br>Was a Temp Removal. |
| 471 | VE-126-0336 | 1/7/2020 | BE | Low Battery (01/07/2020) |
| 472 | VE-126-0336 | 5/6/2020 | ZR | ZR-Sign Repaired |
| 473 | VE-126-0336 | 9/18/2020 | CR | Cell Issue |
| 474 | VE-126-0337 | 5/6/2020 | OR | Front or Outer Door Alarm (05/05/2020)<br>Front or Outer Door Alarm (05/06/2020) |
| 475 | VE-126-0337 | 8/20/2020 | XT | Temp Removal |
| 476 | VE-126-0337 | 10/9/2020 | CA | Call box survey |
| 477 | VE-126-0337 | 10/13/2020 | XI | Temp removal Back in service |
| 478 | VE-126-0342 | 2/10/2020 | OR | Front or Outer Door Alarm (02/10/2020) |

| | Sign | Date | Repair Code | DESCRIPTION |
|---|---|---|---|---|
| 479 | VE-150-0002 | 1/20/2020 | BE | Low Battery (01/20/2020)<br>Low Battery (01/19/2020)<br>Low Battery (01/18/2020)<br>Low Battery (01/17/2020) |
| 480 | VE-150-0002 | 9/9/2020 | CR | Fail To Check In (09/09/2020) |
| 481 | VE-150-0002 | 11/23/2020 | BE | Low Battery (11/23/2020)<br>Low Battery (11/22/2020) |
| 482 | VE-150-0018 | 7/15/2020 | CR | Programing Error (07/15/2020) |
| 483 | VE-150-0042 | 2/7/2020 | OR | Front or Outer Door Alarm (02/07/2020)<br>Front or Outer Door Alarm (02/06/2020) |
| 484 | VE-150-0042 | 7/14/2020 | BE | Low Battery (07/14/2020)<br>Low Battery (07/13/2020)<br>Low Battery (07/12/2020)<br>Low Battery (07/11/2020)<br>Low Battery (07/10/2020)<br>Low Battery (07/09/2020)<br>Low Battery (07/08/2020)<br>Low Battery (07/07/2020)<br>Low Battery (07/06/2020)<br>Low Battery (07/05... |
| 485 | VE-150-0042 | 11/11/2020 | BE | Low Battery (11/11/2020)<br>Low Battery (11/10/2020) |
| 486 | VE-150-0042 | 11/18/2020 | PE | Low Battery (11/18/2020)<br>Low Battery (11/17/2020)<br>Low Battery (11/16/2020)<br>Low Battery (11/15/2020)<br>Low Battery (11/14/2020)<br>Low Battery (11/13/2020) |
| 487 | VE-150-0042 | 11/23/2020 | SE | Low Battery (11/23/2020)<br>Low Battery (11/22/2020)<br>Low Battery (11/21/2020)<br>Low Battery (11/20/2020)<br>Low Battery (11/19/2020) |
| 488 | VE-150-0042 | 11/24/2020 | PE | Tilt Alarm (11/24/2020) |
| 489 | VE-150-0042 | 12/3/2020 | KE | TTY Alarm (12/03/2020)<br>TTY Keypad Error (12/03/2020) |
| 490 | VE-150-0312 | 7/29/2020 | BE | Low Battery (07/29/2020)<br>Low Battery (07/28/2020)<br>Low Battery (07/27/2020)<br>Low Battery (07/26/2020)<br>Low Battery (07/25/2020)<br>Low Battery (07/24/2020)<br>Low Battery (07/23/2020)<br>Low Battery (07/22/2020)<br>Low Battery (07/21/2020)<br>Low Battery (07/20... |

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 1 | VE-001-0002 | (805) 256-5942 | A | 3 | 12 | 4.0 | 195 | 410.0 | 2 |
| 2 | VE-001-0003 | (805) 850-8927 | A | 24 | 56 | 2.3 | 217 | 475.0 | 2 |
| 3 | VE-001-0006 | (805) 218-8439 | A | 2 | 11.0 | 5.5 | 207 | 444.0 | 2 |
| 4 | VE-001-0007 | (805) 256-0282 | A | 5 | 16.0 | 3.2 | 210 | 455.0 | 2 |
| 5 | VE-001-0016 | (805) 256-0039 | A | 3 | 5.0 | 1.7 | 188 | 386.0 | 2 |
| 6 | VE-001-0017 | (805) 256-0041 | A | 7 | 8.0 | 1.1 | 181 | 389.0 | 2 |
| 7 | VE-001-0022 | (805) 218-0618 | A | 5 | 7.0 | 1.4 | 192 | 403.0 | 2 |
| 8 | VE-001-0023 | (805) 256-0183 | A | 11 | 33.0 | 3.0 | 214 | 472.0 | 2 |
| 9 | VE-001-0026 | (805) 256-0032 | A | 6 | 13.0 | 2.2 | 191 | 400.0 | 2 |
| 10 | VE-001-0027 | (805) 256-0034 | A | 27 | 38.0 | 1.4 | 223 | 475.0 | 2 |
| 11 | VE-001-0034 | (805) 218-0861 | XP | | | | | | |
| 12 | VE-001-0035 | (805) 256-0036 | A | 3 | 4.0 | 1.3 | 207 | 458.0 | 2 |
| 13 | VE-001-0038 | (805) 850-9187 | XP | | | | | | |
| 14 | VE-001-0039 | (805) 218-0648 | A | 1 | 1.0 | 1.0 | 219 | 483.0 | 2 |
| 15 | VE-001-0048 | (805) 850-9159 | A | 10 | 13.0 | 1.3 | 197 | 414.0 | 2 |
| 16 | VE-001-0049 | (805) 256-0914 | A | 9 | 13.0 | 1.4 | 213 | 460.0 | 2 |
| 17 | VE-001-0056 | (805) 850-9218 | A | 6 | 10.0 | 1.7 | 202 | 429.0 | 2 |
| 18 | VE-001-0057 | (805) 256-0853 | A | 3 | 22.0 | 7.3 | 217 | 456.0 | 2 |
| 19 | VE-001-0062 | (805) 850-9203 | XP | | | | | | |
| 20 | VE-001-0063 | (805) 256-0435 | A | 26 | 47.0 | 1.8 | 206 | 444.0 | 2 |
| 21 | VE-001-0066 | (805) 850-9232 | XP | | | | | | |
| 22 | VE-001-0067 | (805) 850-9207 | A | 12 | 90.0 | 7.5 | 186 | 381.0 | 2 |
| 23 | VE-001-0072 | (805) 256-5246 | XP | | | | | | |
| 24 | VE-001-0073 | (805) 256-0954 | A | 8 | 33.0 | 4.1 | 189 | 397.0 | 2 |
| 25 | VE-001-0076 | (805) 850-9233 | XP | | | | | | |
| 26 | VE-001-0077 | (805) 665-8525 | A | 27 | 50.0 | 1.9 | 210 | 454.0 | 2 |
| 27 | VE-001-0082 | (805) 850-9148 | XP | | | | | | |
| 28 | VE-001-0083 | (805) 256-0587 | A | 11 | 24.0 | 2.2 | 208 | 447.0 | 2 |
| 29 | VE-001-0087 | (805) 256-0045 | A | 6 | 20.0 | 3.3 | 228 | 505.0 | 2 |
| 30 | VE-001-0092 | (805) 850-9135 | XP | | | | | | |
| 31 | VE-001-0093 | (805) 256-0546 | XP | | | | 13 | 24.0 | 2 |
| 32 | VE-001-0096 | (805) 218-0370 | XP | | | | | | |
| 33 | VE-001-0097 | (805) 256-0529 | A | 3 | 7.0 | 2.3 | 210 | 451.0 | 2 |
| 34 | VE-001-0102 | (805) 256-0873 | A | | | | 216 | 468.0 | 2 |
| 35 | VE-001-0103 | (805) 256-0832 | A | 3 | 9.0 | 3.0 | 182 | 370.0 | 2 |
| 36 | VE-001-0106 | (805) 256-0889 | A | 1 | 1.0 | 1.0 | 206 | 442.0 | 2 |
| 37 | VE-001-0107 | (805) 256-0044 | A | 2 | 2.0 | 1.0 | 213 | 463.0 | 2 |
| 38 | VE-001-0112 | (805) 256-0237 | A | 1 | 5.0 | 5.0 | 204 | 436.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 39 | VE-001-0113 | (805) 256-0831 | A | 3 | 8.0 | 2.7 | 202 | 431.0 | 2 |
| 40 | VE-001-0116 | (805) 665-7850 | A | 1 | 1.0 | 1.0 | 207 | 442.0 | 2 |
| 41 | VE-001-0117 | (805) 218-2695 | A | 2 | 3.0 | 1.5 | 184 | 378.0 | 2 |
| 42 | VE-001-0122 | (805) 256-0957 | A | 2 | 7.0 | 3.5 | 203 | 427.0 | 2 |
| 43 | VE-001-0123 | (805) 256-0185 | A | 2 | 4.0 | 2.0 | 197 | 415.0 | 2 |
| 44 | VE-001-0126 | (805) 256-0878 | A | 4 | 11.0 | 2.8 | 202 | 414.0 | 2 |
| 45 | VE-001-0127 | (805) 218-3843 | A | 3 | 8.0 | 2.7 | 205 | 439.0 | 2 |
| 46 | VE-001-0132 | (805) 256-0293 | A | 2 | 3.0 | 1.5 | 204 | 437.0 | 2 |
| 47 | VE-001-0133 | (805) 320-8342 | A | 2 | 3.0 | 1.5 | 208 | 437.0 | 2 |
| 48 | VE-001-0136 | (805) 256-0395 | A | | | | 200 | 421.0 | 2 |
| 49 | VE-001-0137 | (805) 256-0726 | A | 6 | 8.0 | 1.3 | 202 | 414.0 | 2 |
| 50 | VE-001-0142 | (805) 256-0320 | A | 1 | 1.0 | 1.0 | 201 | 429.0 | 2 |
| 51 | VE-001-0143 | (805) 256-0640 | A | 2 | 6.0 | 3.0 | 205 | 425.0 | 2 |
| 52 | VE-001-0146 | (805) 256-0180 | A | 1 | 1.0 | 1.0 | 195 | 407.0 | 2 |
| 53 | VE-001-0147 | (805) 256-0296 | A | | | | 203 | 431.0 | 2 |
| 54 | VE-001-0152 | (805) 256-0047 | XP | | | | | | |
| 55 | VE-001-0153 | (805) 218-4052 | XP | | | | | | |
| 56 | VE-001-0156 | (805) 320-8348 | XP | | | | | | |
| 57 | VE-001-0157 | (805) 218-4549 | XP | | | | | | |
| 58 | VE-001-0162 | (805) 850-5597 | XP | | | | | | |
| 59 | VE-001-0163 | (805) 256-4247 | XP | | | | | | |
| 60 | VE-023-0032 | (805) 850-9460 | A | 1 | 2.0 | 2.0 | 202 | 426.0 | 2 |
| 61 | VE-023-0036 | (805) 320-4314 | A | 1 | 1.0 | 1.0 | 219 | 481.0 | 2 |
| 62 | VE-023-0037 | (805) 850-9518 | A | | | | 200 | 425.0 | 2 |
| 63 | VE-023-0042 | (805) 850-9448 | A | 2 | 6.0 | 3.0 | 204 | 415.0 | 2 |
| 64 | VE-023-0043 | (805) 256-0586 | A | | | | 203 | 433.0 | 2 |
| 65 | VE-023-0046 | (805) 850-9459 | A | 2 | 6.0 | 3.0 | 192 | 399.0 | 2 |
| 66 | VE-023-0047 | (805) 256-0699 | A | | | | 201 | 417.0 | 2 |
| 67 | VE-023-0052 | (805) 850-9410 | A | | | | 196 | 411.0 | 2 |
| 68 | VE-023-0053 | (805) 850-9476 | A | 2 | 7.0 | 3.5 | 212 | 455.0 | 2 |
| 69 | VE-023-0056 | (805) 320-4095 | A | | | | 194 | 409.0 | 2 |
| 70 | VE-023-0057 | (805) 320-3995 | A | | | | 198 | 406.0 | 2 |
| 71 | VE-023-0062 | (805) 320-3975 | XT | 1 | 1.0 | 1.0 | 180 | 370.0 | 2 |
| 72 | VE-023-0063 | (805) 256-0172 | A | | | | 210 | 454.0 | 2 |
| 73 | VE-023-0066 | (805) 320-4307 | A | | | | 200 | 412.0 | 2 |
| 74 | VE-023-0067 | (805) 850-9488 | A | 1 | 4.0 | 4.0 | 192 | 403.0 | 2 |
| 75 | VE-023-0072 | (805) 477-8451 | A | 2 | 2.0 | 1.0 | 203 | 419.0 | 2 |
| 76 | VE-023-0073 | (805) 850-9662 | A | 1 | 1.0 | 1.0 | 201 | 429.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 77 | VE-023-0076 | (805) 218-0799 | A | | | | 194 | 405.0 | 2 |
| 78 | VE-023-0077 | (805) 850-9483 | A | 3 | 4.0 | 1.3 | 199 | 421.0 | 2 |
| 79 | VE-023-0082 | (805) 218-0803 | A | | | | 191 | 396.0 | 2 |
| 80 | VE-023-0083 | (805) 218-0671 | A | | | | 207 | 444.0 | 2 |
| 81 | VE-023-0086 | (805) 218-0816 | A | | | | 204 | 430.0 | 2 |
| 82 | VE-023-0087 | (805) 850-9546 | A | | | | 198 | 418.0 | 2 |
| 83 | VE-023-0092 | (805) 850-9871 | A | 1 | 1.0 | 1.0 | 189 | 391.0 | 2 |
| 84 | VE-023-0093 | (805) 850-9440 | A | 1 | 1.0 | 1.0 | 209 | 453.0 | 2 |
| 85 | VE-023-0096 | (805) 850-9402 | A | | | | 187 | 385.0 | 2 |
| 86 | VE-023-0097 | (805) 850-9421 | A | 1 | 2.0 | 2.0 | 181 | 383.0 | 2 |
| 87 | VE-023-0102 | (805) 218-0847 | A | | | | 193 | 406.0 | 2 |
| 88 | VE-023-0103 | (805) 850-9525 | A | 2 | 7.0 | 3.5 | 201 | 428.0 | 2 |
| 89 | VE-023-0106 | (805) 218-0819 | A | | | | 195 | 410.0 | 2 |
| 90 | VE-023-0107 | (805) 850-9541 | A | | | | 192 | 395.0 | 2 |
| 91 | VE-023-0112 | (805) 850-9683 | A | | | | 199 | 420.0 | 2 |
| 92 | VE-023-0113 | (805) 850-9396 | A | | | | 197 | 415.0 | 2 |
| 93 | VE-023-0116 | (805) 850-9764 | A | 1 | 4.0 | 4.0 | 208 | 435.0 | 2 |
| 94 | VE-023-0117 | (805) 850-9517 | A | 2 | 2.0 | 1.0 | 193 | 403.0 | 2 |
| 95 | VE-023-0153 | (805) 850-9422 | A | 3 | 5.0 | 1.7 | 209 | 423.0 | 2 |
| 96 | VE-023-0165 | (805) 850-9526 | A | | | | 204 | 424.0 | 2 |
| 97 | VE-023-0175 | (805) 850-9597 | A | 2 | 2.0 | 1.0 | 320 | 659.0 | 2 |
| 98 | VE-023-0186 | (805) 850-9573 | A | 1 | 2.0 | 2.0 | 202 | 431.0 | 2 |
| 99 | VE-023-0196 | (805) 218-8453 | A | 8 | 23.0 | 2.9 | 195 | 409.0 | 2 |
| 100 | VE-023-0209 | (805) 256-0179 | A | 2 | 4.0 | 2.0 | 207 | 445.0 | 2 |
| 101 | VE-023-0219 | (805) 850-9640 | A | 2 | 2.0 | 1.0 | 226 | 506.0 | 2 |
| 102 | VE-023-0233 | (805) 320-4218 | A | 1 | 1.0 | 1.0 | 206 | 438.0 | 2 |
| 103 | VE-033-0002 | (805) 320-8276 | A | 3 | 9.0 | 3.0 | 220 | 463.0 | 2 |
| 104 | VE-033-0003 | (805) 320-8277 | A | | | | 186 | 382.0 | 2 |
| 105 | VE-033-0012 | (805) 320-8264 | A | 3 | 3.0 | 1.0 | 202 | 429.0 | 2 |
| 106 | VE-033-0013 | (805) 320-8331 | A | | | | 210 | 456.0 | 2 |
| 107 | VE-033-0016 | (805) 320-8317 | A | 1 | 1.0 | 1.0 | 193 | 403.0 | 2 |
| 108 | VE-033-0017 | (805) 320-8234 | A | 4 | 14.0 | 3.5 | 204 | 435.0 | 2 |
| 109 | VE-033-0022 | (805) 320-8313 | A | 2 | 2.0 | 1.0 | 193 | 403.0 | 2 |
| 110 | VE-033-0023 | (805) 320-8233 | A | 2 | 2.0 | 1.0 | 236 | 471.0 | 2 |
| 111 | VE-033-0026 | (805) 320-8306 | A | 1 | 1.0 | 1.0 | 205 | 436.0 | 2 |
| 112 | VE-033-0027 | (805) 320-8225 | A | 1 | 3.0 | 3.0 | 200 | 424.0 | 2 |
| 113 | VE-033-0032 | (805) 320-8295 | A | 1 | 1.0 | 1.0 | 203 | 430.0 | 2 |
| 114 | VE-033-0033 | (805) 320-8219 | A | | | | 217 | 471.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 115 | VE-033-0036 | (805) 320-8329 | A | | | | 189 | 390.0 | 2 |
| 116 | VE-033-0037 | (805) 320-8215 | A | | | | 208 | 435.0 | 2 |
| 117 | VE-033-0042 | (805) 320-8286 | A | 1 | 3.0 | 3.0 | 188 | 384.0 | 2 |
| 118 | VE-033-0043 | (805) 320-8214 | A | 2 | 2.0 | 1.0 | 203 | 435.0 | 2 |
| 119 | VE-033-0046 | (805) 320-8327 | A | 4 | 5.0 | 1.3 | 196 | 410.0 | 2 |
| 120 | VE-033-0047 | (805) 320-8213 | A | 2 | 5.0 | 2.5 | 214 | 458.0 | 2 |
| 121 | VE-033-0052 | (805) 320-8322 | A | | | | 221 | 464.0 | 2 |
| 122 | VE-033-0053 | (805) 320-8204 | A | 8 | 18.0 | 2.3 | 227 | 494.0 | 2 |
| 123 | VE-033-0056 | (805) 320-8319 | A | 3 | 9.0 | 3.0 | 204 | 432.0 | 2 |
| 124 | VE-033-0057 | (805) 320-8232 | A | | | | 203 | 434.0 | 2 |
| 125 | VE-033-0062 | (805) 320-8318 | A | 2 | 2.0 | 1.0 | 195 | 409.0 | 2 |
| 126 | VE-033-0063 | (805) 320-8230 | A | 1 | 2.0 | 2.0 | 200 | 421.0 | 2 |
| 127 | VE-034-0086 | (805) 218-8448 | A | 2 | 6.0 | 3.0 | 203 | 431.0 | 2 |
| 128 | VE-034-0102 | (805) 256-0176 | A | 1 | 1.0 | 1.0 | 192 | 400.0 | 2 |
| 129 | VE-034-0105 | (805) 218-0427 | A | 1 | 3.0 | 3.0 | 206 | 442.0 | 2 |
| 130 | VE-101-0004 | (805) 256-0329 | XP | | | | | | |
| 131 | VE-101-0005 | (805) 320-6298 | XP | | | | | | |
| 132 | VE-101-0006 | (805) 850-9685 | A | 1 | 4.0 | 4.0 | 197 | 416.0 | 2 |
| 133 | VE-101-0007 | (805) 701-5087 | A | 2 | 2.0 | 1.0 | 220 | 486.0 | 2 |
| 134 | VE-101-0008 | (805) 850-9927 | XP | | | | | | |
| 135 | VE-101-0009 | (805) 320-6398 | XP | | | | | | |
| 136 | VE-101-0012 | (805) 256-0322 | XP | | | | | | |
| 137 | VE-101-0013 | (805) 320-6788 | XP | | | | | | |
| 138 | VE-101-0014 | (805) 256-0323 | XP | | | | | | |
| 139 | VE-101-0015 | (805) 320-8363 | XP | | | | | | |
| 140 | VE-101-0016 | (805) 218-0945 | A | | | | 221 | 486.0 | 2 |
| 141 | VE-101-0017 | (805) 340-4684 | A | 1 | 1.0 | 1.0 | 225 | 482.0 | 2 |
| 142 | VE-101-0018 | (805) 256-0687 | XP | | | | | | |
| 143 | VE-101-0019 | (805) 320-8419 | XP | | | | | | |
| 144 | VE-101-0022 | (805) 850-9913 | XP | | | | | | |
| 145 | VE-101-0023 | (805) 256-0301 | XP | | | | | | |
| 146 | VE-101-0024 | (805) 218-0783 | XP | | | | | | |
| 147 | VE-101-0025 | (805) 320-8395 | XP | | | | | | |
| 148 | VE-101-0027 | (805) 320-8382 | XP | | | | | | |
| 149 | VE-101-0028 | (805) 218-6248 | A | 1 | 1.0 | 1.0 | 210 | 454.0 | 2 |
| 150 | VE-101-0029 | (805) 320-8367 | A | 4 | 15.0 | 3.8 | 199 | 419.0 | 2 |
| 151 | VE-101-0032 | (805) 665-7810 | XP | | | | | | |
| 152 | VE-101-0033 | (805) 320-8354 | XP | | | | | | |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 153 | VE-101-0034 | (805) 850-9703 | XP | | | | | | |
| 154 | VE-101-0035 | (805) 320-8349 | XP | | | | | | |
| 155 | VE-101-0036 | (805) 218-0513 | A | 1 | 1.0 | 1.0 | 204 | 436.0 | 2 |
| 156 | VE-101-0037 | (805) 320-6158 | A | 5 | 9.0 | 1.8 | 210 | 444.0 | 2 |
| 157 | VE-101-0038 | (805) 218-0856 | XP | | | | | | |
| 158 | VE-101-0039 | (805) 850-5464 | XP | | | | | | |
| 159 | VE-101-0042 | (805) 256-5069 | XP | | | | | | |
| 160 | VE-101-0043 | (805) 320-5123 | XP | | | | | | |
| 161 | VE-101-0044 | (805) 218-0853 | XP | | | | | | |
| 162 | VE-101-0045 | (805) 320-6880 | XP | | | | | | |
| 163 | VE-101-0046 | (805) 218-0860 | A | 1 | 3.0 | 3.0 | 216 | 473.0 | 2 |
| 164 | VE-101-0047 | (805) 256-0264 | A | | | | 212 | 446.0 | 2 |
| 165 | VE-101-0048 | (805) 850-9704 | XP | | | | | | |
| 166 | VE-101-0049 | (805) 256-0238 | XP | | | | | | |
| 167 | VE-101-0052 | (805) 665-8981 | XP | | | | | | |
| 168 | VE-101-0053 | (805) 256-0793 | XP | | | | | | |
| 169 | VE-101-0054 | (805) 850-9375 | XP | | | | | | |
| 170 | VE-101-0055 | (805) 218-1547 | XP | | | | | | |
| 171 | VE-101-0056 | (805) 850-9878 | A | | | | 212 | 460.0 | 2 |
| 172 | VE-101-0057 | (805) 256-0657 | A | 3 | 3.0 | 1.0 | 212 | 450.0 | 2 |
| 173 | VE-101-0058 | (805) 850-9664 | XP | | | | | | |
| 174 | VE-101-0059 | (805) 256-0151 | XP | | | | | | |
| 175 | VE-101-0062 | (805) 665-8932 | XP | | | | | | |
| 176 | VE-101-0063 | (805) 320-3112 | XP | | | | | | |
| 177 | VE-101-0064 | (805) 665-8983 | XP | | | | | | |
| 178 | VE-101-0065 | (805) 256-0500 | XP | | | | | | |
| 179 | VE-101-0066 | (805) 850-9584 | A | 1 | 12.0 | 12.0 | 219 | 475.0 | 2 |
| 180 | VE-101-0067 | (805) 256-0203 | A | 3 | 8.0 | 2.7 | 212 | 457.0 | 2 |
| 181 | VE-101-0068 | (805) 218-0786 | XP | | | | | | |
| 182 | VE-101-0069 | (805) 256-0204 | XP | | | | | | |
| 183 | VE-101-0072 | (805) 850-9675 | XP | | | | | | |
| 184 | VE-101-0073 | (805) 256-0158 | XP | | | | | | |
| 185 | VE-101-0074 | (805) 850-9472 | XP | | | | | | |
| 186 | VE-101-0075 | (805) 256-0154 | XP | | | | | | |
| 187 | VE-101-0076 | (805) 701-5657 | A | 2 | 23.0 | 11.5 | 212 | 457.0 | 2 |
| 188 | VE-101-0077 | (805) 701-3091 | A | 3 | 6.0 | 2.0 | 216 | 468.0 | 2 |
| 189 | VE-101-0078 | (805) 850-8265 | A | 2 | 5.0 | 2.5 | 222 | 485.0 | 2 |
| 190 | VE-101-0079 | (805) 218-8316 | A | | | | 196 | 412.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 191 | VE-101-0082 | (805) 256-0311 | A | 5 | 13.0 | 2.6 | 220 | 486.0 | 2 |
| 192 | VE-101-0083 | (805) 218-0824 | A | 1 | 8.0 | 8.0 | 207 | 442.0 | 2 |
| 193 | VE-101-0084 | (805) 256-4764 | A | 2 | 5.0 | 2.5 | 220 | 485.0 | 2 |
| 194 | VE-101-0085 | (805) 256-0206 | A | | | | 213 | 456.0 | 2 |
| 195 | VE-101-0086 | (805) 665-8676 | A | 8 | 8.0 | 1.0 | 205 | 446.0 | 2 |
| 196 | VE-101-0087 | (805) 320-7391 | A | 3 | 6.0 | 2.0 | 212 | 453.0 | 2 |
| 197 | VE-101-0094 | (805) 850-5419 | A | 1 | 1.0 | 1.0 | 213 | 467.0 | 2 |
| 198 | VE-101-0095 | (805) 256-0659 | A | 9 | 12.0 | 1.3 | 205 | 441.0 | 2 |
| 199 | VE-101-0096 | (805) 665-8674 | A | 1 | 7.0 | 7.0 | 208 | 449.0 | 2 |
| 200 | VE-101-0097 | (805) 256-0170 | A | 11 | 33.0 | 3.0 | 208 | 444.0 | 2 |
| 201 | VE-101-0098 | (805) 256-0312 | A | 8 | 8.0 | 1.0 | 373 | 930.0 | 2 |
| 202 | VE-101-0099 | (805) 320-7405 | A | 5 | 10.0 | 2.0 | 206 | 435.0 | 2 |
| 203 | VE-101-0102 | (805) 256-0317 | A | | | | 203 | 437.0 | 2 |
| 204 | VE-101-0103 | (805) 320-7423 | A | 3 | 5.0 | 1.7 | 198 | 415.0 | 2 |
| 205 | VE-101-0106 | (805) 850-5369 | A | 2 | 3.0 | 1.5 | 207 | 448.0 | 2 |
| 206 | VE-101-0107 | (805) 320-7830 | A | 3 | 13.0 | 4.3 | 192 | 398.0 | 2 |
| 207 | VE-101-0108 | (805) 850-9726 | A | 1 | 1.0 | 1.0 | 214 | 465.0 | 2 |
| 208 | VE-101-0109 | (805) 320-7853 | A | 1 | 1.0 | 1.0 | 204 | 434.0 | 2 |
| 209 | VE-101-0112 | (805) 256-4255 | XP | | | | | | |
| 210 | VE-101-0113 | (805) 320-7792 | XP | | | | | | |
| 211 | VE-101-0116 | (805) 850-9956 | A | 3 | 10.0 | 3.3 | 210 | 454.0 | 2 |
| 212 | VE-101-0117 | (805) 850-5067 | A | 4 | 11.0 | 2.8 | 218 | 469.0 | 2 |
| 213 | VE-101-0122 | (805) 256-0169 | XP | | | | | | |
| 214 | VE-101-0123 | (805) 256-0199 | XP | | | | | | |
| 215 | VE-101-0126 | (805) 256-0181 | A | | | | 218 | 472.0 | 2 |
| 216 | VE-101-0127 | (805) 256-0243 | A | 2 | 5.0 | 2.5 | 206 | 439.0 | 2 |
| 217 | VE-101-0132 | (805) 665-8926 | XP | | | | | | |
| 218 | VE-101-0133 | (805) 256-0164 | XP | | | | | | |
| 219 | VE-101-0136 | (805) 320-3103 | A | | | | 215 | 468.0 | 2 |
| 220 | VE-101-0137 | (805) 256-0150 | A | | | | 219 | 474.0 | 2 |
| 221 | VE-101-0142 | (805) 850-9213 | XP | | | | | | |
| 222 | VE-101-0143 | (805) 320-7373 | XP | | | | | | |
| 223 | VE-101-0146 | (805) 218-3127 | A | 3 | 5.0 | 1.7 | 225 | 492.0 | 2 |
| 224 | VE-101-0147 | (805) 320-7786 | A | | | | 214 | 464.0 | 2 |
| 225 | VE-101-0152 | (805) 850-9087 | XP | | | | | | |
| 226 | VE-101-0153 | (805) 320-7139 | XP | | | | | | |
| 227 | VE-101-0156 | (805) 256-0063 | A | 3 | 6.0 | 2.0 | 229 | 502.0 | 2 |
| 228 | VE-101-0157 | (805) 320-7135 | A | 3 | 11.0 | 3.7 | 210 | 454.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 229 | VE-101-0162 | (805) 320-5282 | XP | | | | | | |
| 230 | VE-101-0163 | (805) 320-7408 | XP | | | | | | |
| 231 | VE-101-0166 | (805) 256-8323 | A | 1 | 2.0 | 2.0 | 233 | 517.0 | 2 |
| 232 | VE-101-0167 | (805) 561-8824 | A | 1 | 1.0 | 1.0 | 219 | 473.0 | 2 |
| 233 | VE-101-0172 | (805) 320-4816 | XP | | | | | | |
| 234 | VE-101-0173 | | XP | | | | | | |
| 235 | VE-101-0176 | (805) 256-0207 | A | | | | 230 | 515.0 | 2 |
| 236 | VE-101-0177 | (805) 256-0200 | A | | | | 210 | 456.0 | 2 |
| 237 | VE-101-0182 | (805) 256-0138 | XP | | | | | | |
| 238 | VE-101-0183 | (805) 256-0983 | XP | | | | | | |
| 239 | VE-101-0186 | (805) 320-5895 | A | 4 | 7.0 | 1.8 | 215 | 460.0 | 2 |
| 240 | VE-101-0187 | (805) 256-0213 | A | 6 | 18.0 | 3.0 | 214 | 461.0 | 2 |
| 241 | VE-101-0192 | (805) 850-8249 | XP | | | | | | |
| 242 | VE-101-0193 | (805) 256-0217 | XP | | | | | | |
| 243 | VE-101-0196 | (805) 320-8596 | A | | | | 236 | 510.0 | 2 |
| 244 | VE-101-0197 | (805) 561-9091 | A | 2 | 14.0 | 7.0 | 225 | 491.0 | 2 |
| 245 | VE-101-0202 | (805) 850-9333 | XP | | | | | | |
| 246 | VE-101-0203 | (805) 256-0210 | XP | | | | | | |
| 247 | VE-101-0206 | (805) 561-9092 | A | 3 | 4.0 | 1.3 | 231 | 516.0 | 2 |
| 248 | VE-101-0207 | (805) 218-4922 | A | 1 | 2.0 | 2.0 | 220 | 480.0 | 2 |
| 249 | VE-101-0212 | (805) 320-4282 | XP | | | | | | |
| 250 | VE-101-0213 | (805) 256-4414 | XP | | | | | | |
| 251 | VE-101-0216 | (805) 256-0155 | A | 1 | 1.0 | 1.0 | 209 | 450.0 | 2 |
| 252 | VE-101-0217 | (805) 850-8145 | A | 4 | 16.0 | 4.0 | 223 | 476.0 | 2 |
| 253 | VE-101-0222 | (805) 256-0913 | XP | | | | | | |
| 254 | VE-101-0223 | (805) 850-9078 | XP | | | | | | |
| 255 | VE-101-0226 | (805) 320-4256 | A | 2 | 3.0 | 1.5 | 226 | 498.0 | 2 |
| 256 | VE-101-0227 | (805) 850-9789 | A | 1 | 3.0 | 3.0 | 228 | 495.0 | 2 |
| 257 | VE-101-0236 | (805) 850-9513 | A | 4 | 9.0 | 2.3 | 210 | 451.0 | 2 |
| 258 | VE-101-0237 | (805) 320-4272 | A | 7 | 22.0 | 3.1 | 207 | 440.0 | 2 |
| 259 | VE-101-0242 | (805) 320-7897 | XP | | | | | | |
| 260 | VE-101-0243 | (805) 320-8130 | XP | | | | | | |
| 261 | VE-101-0246 | (805) 218-9511 | A | 6 | 18.0 | 3.0 | 217 | 475.0 | 2 |
| 262 | VE-101-0247 | (805) 320-8123 | A | 3 | 5.0 | 1.7 | 221 | 463.0 | 2 |
| 263 | VE-101-0252 | (805) 850-8662 | XP | | | | | | |
| 264 | VE-101-0253 | (805) 320-8142 | XP | | | | | | |
| 265 | VE-101-0256 | (805) 665-8436 | A | 7 | 13.0 | 1.9 | 234 | 515.0 | 2 |
| 266 | VE-101-0257 | (805) 320-8126 | A | 1 | 2.0 | 2.0 | 214 | 454.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 267 | VE-101-0262 | (805) 320-7869 | XP | | | | | | |
| 268 | VE-101-0263 | (805) 320-8271 | XP | | | | | | |
| 269 | VE-101-0266 | (805) 320-7883 | A | 2 | 3.0 | 1.5 | 229 | 508.0 | 2 |
| 270 | VE-101-0267 | (805) 320-8031 | A | 4 | 6.0 | 1.5 | 216 | 471.0 | 2 |
| 271 | VE-101-0272 | (805) 320-7864 | XP | | | | | | |
| 272 | VE-101-0273 | (805) 256-0340 | XP | | | | | | |
| 273 | VE-101-0276 | (805) 320-7867 | A | 4 | 12.0 | 3.0 | 231 | 510.0 | 2 |
| 274 | VE-101-0277 | (805) 320-8120 | A | 5 | 13.0 | 2.6 | 219 | 471.0 | 2 |
| 275 | VE-101-0282 | (805) 320-8171 | XP | | | | | | |
| 276 | VE-101-0283 | (805) 256-0593 | XP | | | | | | |
| 277 | VE-101-0286 | (805) 256-0188 | A | 1 | 2.0 | 2.0 | 235 | 523.0 | 2 |
| 278 | VE-101-0287 | (805) 256-4536 | A | 1 | 1.0 | 1.0 | 211 | 441.0 | 2 |
| 279 | VE-101-0292 | (805) 320-7958 | XP | | | | | | |
| 280 | VE-101-0293 | (805) 320-8075 | XP | | | | | | |
| 281 | VE-101-0296 | (805) 320-7928 | A | 3 | 7.0 | 2.3 | 216 | 474.0 | 2 |
| 282 | VE-101-0297 | (805) 320-8079 | A | | | | 208 | 445.0 | 2 |
| 283 | VE-101-0302 | (805) 320-7926 | XP | | | | | | |
| 284 | VE-101-0303 | (805) 320-8101 | XP | | | | | | |
| 285 | VE-101-0306 | (805) 320-7913 | A | | | | 227 | 501.0 | 2 |
| 286 | VE-101-0307 | (805) 320-8107 | A | 1 | 3.0 | 3.0 | 204 | 434.0 | 2 |
| 287 | VE-101-0312 | (805) 850-9172 | A | 2 | 5.0 | 2.5 | 207 | 445.0 | 2 |
| 288 | VE-101-0313 | (805) 218-1206 | A | 4 | 15.0 | 3.8 | 196 | 408.0 | 2 |
| 289 | VE-101-0322 | (805) 477-8445 | A | 2 | 9.0 | 4.5 | 209 | 453.0 | 2 |
| 290 | VE-101-0323 | (805) 256-0885 | A | 2 | 4.0 | 2.0 | 191 | 394.0 | 2 |
| 291 | VE-101-0326 | (805) 850-9056 | A | 2 | 10.0 | 5.0 | 161 | 344.0 | 2 |
| 292 | VE-101-0327 | (805) 850-8923 | A | | | | 207 | 442.0 | 2 |
| 293 | VE-101-0332 | (805) 850-5619 | A | 5 | 10.0 | 2.0 | 216 | 470.0 | 2 |
| 294 | VE-101-0333 | (805) 256-0851 | A | 1 | 6.0 | 6.0 | 203 | 430.0 | 2 |
| 295 | VE-101-0336 | (805) 256-5310 | A | 2 | 4.0 | 2.0 | 206 | 443.0 | 2 |
| 296 | VE-101-0337 | (805) 218-4768 | A | 3 | 10.0 | 3.3 | 221 | 462.0 | 2 |
| 297 | VE-101-0342 | (805) 850-8379 | A | 6 | 27.0 | 4.5 | 220 | 481.0 | 2 |
| 298 | VE-101-0343 | (805) 218-9436 | A | | | | 200 | 416.0 | 2 |
| 299 | VE-101-0346 | (805) 256-0920 | A | 4 | 14.0 | 3.5 | 204 | 435.0 | 2 |
| 300 | VE-101-0347 | (805) 218-9408 | A | 3 | 12.0 | 4.0 | 199 | 418.0 | 2 |
| 301 | VE-101-0352 | (805) 256-0922 | A | 2 | 6.0 | 3.0 | 217 | 475.0 | 2 |
| 302 | VE-101-0353 | (805) 218-7607 | A | 2 | 4.0 | 2.0 | 194 | 403.0 | 2 |
| 303 | VE-101-0356 | (805) 256-4188 | A | 8 | 18.0 | 2.3 | 200 | 424.0 | 2 |
| 304 | VE-101-0357 | (805) 218-7159 | A | 1 | 2.0 | 2.0 | 223 | 486.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 305 | VE-101-0362 | (805) 256-0907 | A | 11 | 22.0 | 2.0 | 233 | 508.0 | 2 |
| 306 | VE-101-0363 | (805) 256-0120 | A | 2 | 7.0 | 3.5 | 211 | 451.0 | 2 |
| 307 | VE-101-0366 | (805) 850-8031 | A | 6 | 15.0 | 2.5 | 188 | 388.0 | 2 |
| 308 | VE-101-0367 | (805) 850-9225 | A | 6 | 32.0 | 5.3 | 214 | 450.0 | 2 |
| 309 | VE-101-0372 | (805) 256-0838 | A | 5 | 16.0 | 3.2 | 190 | 400.0 | 2 |
| 310 | VE-101-0373 | (805) 256-0022 | A | 5 | 10.0 | 2.0 | 195 | 402.0 | 2 |
| 311 | VE-101-0376 | (805) 256-0574 | A | 9 | 12.0 | 1.3 | 216 | 471.0 | 2 |
| 312 | VE-101-0377 | (805) 256-0010 | A | 1 | 3.0 | 3.0 | 195 | 407.0 | 2 |
| 313 | VE-101-0382 | (805) 256-0847 | A | 3 | 24.0 | 8.0 | 193 | 404.0 | 2 |
| 314 | VE-101-0383 | (805) 320-8128 | A | 4 | 11.0 | 2.8 | 210 | 453.0 | 2 |
| 315 | VE-101-0386 | (805) 256-0841 | A | 3 | 8.0 | 2.7 | 210 | 453.0 | 2 |
| 316 | VE-101-0387 | (805) 218-7147 | A | 1 | 2.0 | 2.0 | 211 | 453.0 | 2 |
| 317 | VE-101-0392 | (805) 256-0860 | A | 2 | 5.0 | 2.5 | 222 | 489.0 | 2 |
| 318 | VE-101-0393 | (805) 256-0890 | A | 3 | 18.0 | 6.0 | 200 | 416.0 | 2 |
| 319 | VE-101-0396 | (805) 256-0862 | A | 1 | 1.0 | 1.0 | 207 | 434.0 | 2 |
| 320 | VE-101-0397 | (805) 256-0891 | A | 3 | 8.0 | 2.7 | 205 | 438.0 | 2 |
| 321 | VE-101-0402 | (805) 256-0886 | A | | | | 219 | 467.0 | 2 |
| 322 | VE-101-0403 | (805) 256-4271 | A | 3 | 11.0 | 3.7 | 212 | 451.0 | 2 |
| 323 | VE-101-0403W | (805) 256-8264 | A | 7 | 20.0 | 2.9 | 195 | 406.0 | 2 |
| 324 | VE-101-0406 | (805) 320-8345 | A | 5 | 26.0 | 5.2 | 200 | 421.0 | 2 |
| 325 | VE-101-0407 | (805) 256-0837 | XP | | | | | | |
| 326 | VE-101-0412 | (805) 256-0888 | A | 5 | 60.0 | 12.0 | 207 | 447.0 | 2 |
| 327 | VE-101-0413 | (805) 320-7241 | A | 2 | 11.0 | 5.5 | 206 | 439.0 | 2 |
| 328 | VE-101-0413W | (805) 901-5654 | A | 4 | 11.0 | 2.8 | 201 | 427.0 | 2 |
| 329 | VE-101-0416 | (805) 256-0173 | A | 1 | 1.0 | 1.0 | 195 | 408.0 | 2 |
| 330 | VE-101-0417 | (805) 256-8272 | A | 3 | 6.0 | 2.0 | 199 | 419.0 | 2 |
| 331 | VE-101-0417W | (805) 256-8258 | A | 11 | 46.0 | 4.2 | 210 | 455.0 | 2 |
| 332 | VE-101-0422 | (805) 256-4537 | A | 1 | 3.0 | 3.0 | 214 | 461.0 | 2 |
| 333 | VE-101-0423 | (805) 901-9129 | A | 1 | 2.0 | 2.0 | 198 | 418.0 | 2 |
| 334 | VE-101-0423W | (805) 218-4057 | A | 4 | 5.0 | 1.3 | 202 | 426.0 | 2 |
| 335 | VE-101-0426 | (805) 256-0887 | A | 2 | 11.0 | 5.5 | 216 | 471.0 | 2 |
| 336 | VE-101-0427 | (805) 218-7468 | A | | | | 199 | 418.0 | 2 |
| 337 | VE-101-0427W | (805) 701-8009 | A | 9 | 49.0 | 5.4 | 202 | 428.0 | 2 |
| 338 | VE-101-0432 | (805) 256-0848 | A | 3 | 11.0 | 3.7 | 205 | 438.0 | 2 |
| 339 | VE-101-0433 | (805) 701-4028 | A | 1 | 1.0 | 1.0 | 211 | 460.0 | 2 |
| 340 | VE-101-0433W | (805) 701-3227 | A | 10 | 31.0 | 3.1 | 208 | 445.0 | 2 |
| 341 | VE-118-0002 | (805) 218-0761 | A | 7 | 19.0 | 2.7 | 209 | 434.0 | 2 |
| 342 | VE-118-0003 | (805) 218-0762 | A | 12 | 19.0 | 1.6 | 215 | 464.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 343 | VE-118-0026 | (805) 850-9841 | A | 5 | 19.0 | 3.8 | 196 | 410.0 | 2 |
| 344 | VE-118-0032 | (805) 850-9963 | A | 2 | 5.0 | 2.5 | 209 | 447.0 | 2 |
| 345 | VE-118-0036 | (805) 850-9876 | A | 1 | 3.0 | 3.0 | 188 | 387.0 | 2 |
| 346 | VE-118-0042 | (805) 850-9847 | A | 3 | 7.0 | 2.3 | 216 | 470.0 | 2 |
| 347 | VE-118-0052 | (805) 218-0794 | A | 6 | 18.0 | 3.0 | 200 | 422.0 | 2 |
| 348 | VE-118-0058 | (805) 218-0798 | A | 10 | 27.0 | 2.7 | 205 | 442.0 | 2 |
| 349 | VE-118-0066 | (805) 850-9968 | A | 5 | 19.0 | 3.8 | 202 | 428.0 | 2 |
| 350 | VE-118-0068 | (805) 850-9403 | A | 1 | 4.0 | 4.0 | 209 | 455.0 | 2 |
| 351 | VE-118-0084 | (805) 850-9824 | A | 4 | 10.0 | 2.5 | 196 | 407.0 | 2 |
| 352 | VE-118-0096 | (805) 850-9840 | A | 1 | 6.0 | 6.0 | 219 | 468.0 | 2 |
| 353 | VE-118-0106 | (805) 850-9444 | A | 1 | 5.0 | 5.0 | 189 | 390.0 | 2 |
| 354 | VE-118-0116 | (805) 218-0603 | A | 2 | 2.0 | 1.0 | 209 | 450.0 | 2 |
| 355 | VE-118-0126 | (805) 218-0678 | A | 4 | 5.0 | 1.3 | 209 | 449.0 | 2 |
| 356 | VE-118-0133 | (805) 850-9924 | A | 5 | 28.0 | 5.6 | 221 | 481.0 | 2 |
| 357 | VE-118-0136 | (805) 218-0759 | XP | | | | | | |
| 358 | VE-118-0144 | (805) 850-9967 | A | 4 | 13.0 | 3.3 | 210 | 447.0 | 2 |
| 359 | VE-118-0147 | (805) 850-9936 | A | | | | 242 | 496.0 | 2 |
| 360 | VE-118-0153 | (805) 850-9543 | A | 1 | 1.0 | 1.0 | 229 | 495.0 | 2 |
| 361 | VE-118-0156 | (805) 218-0726 | XP | | | | | | |
| 362 | VE-118-0186 | (805) 850-9938 | A | 1 | 3.0 | 3.0 | 196 | 410.0 | 2 |
| 363 | VE-118-0187 | (805) 256-0334 | A | | | | 224 | 494.0 | 2 |
| 364 | VE-118-0192 | (805) 218-0328 | A | | | | 206 | 439.0 | 2 |
| 365 | VE-118-0193 | (805) 256-0325 | A | 1 | 1.0 | 1.0 | 215 | 471.0 | 2 |
| 366 | VE-118-0196 | (805) 218-0472 | A | | | | 207 | 440.0 | 2 |
| 367 | VE-118-0197 | (805) 256-0324 | A | | | | 216 | 469.0 | 2 |
| 368 | VE-118-0202 | (805) 218-0311 | A | 1 | 4.0 | 4.0 | 224 | 491.0 | 2 |
| 369 | VE-118-0203 | (805) 218-8492 | A | 3 | 5.0 | 1.7 | 216 | 462.0 | 2 |
| 370 | VE-118-0206 | (805) 218-0231 | A | 1 | 1.0 | 1.0 | 214 | 459.0 | 2 |
| 371 | VE-118-0207 | (805) 256-0328 | A | | | | 213 | 461.0 | 2 |
| 372 | VE-118-0212 | (805) 850-9836 | A | 5 | 13.0 | 2.6 | 225 | 484.0 | 2 |
| 373 | VE-118-0213 | (805) 256-0339 | A | 1 | 2.0 | 2.0 | 205 | 436.0 | 2 |
| 374 | VE-118-0216 | (805) 850-9835 | A | 9 | 11.0 | 1.2 | 209 | 442.0 | 2 |
| 375 | VE-118-0217 | (805) 256-0795 | A | 2 | 8.0 | 4.0 | 212 | 458.0 | 2 |
| 376 | VE-118-0222 | (805) 850-9816 | A | 1 | 2.0 | 2.0 | 215 | 451.0 | 2 |
| 377 | VE-118-0223 | (805) 256-0399 | A | | | | 204 | 430.0 | 2 |
| 378 | VE-118-0226 | (805) 850-9766 | A | 3 | 9.0 | 3.0 | 231 | 502.0 | 2 |
| 379 | VE-118-0227 | (805) 256-0386 | A | 4 | 8.0 | 2.0 | 241 | 546.0 | 2 |
| 380 | VE-118-0232 | (805) 850-9589 | XP | | | | | | |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 381 | VE-118-0233 | (805) 256-0602 | XP | | | | | | |
| 382 | VE-118-0236 | (805) 850-9576 | A | | | | 231 | 488.0 | 2 |
| 383 | VE-118-0237 | (805) 256-0604 | A | | | | 234 | 526.0 | 2 |
| 384 | VE-118-0242 | (805) 850-9563 | XP | | | | | | |
| 385 | VE-118-0243 | (805) 256-0669 | XP | | | | | | |
| 386 | VE-118-0246 | (805) 850-9561 | A | | | | 254 | 571.0 | 2 |
| 387 | VE-118-0247 | (805) 256-0297 | A | 2 | 2.0 | 1.0 | 192 | 416.0 | 2 |
| 388 | VE-118-0252 | (805) 218-0417 | XP | | | | | | |
| 389 | VE-118-0253 | (805) 256-0686 | XP | | | | | | |
| 390 | VE-118-0256 | (805) 256-0759 | A | | | | 237 | 527.0 | 2 |
| 391 | VE-118-0257 | (805) 218-5353 | A | 1 | 8.0 | 8.0 | 215 | 465.0 | 2 |
| 392 | VE-118-0262 | (805) 256-0792 | XP | | | | | | |
| 393 | VE-118-0263 | (805) 256-0695 | XP | | | | | | |
| 394 | VE-118-0266 | (805) 256-0757 | A | 2 | 5.0 | 2.5 | 228 | 506.0 | 2 |
| 395 | VE-118-0267 | (805) 256-0187 | A | | | | 226 | 495.0 | 2 |
| 396 | VE-118-0272 | (805) 218-0725 | A | | | | 219 | 478.0 | 2 |
| 397 | VE-118-0273 | (805) 256-0718 | A | 2 | 3.0 | 1.5 | 224 | 473.0 | 2 |
| 398 | VE-118-0276 | (805) 256-0833 | XP | | | | | | |
| 399 | VE-118-0277 | (805) 256-0341 | XP | | | | | | |
| 400 | VE-118-0282 | (805) 256-0807 | A | 1 | 6.0 | 6.0 | 235 | 493.0 | 2 |
| 401 | VE-118-0283 | (805) 320-5767 | A | | | | 212 | 453.0 | 2 |
| 402 | VE-118-0286 | (805) 320-4294 | A | | | | 214 | 465.0 | 2 |
| 403 | VE-118-0287 | (805) 256-0304 | A | 2 | 4.0 | 2.0 | 206 | 442.0 | 2 |
| 404 | ve-118-0292 | (805) 256-0798 | XP | | | | | | |
| 405 | VE-118-0293 | (805) 256-0302 | XP | | | | | | |
| 406 | VE-118-0296 | (805) 256-0806 | A | | | | 210 | 457.0 | 2 |
| 407 | VE-118-0297 | (805) 256-0359 | A | 1 | 2.0 | 2.0 | 198 | 415.0 | 2 |
| 408 | VE-118-0302 | (805) 256-0350 | XP | | | | | | |
| 409 | VE-118-0303 | (805) 256-0348 | XP | | | | | | |
| 410 | VE-118-0306 | (805) 256-0357 | A | 1 | 1.0 | 1.0 | 212 | 458.0 | 2 |
| 411 | VE-118-0307 | (805) 256-0373 | A | 4 | 16.0 | 4.0 | 205 | 437.0 | 2 |
| 412 | VE-118-0312 | (805) 256-0747 | A | 4 | 9.0 | 2.3 | 214 | 467.0 | 2 |
| 413 | VE-118-0313 | (805) 256-0378 | A | 2 | 14.0 | 7.0 | 214 | 459.0 | 2 |
| 414 | VE-118-0316 | (805) 256-0358 | A | 4 | 12.0 | 3.0 | 215 | 466.0 | 2 |
| 415 | VE-118-0317 | (805) 850-9822 | A | | | | 205 | 437.0 | 2 |
| 416 | VE-118-0322 | (805) 256-0802 | A | 5 | 16.0 | 3.2 | 209 | 449.0 | 2 |
| 417 | VE-118-0323 | (805) 256-0595 | A | 1 | 2.0 | 2.0 | 215 | 462.0 | 2 |
| 418 | VE-118-0326 | (805) 256-0719 | A | 4 | 7.0 | 1.8 | 258 | 566.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 419 | VE-118-0327 | (805) 256-0335 | A | 2 | 5.0 | 2.5 | 201 | 428.0 | 2 |
| 420 | VE-126-0002 | (805) 218-8454 | XP | | | | | | |
| 421 | VE-126-0003 | (805) 256-0582 | XP | | | | | | |
| 422 | VE-126-0006 | (805) 218-8460 | XP | | | | | | |
| 423 | VE-126-0007 | (805) 256-0577 | XP | | | | | | |
| 424 | VE-126-0012 | (805) 218-8430 | A | 4 | 12.0 | 3.0 | 252 | 557.0 | 2 |
| 425 | VE-126-0013 | (805) 256-0043 | A | | | | 217 | 471.0 | 2 |
| 426 | VE-126-0016 | (805) 218-8476 | XP | | | | | | |
| 427 | VE-126-0017 | (805) 256-0051 | XP | | | | | | |
| 428 | VE-126-0022 | (805) 256-0029 | A | 2 | 7.0 | 3.5 | 229 | 508.0 | 2 |
| 429 | VE-126-0023 | (805) 256-0052 | A | | | | 209 | 448.0 | 2 |
| 430 | VE-126-0026 | (805) 256-0028 | XP | | | | | | |
| 431 | VE-126-0027 | (805) 256-0049 | XP | | | | | | |
| 432 | VE-126-0032 | (805) 218-2967 | A | | | | 232 | 513.0 | 2 |
| 433 | VE-126-0033 | (805) 218-8528 | A | | | | 201 | 423.0 | 2 |
| 434 | VE-126-0036 | (805) 218-0573 | XP | | | | | | |
| 435 | VE-126-0037 | (805) 256-0033 | XP | | | | | | |
| 436 | VE-126-0042 | (805) 256-4254 | A | 2 | 4.0 | 2.0 | 213 | 457.0 | 2 |
| 437 | VE-126-0043 | (805) 256-0589 | A | | | | 208 | 446.0 | 2 |
| 438 | VE-126-0046 | (805) 850-8014 | XP | | | | | | |
| 439 | VE-126-0047 | (805) 256-0585 | XP | | | | | | |
| 440 | VE-126-0052 | (805) 850-8012 | A | 2 | 2.0 | 1.0 | 232 | 508.0 | 2 |
| 441 | VE-126-0053 | (805) 850-5957 | A | | | | 211 | 455.0 | 2 |
| 442 | VE-126-0056 | (805) 850-5843 | XP | | | | | | |
| 443 | VE-126-0057 | (805) 850-5949 | XP | | | | | | |
| 444 | VE-126-0062 | (805) 850-5936 | A | 2 | 4.0 | 2.0 | 213 | 459.0 | 2 |
| 445 | VE-126-0063 | (805) 256-4253 | A | 3 | 3.0 | 1.0 | 216 | 464.0 | 2 |
| 446 | VE-126-0066 | (805) 850-5892 | XP | | | | | | |
| 447 | VE-126-0067 | (805) 256-4263 | XP | | | | | | |
| 448 | VE-126-0072 | (805) 850-5871 | A | | | | 220 | 482.0 | 2 |
| 449 | VE-126-0073 | (805) 256-4270 | A | | | | 204 | 432.0 | 2 |
| 450 | VE-126-0076 | (805) 850-5877 | XP | | | | | | |
| 451 | VE-126-0077 | (805) 256-0174 | XP | | | | | | |
| 452 | VE-126-0082 | (805) 850-5865 | A | | | | 211 | 453.0 | 2 |
| 453 | VE-126-0083 | (805) 256-4258 | A | | | | 202 | 427.0 | 2 |
| 454 | VE-126-0086 | (805) 850-5860 | XP | | | | | | |
| 455 | VE-126-0087 | (805) 850-5794 | XP | | | | | | |
| 456 | VE-126-0092 | (805) 850-5894 | A | 6 | 13.0 | 2.2 | 218 | 475.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 457 | VE-126-0093 | (805) 850-5796 | A | 8 | 11.0 | 1.4 | 207 | 439.0 | 2 |
| 458 | VE-126-0096 | (805) 850-8043 | XP | | | | | | |
| 459 | VE-126-0097 | (805) 850-5812 | XP | | | | | | |
| 460 | VE-126-0102 | (805) 850-5982 | A | 1 | 1.0 | 1.0 | 208 | 440.0 | 2 |
| 461 | VE-126-0103 | (805) 850-5815 | A | 2 | 8.0 | 4.0 | 207 | 434.0 | 2 |
| 462 | VE-126-0106 | (805) 256-0046 | XP | 4 | 16.0 | 4.0 | 145 | 302.0 | 2 |
| 463 | VE-126-0107 | (805) 850-8042 | XP | | | | | | |
| 464 | VE-126-0112 | (805) 850-8023 | A | 3 | 5.0 | 1.7 | 218 | 477.0 | 2 |
| 465 | VE-126-0113 | (805) 850-5972 | A | 3 | 7.0 | 2.3 | 204 | 431.0 | 2 |
| 466 | VE-126-0116 | (805) 850-5983 | XP | | | | | | |
| 467 | VE-126-0117 | (805) 850-5964 | XP | | | | | | |
| 468 | VE-126-0122 | (805) 850-5937 | A | | | | 208 | 445.0 | 2 |
| 469 | VE-126-0123 | (805) 850-5935 | A | | | | 210 | 450.0 | 2 |
| 470 | VE-126-0126 | (805) 850-5903 | XP | | | | | | |
| 471 | VE-126-0127 | (805) 850-5950 | XP | | | | | | |
| 472 | VE-126-0132 | (805) 850-5872 | A | | | | 217 | 471.0 | 2 |
| 473 | VE-126-0133 | (805) 850-5920 | A | | | | 203 | 429.0 | 2 |
| 474 | VE-126-0136 | (805) 850-5942 | A | 1 | 1.0 | 1.0 | 216 | 468.0 | 2 |
| 475 | VE-126-0137 | (805) 850-5916 | A | | | | 215 | 462.0 | 2 |
| 476 | VE-126-0142 | (805) 256-0588 | A | 3 | 5.0 | 1.7 | 218 | 474.0 | 2 |
| 477 | VE-126-0143 | (805) 218-8442 | A | | | | 203 | 429.0 | 2 |
| 478 | VE-126-0146 | (805) 256-0171 | A | | | | 198 | 414.0 | 2 |
| 479 | VE-126-0147 | (805) 850-5785 | A | 2 | 5.0 | 2.5 | 207 | 440.0 | 2 |
| 480 | VE-126-0152 | (805) 256-0578 | A | 3 | 6.0 | 2.0 | 201 | 425.0 | 2 |
| 481 | VE-126-0153 | (805) 850-5779 | A | 8 | 27.0 | 3.4 | 199 | 417.0 | 2 |
| 482 | VE-126-0156 | (805) 256-0576 | A | 3 | 8.0 | 2.7 | 212 | 454.0 | 2 |
| 483 | VE-126-0157 | (805) 850-5777 | A | 5 | 16.0 | 3.2 | 202 | 424.0 | 2 |
| 484 | VE-126-0162 | (805) 256-0178 | A | | | | 204 | 430.0 | 2 |
| 485 | VE-126-0163 | (805) 850-5788 | A | | | | 199 | 416.0 | 2 |
| 486 | VE-126-0166 | (805) 256-0182 | A | 1 | 2.0 | 2.0 | 201 | 426.0 | 2 |
| 487 | VE-126-0167 | (805) 256-0575 | A | 3 | 5.0 | 1.7 | 210 | 455.0 | 2 |
| 488 | VE-126-0172 | (805) 256-0046 | A | 2 | 3.0 | 1.5 | 27 | 56.0 | 2 |
| 489 | VE-126-0173 | (805) 850-5743 | A | 1 | 4.0 | 4.0 | 209 | 447.0 | 2 |
| 490 | VE-126-0176 | (805) 256-0594 | A | 1 | 1.0 | 1.0 | 198 | 416.0 | 2 |
| 491 | VE-126-0177 | (805) 850-5752 | A | | | | 205 | 438.0 | 2 |
| 492 | VE-126-0178 | (805) 256-0592 | A | 1 | 4.0 | 4.0 | 208 | 438.0 | 2 |
| 493 | VE-126-0179 | (805) 850-5767 | A | 4 | 12.0 | 3.0 | 212 | 464.0 | 2 |
| 494 | VE-126-0186 | (805) 256-0591 | A | | | | 216 | 469.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 495 | VE-126-0187 | (805) 850-5825 | A | | | | 202 | 429.0 | 2 |
| 496 | VE-126-0192 | (805) 850-8041 | A | 1 | 1.0 | 1.0 | 230 | 508.0 | 2 |
| 497 | VE-126-0193 | (805) 850-5859 | A | 1 | 3.0 | 3.0 | 217 | 473.0 | 2 |
| 498 | VE-126-0196 | (805) 850-5893 | A | | | | 221 | 484.0 | 2 |
| 499 | VE-126-0197 | (805) 850-5698 | A | 4 | 19.0 | 4.8 | 216 | 457.0 | 2 |
| 500 | VE-126-0226 | (805) 850-5728 | A | 3 | 3.0 | 1.0 | 235 | 491.0 | 2 |
| 501 | VE-126-0227 | (805) 850-9478 | A | 4 | 9.0 | 2.3 | 218 | 471.0 | 2 |
| 502 | VE-126-0232 | (805) 850-5716 | A | 2 | 10.0 | 5.0 | 205 | 436.0 | 2 |
| 503 | VE-126-0233 | (805) 850-9521 | A | | | | 202 | 430.0 | 2 |
| 504 | VE-126-0236 | (805) 850-5850 | A | 1 | 4.0 | 4.0 | 200 | 422.0 | 2 |
| 505 | VE-126-0237 | (805) 850-9531 | A | | | | 209 | 451.0 | 2 |
| 506 | VE-126-0242 | (805) 850-5847 | A | 1 | 3.0 | 3.0 | 203 | 427.0 | 2 |
| 507 | VE-126-0243 | (805) 850-9439 | A | 1 | 2.0 | 2.0 | 226 | 488.0 | 2 |
| 508 | VE-126-0246 | (805) 850-8034 | A | 1 | 9.0 | 9.0 | 203 | 426.0 | 2 |
| 509 | VE-126-0247 | (805) 850-9395 | A | 1 | 6.0 | 6.0 | 201 | 427.0 | 2 |
| 510 | VE-126-0252 | (805) 850-5846 | A | 1 | 1.0 | 1.0 | 192 | 400.0 | 2 |
| 511 | VE-126-0253 | (805) 850-9414 | A | | | | 199 | 420.0 | 2 |
| 512 | VE-126-0256 | (805) 256-0581 | A | 3 | 4.0 | 1.3 | 209 | 430.0 | 2 |
| 513 | VE-126-0257 | (805) 850-9532 | A | | | | 204 | 434.0 | 2 |
| 514 | VE-126-0262 | (805) 256-0583 | A | | | | 201 | 419.0 | 2 |
| 515 | VE-126-0263 | (805) 850-9475 | A | 1 | 1.0 | 1.0 | 199 | 414.0 | 2 |
| 516 | VE-126-0266 | (805) 320-4110 | A | | | | 205 | 437.0 | 2 |
| 517 | VE-126-0267 | (805) 320-4270 | A | 3 | 4.0 | 1.3 | 206 | 436.0 | 2 |
| 518 | VE-126-0272 | (805) 850-9246 | A | | | | 200 | 422.0 | 2 |
| 519 | VE-126-0273 | (805) 850-9479 | A | | | | 206 | 437.0 | 2 |
| 520 | VE-126-0276 | (805) 850-9438 | A | 3 | 3.0 | 1.0 | 282 | 566.0 | 2 |
| 521 | VE-126-0277 | (805) 850-9467 | A | | | | 215 | 468.0 | 2 |
| 522 | VE-126-0282 | (805) 850-9382 | A | | | | 225 | 495.0 | 2 |
| 523 | VE-126-0283 | (805) 850-9486 | A | 5 | 18.0 | 3.6 | 174 | 367.0 | 2 |
| 524 | VE-126-0286 | (805) 850-9386 | A | 2 | 3.0 | 1.5 | 223 | 480.0 | 2 |
| 525 | VE-126-0287 | (805) 850-9413 | A | | | | 204 | 436.0 | 2 |
| 526 | VE-126-0292 | (805) 850-9127 | A | | | | 211 | 456.0 | 2 |
| 527 | VE-126-0293 | (805) 256-4229 | A | | | | 225 | 493.0 | 2 |
| 528 | VE-126-0296 | (805) 850-9433 | A | | | | 202 | 426.0 | 2 |
| 529 | VE-126-0297 | (805) 256-0177 | A | | | | 201 | 424.0 | 2 |
| 530 | VE-126-0302 | (805) 850-9374 | A | 3 | 11.0 | 3.7 | 212 | 448.0 | 2 |
| 531 | VE-126-0303 | (805) 850-9462 | A | | | | 203 | 430.0 | 2 |
| 532 | VE-126-0306 | (805) 850-9404 | A | | | | 212 | 456.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T

# Ventura call box call breakdown

## Annual Report 2020

| | CALL BOX | Call box Phone Number | Status* | CHP | | | MAINTENANCE | | |
|---|---|---|---|---|---|---|---|---|---|
| | | | | Calls to CHP | Minutes to CHP | Avg Time | Calls to Maint | Minutes to Maint | Avg Time |
| 533 | VE-126-0307 | (805) 850-9495 | A | | | | 190 | 392.0 | 2 |
| 534 | VE-126-0312 | (805) 850-9376 | A | 1 | 8.0 | 8.0 | 194 | 401.0 | 2 |
| 535 | VE-126-0313 | (805) 850-9578 | A | 3 | 5.0 | 1.7 | 200 | 420.0 | 2 |
| 536 | VE-126-0316 | (805) 850-9604 | A | | | | 220 | 477.0 | 2 |
| 537 | VE-126-0317 | (805) 256-0584 | A | 4 | 10.0 | 2.5 | 214 | 463.0 | 2 |
| 538 | VE-126-0322 | (805) 850-9645 | A | 1 | 3.0 | 3.0 | 199 | 420.0 | 2 |
| 539 | VE-126-0323 | (805) 850-9659 | A | | | | 200 | 421.0 | 2 |
| 540 | VE-126-0326 | (805) 850-9358 | A | 4 | 8.0 | 2.0 | 197 | 414.0 | 2 |
| 541 | VE-126-0327 | (805) 850-9527 | A | 5 | 8.0 | 1.6 | 195 | 406.0 | 2 |
| 542 | VE-126-0332 | (805) 850-9676 | A | | | | 213 | 462.0 | 2 |
| 543 | VE-126-0333 | (805) 850-9435 | A | 2 | 6.0 | 3.0 | 165 | 341.0 | 2 |
| 544 | VE-126-0336 | (805) 850-8776 | A | 1 | 7.0 | 7.0 | 227 | 500.0 | 2 |
| 545 | VE-126-0337 | (805) 850-9321 | A | 3 | 10.0 | 3.3 | 179 | 376.0 | 2 |
| 546 | VE-126-0342 | (805) 850-9389 | A | | | | 223 | 495.0 | 2 |
| 547 | VE-126-0343 | (805) 256-0042 | A | 2 | 15.0 | 7.5 | 210 | 453.0 | 2 |
| 548 | VE-150-0002 | (805) 256-4269 | A | 7 | 23.0 | 3.3 | 215 | 469.0 | 2 |
| 549 | VE-150-0007 | (805) 320-8183 | A | 4 | 8.0 | 2.0 | 196 | 412.0 | 2 |
| 550 | VE-150-0018 | (805) 320-8189 | A | 5 | 43.0 | 8.6 | 212 | 457.0 | 2 |
| 551 | VE-150-0026 | (805) 256-4241 | A | 3 | 8.0 | 2.7 | 207 | 439.0 | 2 |
| 552 | VE-150-0042 | (805) 256-4267 | A | 8 | 34.0 | 4.3 | 220 | 461.0 | 2 |
| 553 | VE-150-0058 | (805) 320-8186 | A | 1 | 1.0 | 1.0 | 194 | 402.0 | 2 |
| 554 | VE-150-0083 | (805) 320-8190 | A | 7 | 12.0 | 1.7 | 208 | 446.0 | 2 |
| 555 | VE-150-0097 | (805) 320-8196 | A | 1 | 6.0 | 6.0 | 201 | 428.0 | 2 |
| 556 | VE-150-0108 | (805) 320-8194 | A | 3 | 5.0 | 1.7 | 205 | 430.0 | 2 |
| 557 | VE-150-0120 | (805) 320-8193 | A | 2 | 9.0 | 4.5 | 199 | 418.0 | 2 |
| 558 | VE-150-0131 | (805) 320-8154 | A | | | | 210 | 452.0 | 2 |
| 559 | VE-150-0141 | (805) 320-8175 | A | 6 | 6.0 | 1.0 | 199 | 417.0 | 2 |
| 560 | VE-150-0192 | (805) 850-9874 | A | 3 | 14.0 | 4.7 | 198 | 417.0 | 2 |
| 561 | VE-150-0212 | (805) 320-8156 | A | 24 | 36.0 | 1.5 | 207 | 441.0 | 2 |
| 562 | VE-150-0221 | (805) 320-8158 | A | 2 | 3.0 | 1.5 | 207 | 441.0 | 2 |
| 563 | VE-150-0232 | (805) 320-8165 | A | 3 | 4.0 | 1.3 | 199 | 419.0 | 2 |
| 564 | VE-150-0241 | (805) 320-8181 | A | 1 | 1.0 | 1.0 | 201 | 425.0 | 2 |
| 565 | VE-150-0249 | (805) 850-9553 | A | 2 | 2.0 | 1.0 | 202 | 426.0 | 2 |
| 566 | VE-150-0267 | (805) 256-0579 | A | 8 | 21.0 | 2.6 | 211 | 456.0 | 2 |
| 567 | VE-150-0283 | (805) 320-4107 | A | 6 | 14.0 | 2.3 | 204 | 432.0 | 2 |
| 568 | VE-150-0293 | (805) 320-8173 | A | 7 | 20.0 | 2.9 | 208 | 445.0 | 2 |
| 569 | VE-150-0302 | (805) 256-0330 | A | | | | 209 | 448.0 | 2 |
| 570 | VE-150-0312 | (805) 320-8291 | A | | | | 208 | 436.0 | 2 |

Produced by: $T^3$ Status: A=Active, XT=Temp. Removal, XP=Permanent Removal Data source: AT&T